ARVAL
BNP PARIBAS GROUP

2BLF286

INSPECTION REPORT

End of contract


GENERAL INFO

File	321673
License plate	2BLF286
Vehicle identification number	VSSZZZKLZNR018282
Dossier	2021123031
Make	Seat Leon ST 1.5eTSI 150 Mov.D
Mileage	150123
First registration	03/01/2022
client availability date	30/09/2026
inspectionDate	02/10/2026










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





B 2 BLF 286

DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
35	Front Bonnet // Polish	Y
66	Wing Front Left // Polish	Y
81	Door Front Left // Smart Repair Medium	Y
84	Door Front Left // Repair & Painting	N
87	Door Front Left / Trim / Replace	Y
106	Door Rear Left // Polish	Y
107	Door Rear Left / Trim / Replace	Y
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
154	Rear Bonnet // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
169	Rear Bonnet / Spoiler / Replace & Painting	Y
186	Wing Rear Right // Polish	Y
194	Door Rear Right // Repair & Painting	N
208	Rocker Panel Right / Cover Not Painted / Replace	N
213	Door Front Right // Painting	N
222	Side View Mirror Right // Painting	N
236	Wing Front right // Polish	Y
274	Bumper Front / Grid Central / Replace	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	N
540	Interior // Repair 1	N

Damage Pictures




Door Front Left / Trim / Replace-scratch





Door Rear Left / Trim / Replace-scratch




Door Rear Left // Polish-scratch





Wheel Alloy Rear Left // Repair-scratch






Wing Rear Left // Polish-scratch







Bumper Rear // Polish-scratch




Rear Bonnet / Spoiler / Replace & Painting-scratch

Rear Bonnet / Rear Window / Replace-scratch






Trunk Compartment / Side Cover Left / Replace-scratch







Wheel Alloy Rear Right // Repair-scratch









Wing Rear Right // Polish-scratch



Roof // Polish-scratch



Side View Mirror Right // Painting-scratch



Wing Front right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Front Bonnet // Polish-scratch







Wing Front Left // Polish-scratch




Door Front Left // Smart Repair Medium-scratch












Door Front Left // Repair & Painting-scratch + dent




Bumper Front / Grid Central / Replace-scratch + dent








Door Rear Right // Repair & Painting-scratch + dent







Rear Bonnet // Repair & Painting-scratch + dent










Door Front Right // Painting-bad repair







Rocker Panel Right / Cover Not Painted / Replace-tear






Bumper Front // Painting-stone chipping

Interior // Repair 1-N comf / out of order