AUDI A3 SPORTBACK

Vehicle information

Make:	**AUDI**	License:	**2CTN813**
Gearbox:		Body color:	
Model:	**A3 SPORTBACK**	VIN:	**WAUZZZGY3PA041740**
Fuel type:		Power:	**110 kW**
Version:	**1.4 40 TFSI E S TRONIC SPORTB ATTRACTION**	First registration	**23/11/2022**
Mileage:	**87312 km**	N° of doors:	


Damage summary


Interior	1
Left	1
Rear	3
Right	3


Commercial pictures






















VIN equipment according to manufacturer information

Airbag	Central consol	Central locking	Distance control
Electric adjustable mirrors	Fog lights	GPS	Integrated child seat
Power steering	Rain sensor	Rims alloy	Steering wheel leather
Steering wheel multifunctional	Telephone	Upper cabin spoiler	Windows electric functioning


Options according to the inspector

GPS	**Yes**

Damages

Bumper R
Bad repair
Paint
Rear






Charging cable (fast)
Missing
Replace
Rear




Charging cable (normal)
Missing
Check
Rear




Door FL
Deformed / Strained
Repair and paint (complete)
Left




Door RR
Repaired
No repair
Right



Interior
Damaged
Acceptable
Interior



Roof pillar R
Bad repair
Check
Right





Wing RR
Repaired
No repair
Right



Tyres

Front Left
Summer
Aluminium
205/55/16/94/V
Falken
5.0 mm
Front Right
Summer
Aluminium
205/55/16/94/V
Falken
4.0 mm
Rear Left
Summer
Aluminium
205/55/16/91/V
Continental
8.0 mm
Rear Right
Summer
Aluminium
205/55/16/91/V
Continental
8.0 mm

Checks

Category	**Passenger Car**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Maintenance	**OK**
Maintenance	**over 2700 km**	Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**0**	Number of keys total	**2**
Registration Certificate Car (BE)	**Yes**	Registration Certificate Home (BE)	**Yes**
Repair kit	**Yes**	Reset to factory settings	**No, not possible**
Type of Maintenance book	**Digital maintenance**		

VIN detail - *If the description in the language of your choice is not available, the French description is shown*

ABS (antiblocage des freins)	Accoudoir central avant	Airbag conducteur
Airbag passager	Airbags de tête	Airbags genoux
Airbags latéraux aux sièges avant	Allumage automatique des phares suite obscurité	Antivol électronique transpondeur Audi
Appuis-tête arrière (3)	APS (Acoustic Parking System) arrière	Audi Connect Navigation & Infotainment (3 ans)
Audi Drive Select	Audi Smartphone Interface (si MMI Nav. Plus)	Banquette AR non divisée/dossier divisé et rabat.
Ciel de toit en tissu	Climatisation électronique 2 zones	Combiné d'instruments digital
Contours de fenêtres noirs	Contrôle de la pression des pneus	Cruise Control (ready for adaptive cruise control)
Détecteur de pluie	EDS	Encarts micrometallic argent
ESC (Contrôle électronique de la stabilité)	Feux de jour DEL	Fonction start/stop
Frein à main électromécanique active par bouton	Garantie 3 ans/120.000 km	Garniture de plancher du coffre à bagages
Indicateur d'occupation de siège	JAV 5 branches Aero Design 7.5Jx16''+205/55 R16 91V	Kit crevaison et compresseur 12v
Limiteur de vitesse	MMI Radio Plus DAB+ AM/FM 6HP VC	OPF (Otto Particle Filter)
Outillage de bord	Pack Business	Pack Business (convention A/B/C/D/E/F/H/P)
Pare-brise en verre athermique teinté vert	Phares avant à technologie DEL	Plafonnier central AR à extinction temporisée
Plafonnier central AV à extinction temporisée	Pré-installation GSM Bluetooth	Préparation pour MMI Navigation Touch
Prises 12V AV/AR	Rétroviseurs électriques	Rétroviseurs extérieurs à dégivrage électrique
Rétroviseurs extérieurs couleur carrosserie	Sécurité enfant aux places arrière	Servotronic
Siège conducteur réglable en hauteur	Siège passager réglable en hauteur	Spoiler de toit couleur carrosserie
Système de navigation MMI Plus	Tapis de sol complémentaires AV/AR	Tissu Index
Trousse de secours avec triangle de présignalisation	Verrouillage central 'Keyless-Go' sans safelock	Vitres électriques arrière
Vitres électriques avant	Vitres teintées	Volant multifonction cuir 3 branches cuir+palettes
Volant multifonctions	Volant sport gainé de cuir	

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.