TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48190085
Order No. / Reference: 26976207
Inspection date: 15 Oct 2026

Manufacturer: Volkswagen	Model: Multivan T7 Kurz
VIN: WV2ZZZST9PH009737	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Multivan T7 Kurz	
Vehicle Identification number	WV2ZZZST9PH009737
Mileage (Read)	104,069 km
First registration	8 May 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Starlight blue metallic (T5U)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Beige
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	17,600 km
Last service on / at	05/2026 at 91,621 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS544176
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CQJ 00218		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,850 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 102H	Summer tyres on Steel rim with wheel cover	Falken	5mm / 5mm
2)	215/65 R16 102H	Summer tyres on Steel rim with wheel cover	Falken	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 102H	Winter tyres on Light alloy	Semperit	5mm / 5mm
2)	215/65 R16 102H	Winter tyres on Light alloy	Semperit	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R16 102H C	Summer tyres on Steel	Falken	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments: Various shelves and storage compartments
- Airbag: Side and head airbags for driver and front passenger (head airbags for the outer rear seats - center airbag in the front)
- Exterior mirror housings in high-gloss black
- LED turn signals, integrated into the side of the exterior mirrors
- On-board tools and tire mobility set (in the storage compartments in the luggage compartment)
- Decorative inlays: Decorative inlays "Scale Light Grey"
- Three-phase generator 160-250 A
- Chassis: 16" chassis with 16" disc brakes at the front and 16" disc brakes at the rear
- Windows: Front pane made of laminated safety glass, heat and sound insulating
- Transmission: DSG (dual-clutch transmission), 7-speed automatic
- Boot lid
- Rear window with wiper/washer system, heated
- Child seat anchorage ISOFIX and Top Tether (for each individual seat in the passenger compartment)
- Fuel-powered auxiliary heater
- LED taillights
- Steering wheel: Multifunction leather steering wheel with paddle shifters
- Multi-collision brake
- Fatigue detection
- Non-smoking version
- eCall emergency call system
- Without Mode 3 charging cable
- Radio: "Ready 2 Discover" with 25.4 cm (10 inch) color touchscreen including "Streaming & Internet"
- Radio: Digital radio reception (DAB+)
- Wheels/Tires: 215/65 R 16 102 H XL, optimized for low rolling resistance
- Wheels/Tire Accessories: Wheel covers for 16" wheels
- Sliding door in the passenger/cargo compartment: sliding door on the left
- Keys for locking system: 2 vehicle keys
- Power steering
- dimmable interior safety mirror
- Seat covers: Bi-color fabric seat covers, "Bright Dots" design
- Sun visors with mirrors, ticket holder on the driver's side (airbag label on the sun visor and B-pillar on the passenger side)
- First aid kit, warning triangle and high-visibility vest
- Lashing eyes (4 pieces) (2 fixed lashing eyes in the cargo area - 2 variable lashing eyes for the rail system)
- Central locking with keyless start system "Keyless Start" without safe locking
- Airbag for driver and front passenger (with passenger airbag deactivation)
- Evasive steering assist and turn assist
- Exterior mirrors, electrically adjustable, heated and folding
- Exterior mirrors, left and right convex
- Reinforced battery (68 Ah/ 380 A)
- Floor coverings: Reinforced velour carpet in the passenger compartment
- third brake light
- Roof rails/roof load carrier: Mounting points for roof rack system (6 pieces)
- Electronic Stability Program, ABS, ASR (with deactivation button), EDS (Hill Start Assist)
- Chassis: Suspension and damping, standard
- Electric windows, front
- Cruise control system with speed limiter (and "Intelligent Speed Assist")
- Glove compartment without light
- Tailgate closing without interior unlocking function
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- Air conditioning with manual control
- LED headlights with LED daytime running lights
- Strip between the headlights painted in glossy black
- Headlight range control
- Multifunction display: Digital Cockpit
- Multimedia systems: 2 USB interfaces (Type C) in the dashboard
- Emergency braking assistant "Front Assist" (with pedestrian and cyclist detection)
- Particulate filter: Soot particle filter for diesel engines
- Radio: App-Connect incl. App-Connect Wireless (for Apple CarPlay and Android Auto)
- Radio accessories: Voice control
- Wheels/Tires: 4 steel wheels 6.5 J x 16
- Wheels/Tires: Tire pressure monitoring system
- Windscreen wiper interval control, 4-stage adjustable (for the front windscreen wipers)
- Sliding door in the passenger/cargo compartment: sliding door on the right
- Seat belt monitoring system (warning tone and light for unfastened seat belts front and rear)
- Seats in the passenger compartment: 3 individual seats facing forward in the 2nd row.
- Lane keeping assistant “Lane Assist”
- Daytime running lights with cornering lights
- Telephone: Mobile phone interface
- Traffic sign recognition
- Electronic immobilizer
- Green thermal insulation glazing

Extra equipment

- Towbar, foldable (with electric release (including trailer stabilization))
- Parking assistance in the front and rear areas
- Windows (glass type in the cargo/passenger compartment) - rear windows tinted
- Windows: Front pane made of laminated safety glass, heat and sound insulating, heated
- Tailgate: Tailgate with power closing assist (tailgate with power closing assist - power closing of the tailgate with unlocking function from inside)
- Multifunctional display: Digital Cockpit Pro
- Package: Top Package (panoramic glass roof, tinted, two-part - safety interior mirror, automatically dimming, - sun visors with mirrors, illuminated, - Dynamic Light Assist high beam control for LED matrix headlights - IQ.Light LED matrix headlights with LED daytime running lights - intermittent wiper control with rain sensor - dynamic headlight range control with dynamic cornering lights - LED taillights, bad weather lights including cornering lights, 3-zone climate control - daytime running lights with cornering lights)
- Seats: Armrests for driver and front passenger seats, on both sides (with electric lumbar support and folding table)
- Auxiliary heater for windscreen defrosting and heating/ventilation of the driver's cab (with remote control)
- On-board tools and jack (in the storage compartments in the luggage compartment)
- Driver assistance systems: "Travel Assist" and "Emergency Assist" (Driver assistance "Travel Assist" including lane keeping assist "Lane Assist" and "Emergency Assist" - Lane change assist "Side Assist" including "Blind Spot Detection", parking assist and exit warning - Adaptive Cruise Control ACC "stop & go" with speed limiter)
- Paint finish: Metallic
- Navigation system "Discover Pro" (25.4 cm (10 inch) color touchscreen - streaming & internet)
- Proactive occupant protection system (PreCrash Basic and Front)
- Wheel cover center
- Wheels/Tires: Spare wheel in driving tire size, steel
- Rear View reversing camera
- Sliding door in the passenger/cargo area: Electric sliding door left and right
- Drawers under the outer seats in the passenger compartment and 2 waste bins
- Heated seats for the driver's cab, left and right, separately adjustable
- Partitions: Mesh partition
- Central locking with keyless locking and starting system "Keyless Access/Advanced" (without safe locking)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Side panel - Scratch(es) - Smart repair
2	Rear bumper	Rear bumper - Scratch(es) - Paint
3	Sliding door - left side	Sliding door with glass panel - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Side panel - rear left side	Sill - Scratch(es) - No deduction
3	Mudguard - left side	Mudguard - left side - Scratch(es) - No deduction
4	Roof	Roof - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 19 May 2026	984,30 €
2	Side right, Provided by user / customer, from 19 May 2026	1.089,61 €
3	Side - left, Provided by user / customer, from 20 Jul 2023	1.564,22 €
4	Side - left, Provided by user / customer, from 27 Mar 2026	1.587,14 €
5	Front, Provided by user / customer, from 31 Mar 2026	1.932,79 €

Repainting

No.	Repainting
1	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
2	Door - front left side, Professionally carried out, Invoice of repair done Non-existent
3	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Door - rear right side	178 µm	Door - front left side	166 µm
Door - front right side	202 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents




Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Damage 1: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 1: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 3: Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint




Damage 3: Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint



Damage 3: Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 3: Mudguard - left side: Mudguard - left side - Scratch(es) - No deduction



Wear and tear 3: Mudguard - left side: Mudguard - left side - Scratch(es) - No deduction



Repainting 1: Door - rear right side



Repainting 2: Door - front left side



Repainting 3: Door - front right side