BMW

VIN: WBA7M710X07G21621

Estimated repair cost

741.06 EUR
TOTAL



Description

Registration number	Registration date	Odometer
2AUA879	-	83747 km
Color	**Year**	**Upholstery**
-	-	-
Number of doors	**Number of seats**	**Generation**
-	-	-

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction	net cost
001	Rim / Back Right Material : Aluminium alloy / Rim/Tyre diameter : 17 " / Surface : Chromed	Scratched	Smart repair	225.00 EUR



Bodywork time	Paint time	Part Price	
-	-	-	Lumpsum
Bodywork cost	**Paint cost**	**MaterialCost**	**225.00 EUR**
-	-	-	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

002	Rim / Front Right Material : Aluminium alloy / Rim/Tyre diameter : 17 " / Surface : Chromed	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

003	Bumper / Front Painted : Yes	Dent	Repair	231.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
1.50 h	1.40 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
112.50 EUR	119.00 EUR	-	

004	Fog light trim / Front Left	Scratched	Replace	77.06 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.30 h	-	54.56 EUR	-
Bodywork cost	**Paint cost**	**MaterialCost**	
22.50 EUR	-	-	

005	Bonnet / -	Dent	Repair	207.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	2.00 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	170.00 EUR	-	

006	Door / Front Left Windowed : Yes	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

007	Door / Back Left Windowed : Yes	Chip	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

008	Wing / Back Left Windowed : Yes	Scratched	Acceptable	-

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

009	Bumper / Back Painted : Yes	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

Loose Items

- Registration certificate
- Registration certificate owner
- Spare Key
- User manual
- Rear parcel shelf
- Document holder
- Triangle
- First aid kit

Main set of tyres

Front Left	HANKOOK	225/45/17 94 W All-season	4 mm
Front Right	HANKOOK	225/45/17 94 W All-season	4 mm
Back Left	HANKOOK	225/45/17 94 W All-season	5 mm
Back Right	HANKOOK	225/45/17 94 W All-season	5 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right


Odometer


Navigation



Vin


Other

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Rim / Back Right / Scratched



Rim / Back Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched




Bumper / Front / Dent



Bumper / Front / Dent



Bumper / Front / Dent




Bumper / Front / Dent



Bumper / Front / Dent



Bumper / Front / Dent



Fog light trim / Front Left / Scratched



Fog light trim / Front Left / Scratched



Fog light trim / Front Left / Scratched



Bonnet / - / Dent



Bonnet / - / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bonnet / - / Dent



Door / Front Left / Scratched



Door / Back Left / Chip



Wing / Back Left / Scratched



Bumper / Back / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.