TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48259371
Order No. / Reference: 27104998
Inspection date: 20 Oct 2026

Manufacturer: Mercedes-Benz	Model: A 250 e 8G-DCT AMG Line
VIN: W1K3G8GB1PJ386033	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz A 250 e 8G-DCT AMG Line	
Vehicle Identification number	W1K3G8GB1PJ386033
Mileage (Read)	102,355 km
First registration	5 Sept 2022
Number of holders	1
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,332 ccm / 4
Power	118 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Roségold metallic
Doors / Seats	4 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	233 Tag(e)
Last service on / at	06/2026 at 96,118 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ516596
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / AJO 00070		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,175 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R19 93W	Summer tyres on Light alloy	Bridgestone	5mm / 5mm
2)	225/40 R19 93W	Summer tyres on Light alloy	Bridgestone	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 95V	Winter tyres on Light alloy	Dunlop	5mm / 5mm
2)	225/45 R18 95V	Winter tyres on Light alloy	Dunlop	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS - Anti-lock Braking System
- Airbag: Automatic passenger airbag deactivation
- Airbag: Kneebag for driver
- Airbag: Windowbag for driver and front passenger
- AMG sports pedal assembly made of brushed stainless steel with rubber studs
- Foldable armrest in the center console for driver and front passenger
- Outdoor temperature display
- Brake assist, active
- Double cup holder at the front
- DYNAMIC SELECT
- Door sills with the lettering "Mercedes-Benz"
- Driving light assistant
- Vehicle key with chrome decorative frame
- Black floor mats with AMG lettering
- Speed Limit Assistant
- Halogen headlights with integrated LED daytime running lights
- KEYLESS-GO start function
- THERMATIC automatic climate control
- Rear headrests (3)
- Charging cable for household socket, 5m, smooth
- Steering wheel: Multifunction sports steering wheel in Nappa leather
- Mercedes-Benz emergency call system
- Package: Light and Visibility Package
- Upholstery: ARTICO leatherette/DINAMICA microfiber
- Radio accessories: USB interface in the storage compartment & 2 USB interfaces in the rear center console
- Tire pressure monitoring system
- Windscreen wipers with rain sensor
- Seat belts A-Class
- Seats: Sports seats
- Power outlet: 12V connection
- Touchpad
- Electronic immobilizer
- Central locking
- Adaptive brake light flashing
- Airbag: Driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Acoustic environmental protection
- AMG Styling
- Traction control (ASR)
- ATTENTION ASSIST
- Heated exterior mirrors (left and right), electrically adjustable from inside
- drilled brake discs, front
- Third brake light
- ECO start/stop function
- Electronic Stability Program (ESP)
- Chassis: Comfort chassis
- Electric windows (4-way)
- Luggage net on driver and passenger seatbacks
- Transmission: 8G-DCT automatic
- Heated rear window
- Interior headliner fabric crystal grey
- Mechanical child safety lock
- Communication module (LTE) for the use of Mercedes me connect services
- Charging system: Alternating current charging system (AC charging) 3.7 kW
- Steering: Direct steering
- Otto particulate filter
- Package: Seating comfort
- Radio accessories: Digital radio (DAB)
- Radio: Extended MBUX functions
- Radio: MBUX multimedia system
- Remote Services Plus
- Crosswind Assist
- Seats: Rear seat backrests foldable 40/20/40 split
- Lane Keeping Assist, active
- Cruise control
- High-visibility vest for drivers
- Heat-insulating glass, green all around
- DINAMICA decorative elements

Extra equipment

- Active Parking Assist with PARKTRONIC (Active Parking Assist can find suitable parking spaces and also provides support when parking and exiting parking spaces. It also assists with steering and acceleration - 12 ultrasonic sensors, four each at the front and rear, and two each on the sides in the front and rear bumpers - Detects parking spaces up to 35 km/h - Steering/speed control - Parktronic, visual and acoustic warning of detected obstacles up to approx. 10 km/h - Cross-traffic assist when reversing out of parking spaces)
- Paint finish: Metallic
- Charging cable for wallbox and public charging station, 5m, smooth 11kW (This charging cable, also called Mode 3 cable, allows you to charge the vehicle battery at the wallbox or at public charging stations with up to 11 kW (Type 2, 3-phase, 16 A).)
- MULTIBEAM LED (18 individually controllable high-performance LEDs per headlight to create a column-shaped high beam with 16 controllable individual segments - Low beam and high beam in LED projection technology - Adaptive Highbeam Assist Plus (glare-free permanent high beam) - Cornering light or cornering light with roundabout and intersection function (only in conjunction with hard disk navigation) - Active curve illumination when high beam is activated - City light, country road light and motorway light - Adaptive full-LED rear light)
- Package: MBUX High-End Package (without MBUX Augmented Reality) (Hard drive navigation - Pre-installation for Live Traffic Information - Traffic Sign Assist - Connectivity Package Navigation: Hard drive navigation, Extended navigation services - Smartphone integration: Mobile phone via Apple CarPlay and Android Auto with the media system - Pre-installation for digital key handover - Wireless charging system for mobile devices or multifunction telephony - Media display - Fully digital instrument display)
- Radio accessories: MBUX Interior Assistant (3D camera in the overhead control unit - the system detects and interprets hand movements and distinguishes between driver and front passenger - highlights or enlarges specific elements in the media display (media/ radio, seat settings, navigation or Active Parking Assistant) - activate reading light - move hand up and down below the interior mirror - activate searchlight - extend hand to the unoccupied front passenger seat - call up personal favorites)
- Seats: 4-way lumbar support (Four settings are possible: higher, lower, weaker or stronger.)
- Seats: Heated seats for driver and front passenger (The intensity can be selected in three levels. Intelligent and comfortable: The seat heating switches off automatically.)
- Seats: Front right seat electrically adjustable with memory
- Phone accessories: Wireless charging system for mobile devices (wirelessly charges mobile phones that support the Qi standard on a charging pad, Near Field Communication (NFC) for fast connection to the mobile phone)
- Heat-insulating dark tinted glass
- Decorative elements: aluminum with longitudinal brushing, light finish
- AMG floor mats (made of durable black velour with red or grey contrast stitching and the AMG logo)
- Fire extinguisher (fire extinguisher within easy reach under the driver's seat)
- Head-up Display (projects important information directly into the field of vision on the windshield)
- THERMOTRONIC 2-zone automatic climate control (separate temperature selection for driver and front passenger - automatic control of temperature, air volume and air distribution - sensors maintain the desired climate - continuous monitoring of the intake air for harmful gases with automatic recirculation - a fine dust activated carbon filter improves the air quality in the vehicle - dew point sensor prevents the windows from fogging up - residual heat button for heating/ventilation when the vehicle is switched off)
- Package: Business for €250 (Hard drive navigation - Smartphone integration - Traffic sign assistant - Preparation for digital key handover - Connectivity package navigation - Seat heating for driver and front passenger - Active parking assistant with PARKTRONIC - Public charging package - Charging cable for wallbox and public charging stations, 5m, smooth - Remote and Charging Services Plus)
- Package: KEYLESS-GO Comfort Package (KEYLESS-GO access and drive authorization system - HANDS-FREE ACCESS opens the trunk lid)
- Package: Public Charging (charging cable for wallbox and public charging stations, 5m, smooth (charging the vehicle battery at the wallbox or at public charging stations with up to 11 kW (Type 2, 3-phase, 16 A)) - Remote and Charging Services Plus)
- Package: Mirror package (interior and exterior mirrors on the driver's side automatically dimming - exterior mirrors left and right electrically folding)
- Radio accessories: Burmester surround sound system (The high-performance speakers develop first-class surround sound. You can optimize this specifically for the front and rear seats and intensify the listening experience. A quality that is also visible thanks to the high-quality Burmester lettering.)
- Wheels: 48.3 cm (19") AMG light-alloy wheels, 4-spoke design (titanium grey painted and high-sheen finish with 225/40 R 19 tires on 7.5 J x 19 ET 49 rims)
- Heated windshield washer system
- Sunroof: Electric panoramic sunroof
- Seats: Electrically adjustable driver's seat with memory function (The memory function saves your ideal position for the driver's seat, exterior mirrors, and head-up display. Up to three people can instantly find their preferred position at the touch of a button – making driver changes quick and easy. You can also easily readjust the seat electrically and continuously.)

- Blind Spot Assist (keeps an overview for you during lane changes and can detect objects in the vehicle's blind spot. This can prevent collisions, for example on multi-lane city streets or highways. When stationary, it continues to function for an additional three minutes: If the assistant detects two-wheelers or pedestrians in the danger zone, it warns you visually and audibly.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Sill - left side	Sill - dent(s) - Smooth repair work
2	Front bumper	Spoiler - Scratched - Smart repair
3	Body	Identification plate - Missing - Replace
4	Wheel / tyres	Tyre - front right side (Flanke) - Damaged - Replace
5	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Loss in value
6	Wheel / tyres	Alloy rim - front right side (Materialabtrag) - Scratched - Replace
7	Rear bumper	Rear bumper (Spachtel/ Schleifspuren) - Paint defect - Repair and paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Side panel - rear right side	Side panel - dent(s) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Mudguard - right side	Mudguard - right side - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Documents - Log book
Equipment - charging cable (230V)

Repainting

No.	Repainting
1	Mudguard - left side, Professionally carried out, Invoice of repair done Non-existent
2	Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent
3	Door - front left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - left side	189 µm	Mudguard - right side	254 µm
Door - front left side	179 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.





Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.




Damage 1: Sill - left side: Sill - dent(s) - Smooth repair work




Damage 1: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 1: Sill - left side: Sill - dent(s) - Smooth repair work




Damage 1: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 2: Front bumper: Spoiler - Scratched - Smart repair




Damage 2: Front bumper: Spoiler - Scratched - Smart repair




Damage 2: Front bumper: Spoiler - Scratched - Smart repair



Damage 2: Front bumper: Spoiler - Scratched - Smart repair



Damage 3: Body: Identification plate - Missing - Replace



Damage 4: Wheel / tyres: Tyre - front right side (Flanke) - Damaged - Replace




Damage 4: Wheel / tyres: Tyre - front right side (Flanke) - Damaged - Replace



Damage 5: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 5: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace



Damage 6: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace




Damage 6: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace



Damage 6: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace




Damage 6: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace



Damage 7: Rear bumper: Rear bumper (Spachtel/ Schleifspuren) - Paint defect - Repair and paint




Damage 7: Rear bumper: Rear bumper (Spachtel/ Schleifspuren) - Paint defect - Repair and paint



Damage 7: Rear bumper: Rear bumper (Spachtel/ Schleifspuren) - Paint defect - Repair and paint



Wear and tear 2: Side panel - rear right side: Side panel - dent(s) - No deduction




Wear and tear 2: Side panel - rear right side: Side panel - dent(s) - No deduction



Wear and tear 4: Mudguard - right side: Mudguard - right side - dent(s) - No deduction



Wear and tear 4: Mudguard - right side: Mudguard - right side - dent(s) - No deduction



Missing part 1: Documents: Log book - Missing - Replace



Repainting 1: Mudguard - left side



Repainting 2: Mudguard - right side

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula



Repainting 3: Door - front left side