Audi

VIN: WAUZZZF5XNA003331



Description

Registration number 2AWB562	**First registration date** 11/08/2021	**Odometer** 185368 km
Color Blanc Glacier Métallisé	**Model year** 2021	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 1968	**Gearbox type** Automatic	**Engine type** Combustion
Number of gears 7	**Drivetrain** Front Wheel Drive (FWD)	**Max power** 120 KW

Vehicle Equipments

Rear-view camera	Cruise control	Electrically foldable door mirrors
Automatic headlights	Climate control	Park Assist
Hydraulic tail board	Alloy wheel rims	Rear sensors
SATNAV	Heated seats	Front sensors
Heated door mirrors	Xenon headlights	

Active warning lights

Engine check indicator

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 23/10/2026	**Inspection approval date** 26/10/2026



All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Engine check indicator	Defective	Check
	 		
002	Personal Data / -	Non Compliant	Carry out
			
003	Carpet / Interior Front Left	Dirty	Cleaning
	 		
004	Bumper / Front Painted : Yes	Scratched	Acceptable
			
005	Wing / Back Left	Dent	Acceptable
			

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

006	Interior tailgate lining / Back	Scratched	Acceptable
			
007	Bumper / Back Painted : Yes	Dent	Acceptable
			
008	Armrest door / Interior Back Right	Tear	Replace
	 		
009	Roof post A/B/C / Right	Dent	Acceptable
			
010	Bonnet / Front [1]	Dent	Acceptable
			

[1] X2

Loose Items

- [x] Tyre repair kit complete
- [x] Registration certificate owner
- [x] Registration certificate
- [x] Safety vest
- [x] Triangle
- [x] Rear parcel shelf
- [x] Spare Key
- [x] First aid kit
- [x] Conformity certificate
- [x] Towing hook

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	PIRELLI	225/50/17 Summer	4.5 mm
Front Right	PIRELLI	225/50/17 Summer	4.5 mm
Back Left	PIRELLI	225/50/17 Summer	4 mm
Back Right	PIRELLI	225/50/17 Summer	5 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right




Odometer


Navigation



Spare Tyre


Vin

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Other




Other



Other



Other




Other



Engine check indicator / Defective



Engine check indicator / Defective




Personal Data / - / Non Compliant



Carpet / Interior Front Left / Dirty



Carpet / Interior Front Left / Dirty



Bumper / Front / Scratched



Wing / Back Left / Dent



Interior tailgate lining / Back / Scratched



Bumper / Back / Dent



Armrest door / Interior Back Right / Tear

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Armrest door / Interior Back Right / Tear



Roof post A/B/C / Right / Dent



Bonnet / Front / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.