TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48609880
Order No. / Reference: 27197979
Inspection date: 10 Nov 2026

Manufacturer: Ford	Model: Transit Custom 280 L1H1 LKW VA Autm. Trend
VIN: WF0YXXTTGYNP04410	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit Custom 280 L1H1 LKW VA Autm. Trend	
Vehicle Identification number	WF0YXXTTGYNP04410
Mileage (Read)	80,183 km
First registration	4 Oct 2022
Number of holders	1
Next periodical technical inspection	03/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	96 kW
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Blazer Blau
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Anthracite

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	15,000 km
Last service on / at	05/2025 at 69,914 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP435779
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BMU 07596		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109T	All-season tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm
2)	215/65 R16 109T	All-season tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R16 109T C	All-season tyres on Steel	Goodyear	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, flat
- Double-leaf rear door with 180° opening angle (without window)
- Electronic Stability Program (ESP) with Traction Control System (TCS)
- FordPass Connect
- Generator, 240 A
- Cruise control including imitation leather steering wheel
- Lockable glove compartment with lid
- Front air conditioning
- Paint finish: Solid color paint
- Cargo area floor: Vinyl floor covering, sealed, "Easy Clean"
- Emergency brake assist including emergency brake light
- Front and rear parking pilot system including fog lights
- Radio: Audio system 13 additionally with DAB/DAB+
- Wheels/Tires: Spare wheel, steel wheel
- Headlights: Halogen projector headlights
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Power steering
- Seats: Seat package 13 - partition (load-through flap), without window (Custom Truck Trend)
- Lashing eyes 8
- Heat-insulating glazing, lightly tinted
- Auxiliary heater, electric
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- On-board computer
- Headliner in driver's cab
- Tachometer
- Third brake light
- Front electric windows
- Ford Easy Fuel
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Transmission: 6-speed automatic
- Interior lighting with delay circuit
- Fuel tank 70 l
- Cargo area lighting with activatable switch-off delay
- Steering column, adjustable in height and reach
- Package: Style-Color Package
- Particulate filter: diesel particulate filter
- Wheel trims
- Wheels: Steel wheels 6.5 J x 16 with 215/65 R 16 R tires (6.5 J x 16 with 215/65 R 16 R tires)
- Sliding door: Sliding door, right
- Mud flaps front and rear
- Half-height side wall cladding
- Seat belts
- Start-stop system
- Power outlet: 12-volt connection
- Immobiliser
- Central locking with remote control

Extra equipment

- Radio: Audio System 24: Ford audio system including Ford SYNC 3 with AppLink, DAB/DAB+, navigation system. (Radio (FM/AM) 8" touchscreen multifunction display (20.32 cm), 4 speakers, FordPass Connect Wi-Fi hotspot, integrated control panel and audio remote control on the steering wheel, Ford SYNC 3 with touchscreen (hands-free system with voice control, SMS readout/sending function, Bluetooth, Emergency Assistance...), AppLink (advanced voice control, privacy mode, Android Auto and Apple CarPlay support, capacitive touchscreen technology,...), dynamic navigation, lane guidance, road map for Western Europe)
- Package: Cargo area protection package (side wall lining, high, hardboard - vinyl floor lining "Easy Clean")
- Package: Visibility Package I (Trend) (Heated windshield - Windscreen washer fluid sensor)
- Parking heater, programmable, with remote control
- Wheels: All-season tires (suitable for winter use)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Broken / torn - Replace
2	Wheel / tyres	Wheel cover - rear right side - Scratched - Replace
3	Seat - front	Seat cover - left side (Sitze) - Soiled - Clean
4	Wing mirror - left side	Cap - Scratch(es) - Smart repair
5	Bonnet	Bonnet - dent(s) - Smart repair
6	Rear bumper	Rear bumper (unpainted) - Scratched - Loss in value
7	Door - rear right side	Door handle - outside - Scratched - Replace
8	Sill - left side	Sill - Scratch(es) - Smart repair
9	Sill - right side	Sill - Scratch(es) - Smart repair
10	Door - front left side	Door - Scratch(es) - Smart repair
11	Trim / covers	Boot lining (rechts und links) - Broken / torn - Loss in value
12	Door - front right side	Door (Kratzer und) - dent(s) - Repair and paint
13	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Repair and paint
14	Boot lid / rear door	Rear door - left side - Dent / paintcoat damage - Repair and paint
15	Side panel - rear right side	Side panel (Dellen und) - Scratched - Repair and paint
16	Front bumper	Front bumper - Scratched - Repair and paint
17	Sliding door, right	Sliding door - Dent / paintcoat damage - Repair and paint
18	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Roof	Roof - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Documents




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Wheel / tyres: Wheel cover - front right side - Broken / torn - Replace




Damage 1: Wheel / tyres: Wheel cover - front right side - Broken / torn - Replace




Damage 2: Wheel / tyres: Wheel cover - rear right side - Scratched - Replace



Damage 2: Wheel / tyres: Wheel cover - rear right side - Scratched - Replace




Damage 3: Seat - front: Seat cover - left side (Sitze) - Soiled - Clean



Damage 3: Seat - front: Seat cover - left side (Sitze) - Soiled - Clean



Damage 4: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 4: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 5: Bonnet: Bonnet - dent(s) - Smart repair



Damage 5: Bonnet: Bonnet - dent(s) - Smart repair



Damage 6: Rear bumper: Rear bumper (unpainted) - Scratched - Loss in value



Damage 6: Rear bumper: Rear bumper (unpainted) - Scratched - Loss in value



Damage 7: Door - rear right side: Door handle - outside - Scratched - Replace



Damage 7: Door - rear right side: Door handle - outside - Scratched - Replace



Damage 7: Door - rear right side: Door handle - outside - Scratched - Replace




Damage 8: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 8: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 9: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 9: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 10: Door - front left side: Door - Scratch(es) - Smart repair



Damage 10: Door - front left side: Door - Scratch(es) - Smart repair




Damage 10: Door - front left side: Door - Scratch(es) - Smart repair



Damage 11: Trim / covers: Boot lining (rechts und links) - Broken / torn - Loss in value



Damage 11: Trim / covers: Boot lining (rechts und links) - Broken / torn - Loss in value




Damage 12: Door - front right side: Door (Kratzer und) - dent(s) - Repair and paint



Damage 12: Door - front right side: Door (Kratzer und) - dent(s) - Repair and paint



Damage 12: Door - front right side: Door (Kratzer und) - dent(s) - Repair and paint



Damage 12: Door - front right side: Door (Kratzer und) - dent(s) - Repair and paint




Damage 12: Door - front right side: Door (Kratzer und) - dent(s) - Repair and paint



Damage 13: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 13: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint




Damage 13: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 14: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Repair and paint



Damage 14: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Repair and paint



Damage 14: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Repair and paint




Damage 15: Side panel - rear right side: Side panel (Dellen und) - Scratched - Repair and paint



Damage 15: Side panel - rear right side: Side panel (Dellen und) - Scratched - Repair and paint



Damage 15: Side panel - rear right side: Side panel (Dellen und) - Scratched - Repair and paint



Damage 15: Side panel - rear right side: Side panel (Dellen und) - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint



Damage 16: Front bumper: Front bumper - Scratched - Repair and paint




Damage 16: Front bumper: Front bumper - Scratched - Repair and paint




Damage 16: Front bumper: Front bumper - Scratched - Repair and paint




Damage 16: Front bumper: Front bumper - Scratched - Repair and paint




Damage 17: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 17: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 17: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 17: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 17: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint




Damage 18: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 18: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 18: Vehicle glazing: Windscreen - Stone chips - Replace



Wear and tear 1: Roof: Roof - dent(s) - No deduction



Wear and tear 1: Roof: Roof - dent(s) - No deduction