# HYUNDAI TUCSON

## Vehicle information


| | | | |
|---|---|---|---|
| Make: | **HYUNDAI** | License: | **2CGG650** |
| Gearbox: | | Body color: | |
| Model: | **TUCSON** | VIN: | **TMAJD812DNJ113166** |
| Fuel type: | | Power: | **132 kW** |
| Version: | **1.6 T-GDI PHEV 4WD FEEL AUTO** | First registration | **13/07/2022** |
| Mileage: | **90708 km** | N° of doors: | |


## Damage summary

| | |
|---|---|
| **Front** | 1 |
| **Interior** | 1 |
| **Left** | 1 |
| **Right** | 5 |
| **Roof & others** | 1 |

## Commercial pictures
























## Options according to the inspector

| | |
|---|---|
| GPS | **Yes** |

## Damages

**Alloy rim FR polished**

Scratch(es)

Repair and paint (complete)

Right






**Alloy rim RR polished**

Scratch(es)

Repair and paint (complete)

Right







**Bodywork**


Damaged

Acceptable


Roof & others



























**Bumper moulding F**

Crack

Replace

Front







**Door FL**

Scratch(es)

Paint

Left







**Door RR**

Scratch(es)

Polish

Right






**Interior**

Damaged

Acceptable

Interior




**Wing FR**

Dent(s) and scratch(es)

Repair and paint (complete)

Right







**Wing RR**

Scratch(es)

Paint

Right





## Tyres

**Front Left**

Summer

235/50/19/103/V

Michelin

4.0 mm

**Front Right**

Summer

235/50/19/103/V

Michelin

4.0 mm

**Rear Left**

Summer

235/50/19/103/V

Michelin

4.0 mm

**Rear Right**

Summer

235/50/19/103/V

Michelin

4.0 mm

## Checks

| | | | |
|---|---|---|---|
| Category | **Passenger Car** | Certificate of Conformity | **Yes** |
| Compressor | **Yes** | Maintenance | **OK** |
| Number of charging cables (normal) | **1** | Number of charging cables (rapid charge) | **1** |
| Number of keys total | **2** | Registration Certificate Car (BE) | **Yes** |
| Registration Certificate Home (BE) | **No** | Repair kit | **Yes** |
| Reset to factory settings | **Yes, vehicle is reset to factory settings** | Statutory inspection | **OK** |
| Statutory inspection | **13/07/2028** | Type of Maintenance book | **Maintenance book present** |

## Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.