# VOLVO XC40


## Vehicle information


| | | | |
|---|---|---|---|
| Brand: | **VOLVO** | License plate: | **2BWD029** |
| Gearbox: | | Body color: | |
| Model: | **XC40** | LEVEL: | **YV1XZBWVFN2776495** |
| Fuel type: | | Power: | **95 kW** |
| Version: | **1.5 T4 PHEV R-DESIGN DCT** | First registration | **14/04/2022** |
| Mileage: | **153966 km** | Number of doors: | |


## Summary of damages

| | |
|---|---|
| **Back** | 4 |
| **Before** | 1 |
| **LEFT** | 1 |
| **Interior** | 1 |
| **Roof & other** | 1 |

## Commercial photos


































## Options according to the inspector

| | |
|---|---|
| GPS | **Yes** |

## Damages

**Left Wing** Claw (
s)
Polishing







**Charging cable (normal)**
Missing Rear
Control



**Bodywork**
Damaged -
Acceptable.
Roof & other




**Rear bumper trim with E-**
shaped claw(s)
-
Replace





Damaged **Interior**
- Acceptable
Interior







**Windshield Chip**
(s)
Windshield Repair
Front




Rear **bumper with**
scratches
- Repair and paint (complete)








**Trunk mat**
stain
clean
rear





## Tires

**Front Left**
Winter
Aluminum
235/50/19/99/H
Dunlop
4.0 mm
**Front Right**
Winter
Aluminum
235/50/19/99/H
Dunlop
4.0 mm
**Left Back**
Winter
Aluminum
235/50/19/103/V
Continental
5.0 mm
**Rear Right**
Winter
Aluminum
235/50/19/103/V
Continental
5.0 mm

## Controls

| | | | |
|---|---|---|---|
| Category | **Private vehicle** | Registration certificate - home address section | **No** |
| Vehicle registration certificate | **Yes** | Certificate of Conformity | **Yes** |
| Compressor | **Yes** | Vehicle inspection | **OK** |
| Vehicle inspection | **14/04/2028** | Interview | **OK** |
| Interview | **+ 19818 km** | Repair kit | **Yes** |
| Number of charging cables (220V) | **0** | Number of charging cables (fast charging) | **1** |
| Total number of keys | **2** | Factory reset | **Yes, the vehicle has been reset to factory settings.** |
| Type of maintenance log | **Maintenance logbook present** | | |

**Information on the content and scope of the inspection report:**

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.