APPRAISAL REPORT



IDENTIFICATION VEHICLE

Make:	VOLVO
Model / version:	XC40
Vin:	YV1XZBWV6P2964971
Plate:	2CPC658
Mileage:	192504
SOH:	
First registration:	04/10/2022
Color:	Onyx Black

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	1
Original key:	✓


PICTURES


















































VIN INFORMATION

Radio	Système navigation	14 haut-parleurs
Téléphone	Transmission automatique	7 rapports
Traction avant	Projecteurs directionnels	Projecteurs à LED
Projecteurs antibrouillard	Lave-projecteurs	Matière : alliage
Lettre repère (J)	Diamètre avant 19	Diamètre arrière 19
Largeur avant 7,5	Largeur arrière 7,5	Climatisation automatique 2 zones
Essence	1477 cm3	1.50 litre
115 kw	156 ch	Mica vernissée
Freins avant à disques	Rétroviseur gauche à réglage mémorisé	Rétroviseur droit à réglage mémorisé
Rétroviseur gauche jour/nuit automatique	Rétroviseur droit jour/nuit automatique	Rétroviseur intérieur jour/nuit automatique
Siège avant gauche chauffant	Sièges avant chauffants	Siège avant gauche à réglage électrique

Sièges avant à réglage électrique	Siège avant gauche à réglage mémorisé	Volant chauffant
Aide au stationnement arrière	Caméra avec vision à 360°	Régulateur automatique de la distance
Ouverture du coffre électriquement	Alarme	Pare-brise chauffant
Lunette arrière teintée foncée	Vitres portes arrière teintées foncées	Vitres de custode teintées foncées
détecteur de pluie essuie-vitre	Toit ouvrant électrique	Toit ouvrant vitré panoramique
Fixotoit	Airbag de genoux	Avertisseur d'angle mort
depuis n°châssis -P-941 597	Keyless Entry	sièges baquet av
grille de calandre active Shutter-System	rétroviseurs électrique "8D08"	airbag passager désactivable
sécurité enfants électrique	ceintures de sécurité de type B	appuis-tête av inclinables
ceintures de sécurité à avance électrique "ERR"	pack éclairage intérieur	poignées de portes éclairées
grille de calandre "Type R-Design"	ouverture du hayon à mains libres de génération 2	attache-remorque semi-électrique rabattable avec prise à 13 broches
1477 CC 95/60 KW	T125/70 R 19 .. V	235/50 R 19 .. H
7,5 J x 19 Alu 5 branches Diamond cut noir	avant 235/50 R 19 .. V arrière 255/45 R 19 .. V	galerie de pavillon noir
sortie d'échappement double cachée	Thaïlande	système "Plug-in"

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		235/50R19 103H	Winter		?
Front right	5 mm		235/50R19 103H	Winter		?
Rear left	5 mm		235/50R19 103H	Winter		?
Rear right	5 mm		235/50R19 103H	Winter		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Door panel RL	Grooved
2	Bumper corner RL	Grooved
3	Bumper corner RR	Grooved
4	Charging cable	Missing
5	Boot cover	Grooved
6	Door panel RR	Grooved
7	Interior	Dirty
8	Door panel FL	Grooved
10	Alloy rim FL polished	Grooved
11	Door FL	Grooved
12	Door RL	Dent(s) and scratch(es)
13	Wing RL	Dent(s)
14	Alloy rim RL polished	Grooved
15	Spoier bumper R	Dent(s) and scratch(es)
16	Rear spoiler	Grooved

#	Location	Damage type
17	Inner door sill RR	Dent(s) and scratch(es)
18	Wing trim FR	Grooved
19	Windscreen	Crack
20	Inner door sill RL	Dent(s)

Total: 19

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
9	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Door panel RL - Grooved




2 - Bumper corner RL - Grooved





3 - Bumper corner RR - Grooved




4 - Charging cable - Missing




5 - Boot cover - Grooved






6 - Door panel RR - Grooved




7 - Interior - Dirty







8 - Door panel FL - Grooved




10 - Alloy rim FL polished - Grooved




11 - Door FL - Grooved






12 - Door RL - Dent(s) and scratch(es)






13 - Wing RL - Dent(s)







14 - Alloy rim RL polished - Grooved





15 - Spoier bumper R - Dent(s) and scratch(es)







16 - Rear spoiler - Grooved








17 - Inner door sill RR - Dent(s) and scratch(es)






18 - Wing trim FR - Grooved




19 - Windscreen - Crack




20 - Inner door sill RL - Dent(s)






9 - Bodywork - Dent(s) and scratch(es) - Renta®




















SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

28/10/2026 16:01

