TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48499135
Order No. / Reference: 27156188
Inspection date: 2 Nov 2026

Manufacturer: Audi	Model: Q4 e-tron 40
VIN: WAUZZZFZ1PP013426	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi Q4 e-tron 40	
Vehicle Identification number	WAUZZZFZ1PP013426
Mileage (Read)	33,178 km
First registration	9 Dec 2022
Number of holders	1
Next periodical technical inspection	03/2028
(Report on hand)	
Fuel type	Electric
Power	70 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	SUV
Colour / colour code	Geysirblau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Dark grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	2 Monat(e)
Last service on / at	12/2024 at 20,960 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP853461
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BZK 00058		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,640 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101T	Summer tyres on Light alloy	Hankook	5mm / 5mm
2)	255/50 R19 103T	Summer tyres on Light alloy	Hankook	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101H	Winter tyres on Steel	Pirelli	5mm / 5mm
2)	255/50 R19 103H	Winter tyres on Steel	Pirelli	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Acoustic vehicle warning system
- Anti-lock braking system (ABS)
- Audi connect Remote & Control for MMI plus and pro
- Evasive steering assist and turning assist
- Vehicle tool kit
- Fabric headliner
- Decorative inlay, black tactile lacquer
- Rear parking sensors
- Chassis: Comfort chassis
- Transmission: 1-speed direct drive
- Interior lighting
- i-Size child seat anchors on the front passenger side, i-Size and Top Tether anchors on the outer rear seats
- Headrests (5)
- Mode 3 charging cable for public charging
- LED headlights
- Light and rain sensor
- Model name and performance/technology lettering
- Package: Gloss Package
- Wheel: Tire pressure monitoring system
- Radio: MMI Radio
- Seats: Standard front seats
- Seats: Front seats manually adjustable
- Lane Departure Warning
- Stationary air conditioning
- First aid kit with warning triangle
- Electronic immobilizer
- Central locking
- Airbag: Front side airbags, with head airbag and front interaction airbag
- Audi connect emergency call and service
- Audi pre sense front
- Electrically adjustable/heated exterior mirrors
- third brake light
- Aluminum roof rails
- Tachometer
- Electronic Stability Control (ESC)
- front and rear floor mats
- rear window wiper
- Interior mirror dimming
- Automatic air conditioning
- Comfort center armrest in front
- Combo 2 charging socket (EU)
- LED taillights
- Steering wheel: Double-spoke leather steering wheel with multifunction
- On-board charger up to 11 kW (AC)
- Upholstery: Fabric Index
- Wheel: Steel wheels 8.0 J x 19"
- Power steering
- Seats: Rear seat backrest foldable
- Speed limiter without cruise control and without adaptive cruise control.
- 12-volt socket
- Camera-based traffic sign recognition
- Green thermal insulation glazing

Extra equipment

- e-tron compact charging system (The e-tron compact charging system is designed for charging at wall sockets, a so-called Mode 2 charging system. It is portable. It consists of a control unit including a vehicle connection cable and two different mains connection cables (with household and industrial plugs). Manual switching between 100% and 50% charging power. LEDs indicate the status of the charging system and the charging process. Charging power at your vehicle up to 11 kW (three-phase) or 7.4 kW (single-phase).)
- Front seat heating (heats seat and backrest center section (standard seats in fabric), otherwise seat and backrest center section as well as seat side bolsters - individually adjustable in 3 stages for driver and front passenger via direct selection button on the climate control unit)
- Navigation: MMI Navigation plus (11.6-inch MMI Navigation plus with MMI touch including Audi connect Navigation & Infotainment - camera-based traffic sign recognition - 10.25-inch Audi virtual cockpit with two display options "Classic" and "Sport" - voice control)
- Package: Function package (storage and luggage compartment package, consisting of: - storage nets on the back of the front seat backrests - comfort cupholders in the front with clamping elements - lockable glove compartment - luggage compartment net (spider) - 12-volt socket in the luggage compartment - variable loading floor (folding 40:60) including luggage compartment cover that can be stowed under the loading floor - removable luggage compartment partition net for attachment to the body or fixing to the folding rear seat backrest)
- Package: Smartphone package in conjunction with MMI Navigation plus (Audi phone box (Bluetooth, inductive charging function) - Smartphone interface - 12-volt on-board power socket and 2 USB-C ports for charging devices)
- Paint finish: Metallic
- Steering wheel heating
- Towing device (The mechanically swiveling towing device can be conveniently locked and unlocked via a release mechanism - ball head mechanically swiveling, with electric release - ball rod and head made of forged steel - trailer stabilization via the electronic stability control (ESC) - the integrated swiveling system socket allows continuous operation of electrical devices in the trailer or caravan while driving)
- Audi connect Navigation & Infotainment plus (e-tron route planner - Online points of interest - On-street parking - Online traffic information - Hazard information - Online traffic sign information - Weather information - Wi-Fi hotspot - Online news - User profiles - Navigation with Google Satellite Map - Online search for navigation destinations - Online voice input - Online traffic information plus - Highly detailed 3D city display - Online radio - Hybrid radio - Amazon Alexa integration)
- Deletion of model designation and performance/technology lettering
- Heat pump (Within the system limits, the heat pump uses the waste heat from the electric drive components and the outside air to heat the vehicle interior. This supports the provision of the required heating power at low outside temperatures. The electrical energy not needed for heating can, for example, also have a positive effect on the vehicle's range.)
- Package: Assistance Package Plus (Adaptive Cruise Control, the system uses a radar sensor to detect vehicles ahead within the system's limits and maintains the set speed and distance as constant as possible within the control range. - Speed limiter - Parking Assist Plus, supports the driver when parking and maneuvering forwards and backwards with acoustic signals and visual display with virtual lane guidance. - Rearview camera)
- Package: Climate Control Package (The 3-zone automatic climate control electronically regulates the air temperature, volume, and distribution. An additional function is the sun-position-dependent control. The temperature settings for the driver and front passenger sides can be adjusted separately. Separate temperature control and air vents are available in the rear. The 3-zone automatic climate control features automatic recirculation in combination with a dust- and odor-removing cabin air filter. The comfort stationary climate control cools or heats the interior.)
- Radio accessories: Audi sound system (8 speakers including center speaker and subwoofer, 6-channel amplifier with a total output of 180 watts)
- Steering wheel: Double-spoke leather steering wheel with multifunction and shift paddles in conjunction with steering wheel heating or advanced driver assistance systems. (For convenient operation of the extensive standard and optional infotainment features, the steering wheel is equipped with multifunction buttons with touch control. Height and reach of the steering wheel are manually adjustable.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Sill - dent(s) - Smart repair

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 3 Jan 2025	2.427,24 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Damage 1: Side panel - rear left side: Sill - dent(s) - Smart repair



Damage 1: Side panel - rear left side: Sill - dent(s) - Smart repair



Damage 1: Side panel - rear left side: Sill - dent(s) - Smart repair