CITROÃ‹N GRAND C4 SPACETOURER

Vehicle information


Brand:	**CITROËN**	License plate:	**2CHJ124**
Gearbox:		Body color:	
Model:	**GRAND C4 SPACETOURER**	LEVEL:	**VF73AHNS2NJ655116**
Fuel type:		Power:	**96 kW**
Version:	**1.2 PURETECH 130 S/S SHINE**	First registration	**28/07/2022**
Mileage:	**84263 km**	Number of doors:	

Summary of damages


- **Back** 3
- **RIGHT** 1
- **Interior** 1
- **Roof & other** 2


Commercial photos









































Options according to the inspector

GPS	**Yes**

Damages

Bodywork
Damaged -
Acceptable.
Roof & other



Rear cover trim
with E -claw(s)
-
Replace




Damaged **Interior**
- Acceptable
Interior







Polished front right alloy wheel
with scratches on
the left - Repair and paint (complete)





Broken **trunk/tailgate seal**
E - Replace
Rear

Rear **bumper with**
scratches
- Repair and paint (complete)






Pavillon
Griffe(s)
LI - Repair and paint (complete)
Roof & other





Tires

Front Left
Summer
Aluminum
205/55/17/95/V
Hankook
4.0 mm
Front Right
Summer
Aluminum
205/55/17/95/V
Hankook
4.0 mm
Left Back
Summer
Aluminum
205/55/17/95/V
Continental
5.0 mm
Rear Right
Summer
Aluminum
205/55/17/95/V
Continental
5.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Vehicle inspection	**OK**
Vehicle inspection	**28/07/2028**	Interview	**OK**
Interview	**in 12900 km**	Repair kit	**Yes**
Number of charging cables (220V)	**0**	Number of charging cables (fast charging)	**0**
Total number of keys	**2**	Factory reset	**Yes, the vehicle has been reset to factory settings.**
Type of maintenance log	**Digital interview**		

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.