APPRAISAL REPORT



VEHICLE IDENTIFICATION

Driver name:	HM Tongeren
Make:	VOLKSWAGEN
Model / version:	PASSAT VARIANT
Wine:	WVWZZZ3CZNE002912
Plate:	2AWU408
Mileage:	90359
First registration:	19/08/2021
Color:	manga grey

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book	
Number of keys:	2
Original key:	✓


PICTURES























































WINE INFORMATION

Radio	8 speakers	Bluetooth
USB port	Sequential transmission	7 reports
5 doors	Break	Automatic headlights
Adaptive headlights	LED spotlights	Fog lights
LED taillights	Comfortline Equipment	Chrome window surround
Material: alloy	Reference letter (J)	Front diameter 16
Rear diameter 16	Front width 6.5	Rear width 6.5
Front diameter 16	Rear diameter 16	Front height 60
Rear height 60	Forward speed index V	Rear speed index V
Front width 215	Rear width 215	Additional heating
Rear air conditioning	3-zone automatic climate control	Air conditioning refrigerant 1234YF
On-board computer	Diesel	1968 cm3

2.00 liters	90 kW	122 hp
Metallic varnished	Automatic day/night interior rearview mirror	Heated front left seat
Heated front seats	Height-adjustable front left seat	Electrically adjustable front left seat
Siège avant gauche à réglage lombaire	Sièges avant sport	Garnitures cuir
Volant cuir	Volant sport	Volant chauffant
Volant multifonction	Aide au stationnement avant	Aide au stationnement arrière
Caméra avant	Caméra arrière de recul	Régulateur automatique de la distance
Equipement Stop & Start	Affichage lecture des panneaux de signalisation	Carte mains libres
Ouverture du coffre électriquement	détecteur de pluie essuie-vitre	Airbag passager désactivable
Airbag de genoux	Protection piéton	Assistant maintien de la voie
Freinage d'urgence assistée autonome (urbain)	depuis 07.21	radio avec récepteur digital
BlueMotion Technology	éclairage périphérique Ambiente équipement 2	rétroviseurs électrique, rabattables, chauffants et d inclinable vers le bas
antenne AM/FM	GARNIT PORTE SIMILI	traitement des gaz d'échappement avec catalyseur SCR
roues av motrices (traction)	norme anti-pollution Euro 6 AP	Online services
ceintures de sécurité ar avec prétensionneurs	entretien à intervalle flexible (Long Life) QI6	spoilers latéraux noir gloss (petits)
freins ar 300x12		

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		215/60R16 95V	Summer		?
Front right	5 mm		215/60R16 95V	Summer		?
Rear left	5 mm		215/60R16 95V	Summer		?
Rear right	5 mm		215/60R16 95V	Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Boot cover	Grooved
2	Inner door sill RR	Dent(s) and scratch(es)
3	Bumper F	Grooved
4	Bumper spoiler F	Grooved
5	Outside rear-view mirror housing L	Scratches
6	Door RL	Teeth and scratches
7	Inner door sill RL	Teeth and scratches
8	Wing RL	Teeth)
9	Roof	Chemical pollution
10	Bumper R	Teeth and scratches
11	Bodywork - Heel of auto moet gepolijst worden	Chemical pollution

#	Location	Damage type
12	Cap	Teeth and scratches

Total: 12

ACCEPTABLE / NOT TO BE INVOICED

#	Rental	Damage type	Renta®	Repaired	Already invoiced


No damages present

DAMAGE DETAILS

1 - Boot cover - Grooved









2 - Inner door sill RR - Dent(s) and scratch(es)






3 - Bumper F - Grooved









4 - Bumper spoiler F - Grooved








5 - Outside rear-view mirror housing L - Scratch(es)

6 - Door RL - Dent(s) and scratch(es)




7 - Inner door sill RL - Dent(s) and scratch(es)








8 - Wing RL - Tooth(s)









9 - Roof - Chemical pollution





10 - Bumper R - Dent(s) and scratch(es)








11 - Bodywork - Heel of car moet gepolijst worden - Chemical pollution








12 - Bonnet - Tooth(s) and scratch(es)






SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

26/10/2026 10:47

