ARVAL
BNP PARIBAS GROUP

2BVM781

INSPECTION REPORT

End of contract

GENERAL INFO

File	324930
License plate	2BVM781
Vehicle identification number	TMBGP6NW6N3084941
Dossier	2021281047
Make	Skoda Kamiq 1.0TSI 70kW Clever
Mileage	163156
First registration	07/04/2022
client availability date	14/10/2026
inspectionDate	21/10/2026










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




2-BVM-781
KEURING
BELCAR

DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
139	Bumper Rear / Spoiler / Replace	N
14	Bumper Front // Repair & Painting	N
111	Wing Rear Left // Smart Repair Medium	Y
193	Door Rear Right // Painting	Y
216	Door Front Right // Polish	Y
321	Wheel Alloy Rear Left // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Wing Rear Left // Smart Repair Medium-scratch




Bumper Front // Repair & Painting-scratch + dent





Door Front Right // Polish-scratch




Door Rear Right // Painting-scratch




Bumper Rear / Spoiler / Replace-scratch


Bumper Rear // Painting-scratch