TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48023421
Order No. / Reference: 26837733
Inspection date: 9 Oct 2026

Manufacturer: Mercedes-Benz	Model: GLE 300 d 4Matic 9G-TRONIC AMG Line
VIN: W1NFB0KB5PA964769	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz GLE 300 d 4Matic 9G-TRONIC AMG Line	
Vehicle Identification number	W1NFB0KB5PA964769
Mileage (Read)	92,253 km
First registration	5 Jul 2023
Number of holders	1
Next periodical technical inspection (Report on hand)	07/2026
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,993 ccm / 4
Power	200 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	SCHWARZ - UNILACK
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	75 Tag(e)
Last service on / at	10/2025 at 77,109 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV710250
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / AXS 00240		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,000 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	285/40 R22 106Y	Summer tyres on Light alloy	Pirelli	4mm / 4mm
2)	325/35 R22 110Y	Summer tyres on Light alloy	Pirelli	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	275/50 R20 113V	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	275/50 R20 113V	Winter tyres on Light alloy	Continental	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Exhaust system with 2 chrome-plated tailpipe trims
- Adaptive Highbeam Assist
- Adaptive brake light (flashing)
- Airbag: Kneebag for driver
- Airbag: Windowbags
- Active Brake Assist
- 4MATIC permanent all-wheel drive
- AMG floor mats in black velour with "AMG" lettering
- AMG sports pedal assembly made of brushed stainless steel with black rubber studs
- Anti-lock braking system
- Traction control (ASR)
- Foldable armrest for driver and front passenger (with storage compartment)
- Rear armrest (foldable)
- Automatic passenger airbag deactivation
- Electrically adjustable and heated exterior mirrors
- Brake Assist BAS (with brake force support during detected emergency braking)
- Downhill Speed Regulation (DSR) (Speed setting between 2 and 18 km/h via the cruise control - switch for turning it on and off in the center console - display in the multimedia display)
- EASY-Pack cargo cover (removable)
- Front door sills with "Mercedes-Benz" lettering illuminated in white
- Chassis with steel springs and lowered suspension (steel springs with passive damping system)
- Speed Limit Assistant (camera behind the windshield - uses image recognition to determine the maximum permissible speed of the currently driven route based on the corresponding signage - if there are no signs, additional information such as the lane width can be used to determine the maximum permissible speed - display of speed limits including restrictive additional signs in the instrument cluster and in the optionally available display)
- Interior headliner fabric crystal grey
- Mechanical child safety locks in the rear doors (and electric locks for the rear window regulators)
- Communication module (LTE) for using Mercedes me connect services (The communication module (LTE) offers you a clear increase in comfort and safety. It constantly connects the vehicle to the internet – so that you can use helpful services such as the Live Traffic Information from Mercedes me connect. Two mobile antennas and an LTE-enabled SIM card ensure a fast connection.)
- Headrests adjustable in 5 positions (height and tilt)
- Radiator grille with 2 chrome-plated louvers in SUV design
- ADAPTIVE BRAKE (with HOLD function - including hill start assist and drying brakes in wet conditions)
- Airbag: Driver and passenger side
- Airbag: Sidebag for driver and front passenger (combined thorax/ pelvisbag)
- Active Lane Keeping Assist
- Ambient lighting (ambient lighting in 64 colors - all colors can be selected individually - brightness of the lighting zones can be selected from 0 to 100% frei - nine color schemes with different color combinations - Dynamic mode: atmospheric color change through slow, continuous transition between different colors - Climate effect: color feedback when the temperature setting is changed - Welcome effect: special lighting when entering the vehicle)
- ATTENTION ASSIST (can detect typical signs of fatigue through driver behavior and warn the driver of increasing fatigue or inattentiveness)
- Roof rails in aluminum look
- Diesel particulate filter
- Tachometer
- Third brake light
- EASY-Pack tailgate with electric operation for opening and closing
- ECO start/stop function
- Electronic Stability Program (ESP)
- Electronic traction system for all-wheel drive (4ETS)
- Electric windows, front and rear
- electric parking brake
- Transmission: 9G-TRONIC (9-speed automatic transmission - DIRECT SELECT selector lever - DIRECT SELECT steering wheel shift paddles - DYNAMIC Select)
- Lockable, air-conditioned and illuminated glove compartment
- Heated rear window (with timer)
- Rear window wiper with intermittent function (and automatic activation when reversing)
- KEYLESS-GO start function
- Climate: THERMATIC automatic climate control (2-zone automatic climate control: allows individually adjustable temperature for driver and front passenger - climate settings controlled via the instrument panel controls or the touchscreen - sensor system for detecting, for example, interior/exterior temperature, sunlight, humidity and dew point - combination activated carbon filter for filtering dust, soot and pollen - windshield fogging sensor - recirculation mode activated by pressing the button for 2 seconds (with sunroof closing))
- Paint finish: Metallic
- Steering wheel: Multifunction sports steering wheel in Nappa leather (The multifunction sports steering wheel in Nappa leather with chrome controls is flattened at the bottom and perforated in the grip area – an excellent feature for sporty driving. You will not only see this, but feel it immediately when you touch the steering wheel. The high-quality, soft Nappa leather is also a premium experience in itself.)

- LED High Performance Headlights (Signal light with trifunctional torch for daytime running light, position light and turn indicator in LED light guide technology with thick-walled optics; high beam in LED reflection technology; low beam in LED projection technology; the elements of the rear lights in LED technology: all light functions in full LED technology; tail light; brake light and parking light; rear fog light (only on the left side); turn indicator in the white light strip; reversing light in the white light strip)
- Mercedes-Benz emergency call system
- Navigation accessories: Pre-installation for navigation services (Wherever you go, you're always well-informed. Your vehicle answers your questions about your journey and you can find out current fuel prices at your destination, the number of available parking spaces, or the current weather. This makes trip planning even easier.)
- Package: Chrome (window line trim strip, front and rear underride protection, chrome-plated beltline trim strip)
- Package: Chrome Interior Package (controls and trim strip in the door interior in silver chrome - controls to the left of the steering wheel in silver chrome - touchpad, hand rest, control switches and cupholder of the center console in silver chrome - climate control strip in silver chrome)
- Package: Parking package with reversing camera (Active Parking Assist with PARKTRONIC)
- Upholstery: ARTICO leatherette/DINAMICA microfiber
- PRE-SAFE system (with reversible belt tensioners for driver and front passenger seats and closing function for side windows)
- Radio accessories: Digital radio (DAB)
- Radio accessories: Additional USB ports
- Tire pressure monitoring system (TPMS)
- Wheels: 45.7 cm (18") light alloy wheels in 10-spoke design (vanadium silver painted with 235/60 R 18 on 8 J x 18 ET 52.5)
- Windscreen wipers with rain sensor
- Power steering
- 3-point safety belts (including mechanical belt height adjustment and belt force limiter for driver and front passenger as well as automatic belt height adjustment in the rear outer seats)
- Seats: Sports seats for driver and front passenger with specific seat graphics (fully electric seat adjustment)
- Cruise control with variable speed limiter
- High-visibility vest for drivers
- Immobiliser
- Heat-insulating glass, all around
- Central locking with interior switch (including automatic locking (can be deactivated) and crash sensor with emergency opening)
- Decorative elements: Brushed aluminum with light longitudinal grain
- Steering column mechanically adjustable lengthwise and heightwise.
- Navigation accessories: Extended MBUX functions (personalization (profiles) and prediction functions - LINGUATRONIC with natural language understanding - activation via "Hey Mercedes" - Wi-Fi hotspot - internet radio)
- Navigation: Hard drive navigation (Mercedes-Benz look and feel of the navigation system, all map data stored on the hard drive - fast hard drive navigation - destination input via touch function or voice control - route calculation including waypoints - numerous route options and avoidance options - 3D image of the upcoming driving maneuver and lane recommendation - easy switching between 2D and 3D views - compass - route recording function (prerequisite: a USB device is connected to the multimedia system))
- Package: Mirror package (both exterior mirrors electrically folding (button in the driver's door control panel) - automatic lowering of the passenger-side mirror glass to the parking position when reverse gear is engaged - interior mirror and driver's side exterior mirror automatically dimming - ambient lighting in both exterior mirrors: with projection of the brand logo to illuminate the entry area)
- Remote Services Plus (The Remote Services Plus package transforms mobility into a new experience, offering greater comfort and safety. Status queries provide information about the remaining range. You can remotely control certain functions and locate your vehicle. Services such as maintenance management coordinate service appointments, saving you valuable time.)
- Seats: 4-way lumbar support for driver and front passenger
- Seats: Heated seats for driver and front passenger seats
- Seats: Rear seat backrests foldable (40/20/40 split ratio)
- Phone accessories: Smartphone integration (Android Auto and Apple CarPlay). Smartphone integration merges the mobile phone with the media system via Apple CarPlay and Android Auto.
- Widescreen Cockpit (instrument display and media display as an optical unit under a continuous cover glass - display cluster consisting of two fully digital color displays in flatscreen look with a screen diagonal of 12.3 inches each and a resolution of 1920 x 720 pixels - touchscreen version for the media display - display styles: "Classic", "Sport", "Progressive" and "Discreet")

Extra equipment

- Airbag: Sidebags in the rear, left and right
- Towbar with ESP trailer stabilization
- Black fabric headliner
- Fuel tank with larger volume (85 l)
- Chrome-look loading sill protector
- Package: AIRMATIC package (air suspension system with adaptive damping system ADS+ - automatic level control, depending on - payload: load detection for a constant chassis level - driving speed: lowering for higher driving speeds - DYNAMIC SELECT driving program: lowering in the "Sport"/"Sport plus" program or raising in the "Offroad"/"Offroad plus" program - demand-based level control: - rear lowering for loading and unloading - individual selection of the chassis level)
- Package: Driving Assistance Package Plus (Active Distance Assist DISTRONIC - Active Steering Assist - Active Brake Assist - Evasive Steering Assist - Active Lane Keeping Assist - Active Blind Spot Assist - PRE-SAFE PLUS - Active Traffic Jam Assist)
- Package: KEYLESS-GO Comfort Package (vehicle key with KEYLESS-GO functionality - KEYLESS-GO access and drive authorization system - start/stop button - comfort opening and closing - door handles with chrome inlay - HANDS-FREE ACCESS - handle recess lighting - remote trunk lid closing - EASY-PACK tailgate)
- Package: Parking Package with 360° camera (12 sensors: four front, four rear, two on the sides in the front/rear bumper; detects parking spaces up to 35 km/h; steering control; in conjunction with automatic transmission, assists with acceleration, braking, and gear changes; 360° camera; visual/audible warning of detected obstacles in front of/ behind the vehicle up to approx. 10 km/h; Rear Cross Traffic Alert warns of detected cross traffic; Drive Away Assist (only in conjunction with automatic transmission); button on the center console or on the control panel for the assistance systems)
- Protection and preservation (The reversible mat helps in two ways: With its fine velour side, it effectively protects the cargo area from dirt, while its rubberized side prevents cargo from slipping. The foldable zigzag loading sill protector with Velcro fastening can prevent clothing from getting dirty or the paintwork from being scratched during loading and unloading.)
- Partition net for luggage compartment separation and occupant protection
- Illuminated running boards in aluminum look with rubber studs
- Type designation removed from luggage compartment lid
- WKR 5-twin-spoke wheel, Himalayan Grey Matt
- Decorative elements: Linden wood, anthracite glossy
- Trailer maneuvering assistant (assistance system - articulation angle sensor in the ball head of the trailer hitch - rotating magnetic ring on the ball head)
- Paint finish: Solid
- Package: AIR-BALANCE (fragrance generator with filled fragrance bottle and function button in the glove compartment - ionizer in the side nozzle channel - improved filter system between the intake area and the air distribution system of the air conditioning unit)
- Package: AMG Line Exterior (diamond grille with chrome pins, integrated Mercedes star and one louvre painted in matte iridium silver with chrome inserts - AMG Styling: AMG front apron with chrome trim strip, sporty and distinctive air intakes in the wheel arch trims, fender flares front and rear in body paint, AMG side sill trims, AMG rear apron with diffuser-look insert in black and chrome trim strip - AMG light-alloy wheels in 5-twin-spoke design, painted tremolite grey and polished with front axle 275/50 R 20 on 9 J x 20 ET 57, rear axle 275/50 R 20 on 9 J x 20 ET 44)
- Package: Night (Diamond grille with chrome pins and high-gloss black louvre; AMG light-alloy wheels in 5-twin-spoke design, high-gloss black lacquer and gloss black, with front axle 275/50 R 20 on 9.0 x 20 ET 57, rear axle 275/50 R 20 on 9.0 x 20 ET 44; AMG front windscreen in A-wing design with high-gloss black trim strip; AMG rear windscreen with high-gloss black diffuser and high-gloss black trim strip; air intakes in radiator grille and front windscreen; roof rails in matte black; heat-insulating dark-tinted glass from the B-pillar; exterior mirror housings in high-gloss black; window trim and beltline trim in black)
- Wheels: 55.9 cm (22") AMG light-alloy wheels in 5-twin-spoke design (painted in high-gloss black and polished with front axle 285/40 R 22 on 10.0 J x 22 ET 56.1, rear axle 325/35 R 22 on 11.0 J x 22 ET 50)
- Sunroof: Panoramic sunroof (large glass module made of heat-insulating, tinted safety glass - mesh wind deflector in the front area - electric sunshade with one-touch operation - comprehensive protection concept: - anti-pinch protection - automatic rain closing - PRE-SAFE closing function (only in conjunction with PRE-SAFE system))
- Auxiliary heater (with auxiliary ventilation)
- Telephone accessories: Wireless charging system for mobile devices (wireless charging for compatible mobile phones - fast connection setup between multimedia system and mobile phone via Near Field Communication (NFC) for identification of the mobile device - storage compartment for wireless charging is located in the storage compartment at the front of the center console)
- Heat-insulating dark tinted glass

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Sill - dent(s) - Smooth repair work
2	Misc.	Main inspection - Due - Replace
3	Interior	Interior (Hundegeruch) - Odour - Ozone treatment
4	Door - rear right side	Door - Scratch(es) - Smart repair
5	Interior	Interior (Tierhaare) - Soiled - Clean
6	Trim / covers	Boot lining - Scratch(es) - Replace
7	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
8	Wheel / tyres	Alloy rim - front left side - Scratched - Loss in value
9	Rear bumper	Rear bumper (+ Spoiler lackieren) - Scratch(es) - Paint
10	Front bumper	Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Door - rear right side	Door - dent(s) - Smooth repair work

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.






Figure 35: Misc.



Damage 1: Side panel - rear left side: Sill - dent(s) - Smooth repair work



Damage 1: Side panel - rear left side: Sill - dent(s) - Smooth repair work



Damage 2: Misc.: Main inspection - Due - Replace



Damage 4: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 4: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 5: Interior: Interior (Tierhaare) - Soiled - Clean



Damage 5: Interior: Interior (Tierhaare) - Soiled - Clean



Damage 5: Interior: Interior (Tierhaare) - Soiled - Clean



Damage 5: Interior: Interior (Tierhaare) - Soiled - Clean



Damage 5: Interior: Interior (Tierhaare) - Soiled - Clean




Damage 6: Trim / covers: Boot lining - Scratch(es) - Replace




Damage 6: Trim / covers: Boot lining - Scratch(es) - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 8: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 8: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 8: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 8: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 8: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 8: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 9: Rear bumper: Rear bumper (+ Spoiler lackieren) - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper (+ Spoiler lackieren) - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper (+ Spoiler lackieren) - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper (+ Spoiler lackieren) - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper (+ Spoiler lackieren) - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper (+ Spoiler lackieren) - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper (+ Spoiler lackieren) - Scratch(es) - Paint




Damage 9: Rear bumper: Rear bumper (+ Spoiler lackieren) - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper (+ Spoiler lackieren) - Scratch(es) - Paint



Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation



Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation




Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation



Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation



Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation




Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation



Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation




Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation




Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation



Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation



Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation




Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation




Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation



Damage 10: Front bumper: Front bumper (+Zierleiste links unten lose+ rechtes verkratzt erneuern) - Dent / paintcoat damage - repair according to calculation




Wear and tear 1: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - No deduction



Wear and tear 1: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - No deduction



Wear and tear 3: Door - rear right side: Door - dent(s) - Smooth repair work



Wear and tear 3: Door - rear right side: Door - dent(s) - Smooth repair work