APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	PEUGEOT
Model / version:	BOXER 435 LWB DSL - 2014
Vin:	VF3YDBNDC12S05034
Plate:	2AHB248
Mileage:	83184
First registration:	31/03/2021
Color:	Banquise Wit

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	1
Original key:	✗

PICTURES












































VIN INFORMATION

Radio	Système navigation	Commande radio au volant
Prééquipement Bluetooth	Prise USB	Boîte manuelle
6 rapports	Plateau simple cabine	Plateau double cabine
4 035 mm	3 500 kg	Matière : tôle
Lettre repère (J)	Diamètre avant 16	Diamètre arrière 16
Largeur avant 6,5	Largeur arrière 6,5	Diamètre avant 16
Diamètre arrière 16	Hauteur avant 75	Hauteur arrière 75
Indice de vitesse avant C	Indice de vitesse arrière C	Largeur avant 225
Largeur arrière 225	Diamètre 16	Climatisation
Climatisation réfrigérant R134A	Diesel	2179 cm3
2.20 litres	103 kw	140 ch
Euro 6	Filtre à particules	Unie vernissée

Rétroviseur gauche à réglage électrique
Garnitures simili-cuir
Equipement Stop & Start
depuis 12.20
protection sous mécanique
Rétroviseur droit à réglage électrique
Suspension renforcée
Programme électronique de stabilité ESP
siège conducteur avec accoudoir
réservoir carburant 90 L
Siège avant gauche à réglage lombaire
Régulateur et limiteur de vitesse
Antipatinage ASR / ASC+T
banquette passagers av à 2 places

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm	Pirelli	225/75/R16/118R	Summer	Steel	×
Front right	5 mm	Pirelli	225/75/R16/118R	Summer	Steel	×
Rear left	5 mm	Pirelli	225/75/R16/118R	Summer	Steel	×
Rear right	5 mm	Pirelli	225/75/R16/118R	Summer	Steel	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Contact key	Forced
2	Dashboard	Broken
3	Roof liner	Dirty
4	Interior	Dent(s) and scratch(es)
5	Bonnet	Dent(s) and scratch(es)
6	Bonnet	Broken
7	Inner door sill FL covering	Dent(s) and scratch(es)
8	Door seal FL	Forced
9	Door RR	Dent(s) and scratch(es)
10	Door FR	Dent(s) and scratch(es)
11	Compressor	Missing

Total: 11

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced

No damages present

DAMAGES DETAILS

1 - Contact key - Forced



2 - Dashboard - Broken







3 - Roof liner - Dirty






4 - Interior - Dent(s) and scratch(es)



5 - Bonnet - Dent(s) and scratch(es)




6 - Bonnet - Broken






7 - Inner door sill FL covering - Dent(s) and scratch(es)




8 - Door seal FL - Forced




9 - Door RR - Dent(s) and scratch(es)





10 - Door FR - Dent(s) and scratch(es)





11 - Compressor - Missing



SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

27/10/2026 08:28

