TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48293485
Order No. / Reference: 27170335
Inspection date: 23 Oct 2026

Manufacturer: Volkswagen	Model: Touran 2.0 TDI SCR DSG Highline
VIN: WVGZZZ1T8RW004717	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Touran 2.0 TDI SCR DSG Highline	
Vehicle Identification number	WVGZZZ1T8RW004717
Mileage (Read)	173,599 km
First registration	19 Sept 2023
Number of holders	1
Next periodical technical inspection	09/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Delfingrau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	3,600 km
Last service on / at	03/2026 at 147,541 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV406326
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / BWR 00507		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,230 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 94V	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	215/55 R17 94V	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	205/60 R16 96H	Winter tyres on Light alloy	Pirelli	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment with lid on the instrument panel
- Airbag for driver and front passenger
- Ambient lighting
- Electrically folding exterior mirrors
- Exterior mirror housings and door handles in body color
- Chrome trim on the side windows
- Roof rails, silver anodized
- Diesel particulate filter
- Tachometer
- Electronic parking brake including auto-hold function
- Automatic headlight control with daytime running lights
- Windscreen made of laminated safety glass, heat and sound insulating
- Baggage management package
- Additional luggage compartment lighting
- Transmission: 7-speed DSG
- Rear window heated
- Interior lights with delayed shut-off and dimming function, 2 LED reading lights front and rear
- Air conditioning system "Air Care Climatronic"
- Front headrests
- Paint finish: Solid
- LED headlights with daytime running lights
- Dynamic headlight range control
- Illuminated makeup mirrors in the sun visors
- Multifunctional camera
- Fog lights and cornering lights
- Emergency braking assistant "Front Assist" (for automatic distance control ACC up to 210 km/h)
- Proactive occupant protection system in conjunction with "Front Assist" and "Side Assist"
- Radio accessories: Digital radio reception DAB+
- Wheels: Tire Mobility Set omitted
- Wheels: Tire pressure monitoring system
- Automatically heated front windshield washer nozzles
- Keyless start system without safe locking
- electromechanical power steering
- Seats: 3 individual seats in the 2nd row
- Seats: Folding tables on the backs of the front seats
- Seats: Lumbar support in the front
- Seats: Heated front seats
- Lane keeping assistant “Lane Assist”
- Start-stop system
- Bumpers in body color
- Textile floor mats
- First aid kit, warning triangle and high-visibility vest
- Prepared for later activation: Discover Media navigation function incl. streaming & internet
- Electronic immobilizer
- Storage compartments in the overhead console
- Airbag: Side airbags for the outer seats of the 2nd row.
- Adaptive Cruise Control (ACC) "stop & go", with speed limiter
- third brake light
- Headliner in Storm Grey
- Decorative inlays "Piano Black"
- Digital Cockpit Pro, multicolor
- Parking assistance
- Electronic Stability Program (ESP) with counter-steering support
- Pedestrian and cyclist detection as well as active front hood
- luggage compartment cover
- Height-adjustable luggage compartment floor
- Glove compartment with cooling option
- Rear window wiper with intermittent function
- Interior mirror automatically dimming
- ISOFIX mounting points on rear seats
- Headrests (3) in the 2nd row of seats
- Black radiator grille with chrome strips on the slats
- LED light in the front footwell
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters
- front center armrest
- Fatigue detection
- Non-smoking version
- Emergency call service
- Upholstery in microfleece “ArtVelours”
- Radio
- Radio accessories: 8 speakers
- Rain sensor
- Wheels: Light alloy (4) "Alexandria" 6.5 J x 17
- Gearshift knob in leather
- Headlight cleaning system
- Drawers under the front seats
- Seat belts: 3 three-point automatic seat belts in the rear
- Seats: Front passenger seat backrest folds down completely
- Seats: Top comfort seats in the front
- Seats: Front seats are height-adjustable
- Lane change assistant "Side Assist" and parking assistant
- 12V power outlet on the rear of the center console
- Telephone interface
- USB-C interface
- Prepared for "We Connect" and "We Connect Plus"
- Washer fluid level warning light
- Warning tone and light for unfastened front seat belts
- Green thermal insulation glazing

- Central locking without safe locking, with remote control and 2 remote folding keys

Extra equipment

- Anti-theft alarm system (with interior monitoring, backup horn and tow-away protection)
- Navigation system "Discover Pro" incl. "Streaming & Internet" (23.4 cm (9.2 inch) touchscreen with voice control and traffic sign recognition - navigation system - USB-C interfaces and a mobile phone interface via Bluetooth - DAB+C - App-Connect Wireless for Apple CarPlay and Android Auto - voice control)
- Package: Business Premium incl. Navigation (DSG) (Air Care Climatronic air conditioning - Lumbar support front, electrically adjustable on driver's side, massage function driver's side - Multifunction leather steering wheel with shift paddles - Cargo net partition - Automatically heated windshield washer nozzles front - Headlight cleaning system - Drawer under the right front seat - Microfleece seat center panels "ArtVelours" - Top comfort seats front - Heated front seats - Height-adjustable front seats, ergoActive seat on the driver's side - Washer fluid level warning light)
- Package: Top package (Highline) (Panoramic tilt/slide sunroof with panoramic roof at the rear - LED taillights - Darkened rear side windows and rear window)
- Rear View reversing camera (displays the rear of the vehicle in real time on the radio/navigation system display)
- 230V power outlet in the luggage compartment on the left (additional luggage compartment lighting, removable and usable as a flashlight)
- Front USB-C ports (2) (2 USB-C charging ports on the rear center console; charging power up to 45 W)
- Steering wheel: Multifunction leather steering wheel, heated, with paddle shifters
- Package: "Easy Open & Close" package with safe locking (tailgate with sensor-controlled opening and closing, with remote unlocking - keyless locking and starting system "Keyless Access" with safe locking)
- Package: Assistance package "IQ.DRIVE" incl. IQ.LIGHT (DSG) (Dynamic Light Assist high beam - Travel Assist, Lane Assist and Emergency Assist - LED headlights with LED daytime running lights and cornering lights - Dynamic headlight range control with dynamic cornering lights)
- Package: Exterior Design Package "Black Style" for Highline (Exterior mirror housings in black and door handles in body color - roof rails in black - radiator grille in black with chrome strip on lower louvre - bumpers in body color - trim strips in black on the side windows)
- Package: Family (foldable and removable reversible luggage compartment mat - electric child safety lock for rear doors, operable from the driver's seat - sunshade roller blind on the rear door windows)
- Wheels: Winter wheels (additional) LM "Karlstad" 6.5 J x 16 (4 light alloy wheels 6.5 J x 16 - on-board tools and jack - AirStop winter tires 205/60 R 16 H)
- Seats: ergoActive seat with 14-way adjustment and massage function in front in conjunction with Business Package Premium (ergoActive front seats height-adjustable, seat and backrest tilt adjustable - lumbar support in front electrically adjustable and with massage function - without drawers under the front seats - seat center panels in microfleece "ArtVelours" - top comfort seats in front - heated front seats)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Vehicle key with remote control (Batterie) - Empty - Replace
2	Wheel / tyres	Tyre - front right side (Flanke) - Damaged - Replace
3	Side panel - rear left side	Side panel - Dent / paintcoat damage - Smart repair
4	Sill - right side	Sill - Unprofessionally repaired - Repair and paint
5	Door - rear right side	Door - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet (Oberflächlich) - Scratch(es) - No deduction
2	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
2nd wheel set - Wheel cover set - complete (4x Nabendeckel)

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 31 Mar 2025	1.375,05 €
2	Side right, Provided by user / customer, from 8 Jul 2026	3.492,74 €
3	Front, Side right, Provided by user / customer, from 10 Apr 2024	4.794,55 €
4	Front, Side - left, Side right, Provided by user / customer, from 15 Apr 2025	11.938,46 €

Repainting

No.	Repainting
1	Roof, Professionally carried out, Invoice of repair done Non-existent
2	Bonnet, Professionally carried out, Invoice of repair done Non-existent
3	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
4	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Roof	155 µm	Bonnet	152 µm
Door - rear right side	221 µm	Door - front right side	147 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Damage 2: Wheel / tyres: Tyre - front right side (Flanke) - Damaged - Replace



Damage 2: Wheel / tyres: Tyre - front right side (Flanke) - Damaged - Replace



Damage 3: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 4: Sill - right side: Sill - Unprofessionally repaired - Repair and paint



Damage 4: Sill - right side: Sill - Unprofessionally repaired - Repair and paint



Damage 4: Sill - right side: Sill - Unprofessionally repaired - Repair and paint



Damage 4: Sill - right side: Sill - Unprofessionally repaired - Repair and paint




Damage 4: Sill - right side: Sill - Unprofessionally repaired - Repair and paint




Damage 4: Sill - right side: Sill - Unprofessionally repaired - Repair and paint



Damage 5: Door - rear right side: Door - Scratch(es) - Paint




Damage 5: Door - rear right side: Door - Scratch(es) - Paint



Damage 5: Door - rear right side: Door - Scratch(es) - Paint



Damage 5: Door - rear right side: Door - Scratch(es) - Paint



Damage 5: Door - rear right side: Door - Scratch(es) - Paint



Damage 5: Door - rear right side: Door - Scratch(es) - Paint



Damage 5: Door - rear right side: Door - Scratch(es) - Paint



Missing part 1: 2nd wheel set: Wheel cover set - complete (4x Nabendeckel) - Missing - Replace



Repainting 1: Roof



Repainting 2: Bonnet



Repainting 3: Door - rear right side



Repainting 4: Door - front right side