BMW

VIN: WBA11AK0X07L94647



Description

Registration number 2DAH434	**First registration date** 13/01/2023	**Odometer** 116459 km
Color SUNSET ORANGE METALLIC	**Model year** 2020	**Upholstery** -
Number of doors 4	**Number of seats** 5	**Generation** -
CO2 149	**Engine displacement** 1499	**Gearbox type** Automatic
Engine type Combustion	**Number of gears** 7	**Drivetrain** Front Wheel Drive (FWD)
Max power 100 KW		

Vehicle Equipments

Climate control	Alloy wheel rims	Rain-sensitive wipers
Automatic headlights	SATNAV	Park Assist
Cruise control		

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 21/10/2026	**Inspection approval date** 22/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Rim / Front Right Rim/Tyre diameter : 16 "	Scratched	Repair

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.






002	Bumper / Front Painted : Yes	Scratched	Smart repair




003	Bumper / Back [1] Painted : Yes	Scratched	Acceptable









004	Tailgate / Boot door / -	Paint etching	Polishing




005	Wing / Back Left Windowed : Yes	Scratched	Smart repair




[1] Avec rayures

Loose Items

- [x] Load cover
- [x] Conformity certificate
- [x] Registration certificate
- [x] Registration certificate owner
- [x] Card key
- [x] Spare Key

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	GOODYEAR	205/55/16 Summer	8 mm
Front Right	GOODYEAR	205/55/16 Summer	8 mm
Back Left	BRIDGESTONE	205/55/16 Summer	7 mm
Back Right	BRIDGESTONE	205/55/16 Summer	7 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat




Front passenger compartment



Front right



Odometer



Navigation




Vin




Other

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Other



Other



Other



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Bumper / Front / Scratched



Bumper / Front / Scratched



Bumper / Back / Scratched




Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Tailgate / Boot door / - / Paint etching

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Tailgate / Boot door / - / Paint etching



Wing / Back Left / Scratched



Wing / Back Left / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.