TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48546738
Order No. / Reference: 27262161
Inspection date: 4 Nov 2026

Manufacturer: Renault	Model: Trafic Blue dCi 150 Life
VIN: VF1JL000269817632	





Vehicle details

Manufacturer / Type / Model / Equipment	
Renault Trafic Blue dCi 150 Life	
Vehicle Identification number	VF1JL000269817632
Mileage (Read)	115,436 km
First registration	5 Dec 2022
Number of holders	2
Fuel type	Diesel
Engine displacement / Cylinder	1,997 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Weiß Uni
Doors / Seats	4 / 8
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	
Last service on / at	03/2025 at 81,998 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ429610
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	3333 / BOQ 00693		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,995 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 106H	Summer tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm
2)	215/65 R16 106H	Summer tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	Winter tyres on Light alloy	Firestone	7mm / 7mm
2)	205/65 R16 107T	Winter tyres on Light alloy	Firestone	7mm / 7mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 4.2-inch color instrument panel
- ABS with brake force distribution
- Airbag: Front airbag for driver and front passenger (can be deactivated)
- Brake assist (with automatic activation of the hazard warning lights during emergency braking)
- ESP with load detection, extended grip and hill start assist
- Window: Pane with sliding window, front left
- luggage compartment cover
- Rubber flooring
- Tailgate, glazed, with heated rear window and rear window wiper
- Child safety lock on the side sliding door
- Rear headrests (6) (height adjustable)
- Paint finish: Solid
- Steering wheel adjustable in 2 ways (depth, height)
- Mobility set
- Pollen filter
- Mudguard centre covers
- Tire pressure monitoring system
- Self-cleaning diesel particulate filter
- Wheels: 16-inch steel rims with 215/65 R 16 tires
- Sliding door, right with sliding window
- Power steering
- Seats: Passenger seat "Comfort", 3-way adjustable (with enhanced lateral support, adjustable lumbar support and armrest)
- Seats: Bench seat for three people (in the third row - removable, foldable and rollable)
- Front bumper (rear light carrier, side sliding door rail and exterior mirrors in body color, - side protection strips and door handles in black plastic)
- Electronic immobilizer
- Central locking with remote control (including automatic door locking when driving off)
- Storage compartments in the doors (driver's and passenger's door)
- Exterior mirrors, electrically adjustable and heated (with wide-angle insert)
- third brake light
- Tachometer
- Fixed window on the left
- Electric front windows (with one-touch function)
- Transmission: 6-speed manual transmission
- Illuminated glove compartment (cooled when in conjunction with air conditioning)
- Keycard Handsfree (Automatic unlocking of doors and/or tailgate upon approach - Starting at the touch of a button)
- Front headrests (2), height adjustable
- LED headlights with daytime running lights
- light sensor
- rear fog light
- Upholstery: Fabric "Java"
- Radio: Radio Connect R&GO (Digital radio DAB+, FM radio - Bluetooth hands-free system - USB and AUX connection, audio streaming - control satellite on the steering wheel)
- Shift point indicator
- Rear side windows and rear window tinted
- Seats: Armrests on rear seats
- Seats: Driver's seat "Comfort", 3-way adjustable (with enhanced lateral support, adjustable lumbar support and armrest)
- Seats: Bench seat for three people (in the second row - removable)
- Cruise control with speed limiter
- Paneling of the side surfaces in the passenger compartment, complete
- Heat-insulating glass

Extra equipment

- 2. Battery with disconnect switch (for voltage converter)
- Airbag: Side airbags and front windowbags
- Parking assistance rear, front and side
- Bott Interior Fittings - Order No. 4700101358
- Assembly
- Package: Smoker's package (cigarette lighter - ashtray)
- Radio: EASY LINK 8-inch with smartphone integration (online multimedia system with 8-inch touchscreen - smartphone integration via Android Auto or Apple CarPlay - DAB+ digital radio, FM and AM radio - Bluetooth hands-free system - USB port, audio streaming - voice control - steering wheel controls)
- Strip fuse MEGA 200 A
- First aid kit, high-visibility vest, warning triangle, spare bulb
- Winter complete wheels Bridgestone 225/65 R16
- 3 x 12V sockets
- Trailer hitch
- EUROVIA logos and lettering according to corporate design
- Package: Sound & Climate Package Plus with Navigation (front and rear air conditioning with quick heater - EASY LINK multimedia system incl. navigation - separate auxiliary heater for passenger compartment)
- Rear view camera
- Safety partition net (to protect against loose luggage)
- Seats: Driver and front passenger seats are heated (with double passenger seat only for the driver, - with single passenger seat for driver and front passenger)
- Warning marking according to DIN 30710

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Seat - front	Seat cover - left side - Soiled - Clean
3	Seat - front	Seat cover - right side - Soiled - Clean
4	Engine	Engine cover - Damage caused by marten / rodent - Replace
5	Body	Body - Glued / labelled - De-glue / neutralise
6	Wing mirror - right side	Cap - Broken / torn - Replace
7	Vehicle glazing	Windscreen (kein Staubschutz) - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Scratch(es) - No deduction
2	Door - front right side	Door - Scratch(es) - No deduction
3	Rear bumper	Rear bumper (unpainted) - Scratch(es) - No deduction
4	Door - front left side	Door - dent(s) - No deduction
5	Sliding door, right	Sliding door - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Damage 2: Seat - front: Seat cover - left side - Soiled - Clean



Damage 2: Seat - front: Seat cover - left side - Soiled - Clean



Damage 3: Seat - front: Seat cover - right side - Soiled - Clean



Damage 3: Seat - front: Seat cover - right side - Soiled - Clean



Damage 4: Engine: Engine cover - Damage caused by marten / rodent - Replace



Damage 4: Engine: Engine cover - Damage caused by marten / rodent - Replace



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 6: Wing mirror - right side: Cap - Broken / torn - Replace




Damage 6: Wing mirror - right side: Cap - Broken / torn - Replace



Damage 6: Wing mirror - right side: Cap - Broken / torn - Replace



Damage 7: Vehicle glazing: Windscreen (kein Staubschutz) - Stone chips - Replace



Damage 7: Vehicle glazing: Windscreen (kein Staubschutz) - Stone chips - Replace



Damage 7: Vehicle glazing: Windscreen (kein Staubschutz) - Stone chips - Replace