TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48205797
Order No. / Reference: 27153456
Inspection date: 12 Oct 2026

Manufacturer: CUPRA	Model: Born 170kW/58kWh
VIN: VSSZZZK18RP016991	





Vehicle details

Manufacturer / Type / Model / Equipment	
CUPRA Born 170kW/58kWh	
Vehicle Identification number	VSSZZZK18RP016991
Mileage (Read)	40,962 km
First registration	12 Mar 2024
Number of holders	1
Next periodical technical inspection	03/2027
(Report not on hand)	
Fuel type	Electric
Power	70 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Car hatchback
Colour / colour code	Quasar Grey Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	-220 Tag(e)
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY924874
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	7593 / ASM 00025		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,290 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R19 93T	All-season tyres on Light alloy	Continental	1mm / 1mm
2)	215/50 R19 93T	All-season tyres on Light alloy	Continental	2mm / 2mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Airbag for driver and front passenger (center airbag - side airbags for driver and front passenger)
- Ambient lighting in the front door trim (including footwell lighting)
- Electrically adjustable, folding and heated exterior mirrors (including passenger-side mirror lowering function)
- C-pillar with CUPRA design element
- CUPRA Drive Profile (driving profiles can be individually selected - Range, Comfort, Performance, Individual, CUPRA)
- CUPRA side skirts in Liquid Grey
- Decorative elements (decorative element on instrument panel Black, decorative stitching in Copper - decorative inlay in front doors, Dinamica Granite Grey, made from recycled materials - decorative elements in Copper)
- Luggage compartment lighting
- Speed limiter
- rear window wiper
- Rear bumper and diffuser in body color (with Liquid Grey accents)
- Interior mirror automatically dimming
- ISOFIX child seat restraint system, in the 2nd row left and right as well as on the front passenger seat (i-Size compatible - incl. top tether anchor points at the rear)
- Headrests, 2 front
- Headrests, 3 rear
- Steering wheel: CUPRA Supersport multifunction steering wheel in leather with CUPRA Mode Selector (heated - CUPRA e-Boost Activator and paddles for recuperation setting)
- Front center armrest (in Dinamica Granite Grey, front, made from recycled materials)
- Center console with integrated storage compartment and cup holder (including roller shutter, in black)
- Emergency call service (no registration required - service is activated upon delivery)
- Rain sensor
- Tire pressure monitoring system
- Seat belts - front and rear (warning buzzer and warning light for unfastened seat belts)
- Seats: 3 rear seats, rear seat backrest asymmetrically split and foldable
- Seats: CUPRA front sport bucket seats (made of SEAQUAL Yarn fabric, Black)
- Sun visors with illuminated makeup mirror
- Lane departure warning system
- Front bumper in body color (with air intakes in Liquid Grey and trim in Copper)
- Electronic immobilizer
- thermal insulation glazing
- Airbag: Passenger airbag deactivation
- Airbag: Head airbag system, front and rear
- Exterior mirrors: aspherical on driver's side, convex on passenger's side
- Exterior mirror housing in Liquid Grey
- third brake light
- CCS charging socket
- CUPRA e-Sound (AVAS Acoustic Vehicle Alert System, acoustic vehicle warning system) from 0-50 km/h
- CUPRA lettering on tailgate
- Black headliner
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC) (Anti-lock Braking System (ABS) - Traction Control System (ASR))
- Electric window regulator with anti-pinch protection and one-touch function
- Transmission: 1-speed automatic
- Rear spoiler in car color
- Manufacturer's warranty: 5 years or up to 150,000 km
- High-voltage battery warranty 8 years or maximum 160,000 km, with 70% Abattery power
- Keyless Go (engine start/stop button)
- Air conditioning: Climatronic with electronic temperature control (separate for driver and front passenger, with stationary air conditioning)
- Mode 3 Type 2 charging cable, 16 A
- Lights: Full headlights (full LED headlights with light sensor and automatic headlight control, cornering light function and bad weather light - full LED taillights with Infinite Light; dynamic LED light strip at the rear - turn signals with LED technology integrated into exterior mirrors including welcome light projection under the exterior mirrors - Ceremony Light)
- Fatigue detection
- Progressive steering
- Radio: Radio, navigation and multimedia systems (2 USB-C charging ports for the 2nd row of seats - 7 speakers - Virtual Cockpit-5, 3" fully digital instrument cluster - antenna for FM reception - Bluetooth interface with integrated hands-free system and audio streaming - Android Auto, Apple CarPlay incl. Full Link Wireless - 2 USB-C ports in the front - DAB+ - infotainment system with 12" color touchscreen - voice control - CUPRA CONNECT)
- Seats: Driver's seat with height adjustment
- Sport pedals in aluminum look
- 12V socket in the luggage compartment
- Ultrasonic parking aid front and rear
- Front Assist area monitoring system with City Emergency Braking function

Extra equipment

- Privacy Glass: Side windows from the 2nd row of seats and rear window are dark tinted.
- Radio accessories: Beats Audio sound system (9 speakers, digital multi-channel amplifier, subwoofer, 395 watts total power)
- Wheels: All-season tires TYPHOON 7.5J x 19" Black/Copper, diamond-cut (tires 215/50 R 19 with self-sealing function)
- Package: Pilot M Pack (Adaptive Cruise Control ACC with predictive speed control - CUPRA CONNECT PLUS - prepared for activation of the Online Infotainment service package - High Beam Assistant - Traffic Sign Recognition - Navigation system with 12" color touchscreen - Rearview camera)
- Paint finish: Metallic

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Vehicle glazing	Windscreen seal - Scratch(es) - Replace
2	Door - front left side	Door - Scratch(es) - Smart repair
3	Rear bumper	Rear bumper - Scratch(es) - Smart repair
4	Misc.	Inspection / maintenance - Due - Perform
5	Wheel / tyres	Tyres - complete set - Worn - Replace

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	Mudguard - right side	Mudguard - right side - Scratch(es) - No deduction
4	Mudguard - left side	Mudguard - left side - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Instrument panel



Figure 10: Interior 360° view



Figure 11: Cargo area



Figure 12: Cargo area



Figure 13: VIN



Figure 14: Mounted tyres




Figure 15: Documents



Figure 16: Documents




Figure 17: Documents



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Damage 1: Vehicle glazing: Windscreen seal - Scratch(es) - Replace



Damage 1: Vehicle glazing: Windscreen seal - Scratch(es) - Replace



Damage 2: Door - front left side: Door - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door - Scratch(es) - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 4: Misc.: Inspection / maintenance - Due - Perform



Damage 5: Wheel / tyres: Tyres - complete set - Worn - Replace



Damage 5: Wheel / tyres: Tyres - complete set - Worn - Replace



Damage 5: Wheel / tyres: Tyres - complete set - Worn - Replace



Damage 5: Wheel / tyres: Tyres - complete set - Worn - Replace