TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 47743295
Order No. / Reference: 27003442
Inspection date: 24 Sept 2026

Manufacturer: IVECO	Model: Daily 35 S 14NA8 V Kasten
VIN: ZCFCR35AX05542563	





Vehicle details

Manufacturer / Type / Model / Equipment	
IVECO Daily 35 S 14NA8 V Kasten	
Vehicle Identification number	ZCFCR35AX05542563
Mileage (Read)	6,274 km
First registration	17 Aug 2023
Number of holders	1
Next periodical technical inspection (Report on hand)	07/2027
Fuel type	Natural gas
Engine displacement / Cylinder	2,998 ccm / 4
Power	100 kW
Gearbox / Number of gears	Automatic / 6
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	WHITE IC 194
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Not roadworthy / moveable

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY110793
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	4192 / 000 000		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R16 112T	Summer tyres on Steel rim with wheel cover	Bridgestone	8mm / 8mm
2)	225/65 R16 112T	Summer tyres on Steel rim with wheel cover	Bridgestone	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R16 112R	Winter tyres on Steel	Bridgestone	10mm / 10mm
2)	225/65 R16 112R	Winter tyres on Steel	Bridgestone	10mm / 10mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- TIRES 225/65R16 ECO

Extra equipment

- STORAGE PACKAGE
- Alarm system with central locking and remote control
- EVOLUTION EQUIPMENT PACKAGE
- CNG TANK CENTRAL ENLARGED
- Front parking sensors retrofitted
- Heated windows in rear doors
- ADDITIONAL SPEED LIMITER, PROGRAMMABLE
- REAR DOORS OPEN 260°
- AUTOMATIC AIR CONDITIONING
- COMFORT HEADRESTS
- Charging light above rear door
- LEATHER STEERING WHEEL
- LIGHT AND RAIN SENSOR
- LUXURY DRIVER'S SEAT. SUSPENDED; HEATED AND ADJUSTABLE.
- WITHOUT REDUCING ENGINE POWER
- Dynamic reversing camera. Lines
- Heated front seats
- VOICE ASSISTANT ALEXA
- TRACTION PLUS WITH HILL DESCENT ASSIST
- FULL LED HEADLIGHTS
- WINTER NP
- AIRBAG AND WINDOWBAG FOR DRIVER AND PASSENGER
- PASSENGER SEAT WITH MULTIFUNCTIONAL STORAGE
- ROOF STORAGE ABOVE WINDSHIELD
- REAR PARKING SENSORS
- FtADIO HI-CONNECT WITH NAVI.
- GRIP ON A-PILLAR
- REAR AXLE TRANSITION I = 3.62
- AIR CONDITIONING COMPRESSOR 170 CC
- Radiator grill with chrome inserts
- LED cargo area lights
- STEERING COLUMN ADJUSTABLE IN HEIGHT AND TILT
- REAR AXLE AIR SUSPENSION
- FOG LIGHTS
- WITHOUT CNG TANK IN OVERHANG
- WITHOUT SERVICE INDICATOR
- Security locks for sliding and rear doors
- MIRROR FOR MOUNTING WIDTH 2,200 MM CATEGORY IV
- Cruise control
- PARTITION WALL WITH WINDOW
- Heated windscreen
- Central storage compartment with charging tray and USB port

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Bonnet	Bonnet - dent(s) - Smart repair
2	Rear axle	Rear axle (Luftfahrwerk) - on - Perform diagnosis
3	Wheel / tyres	Tyre - rear left side - Defective - Replace
4	Interior	Interior (Laderaum) - Holes - Loss in value
5	Body	Body - Glued / labelled - De-glue / neutralise

Wear and tear

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Documents - Service book

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Damage 1: Bonnet: Bonnet - dent(s) - Smart repair



Damage 1: Bonnet: Bonnet - dent(s) - Smart repair



Damage 2: Rear axle: Rear axle (Luftfahrwerk) - on - Perform diagnosis



Damage 3: Wheel / tyres: Tyre - rear left side - Defective - Replace




Damage 3: Wheel / tyres: Tyre - rear left side - Defective - Replace



Damage 4: Interior: Interior (Laderaum) - Holes - Loss in value



Damage 4: Interior: Interior (Laderaum) - Holes - Loss in value



Damage 4: Interior: Interior (Laderaum) - Holes - Loss in value



Damage 4: Interior: Interior (Laderaum) - Holes - Loss in value



Damage 4: Interior: Interior (Laderaum) - Holes - Loss in value



Damage 4: Interior: Interior (Laderaum) - Holes - Loss in value



Damage 4: Interior: Interior (Laderaum) - Holes - Loss in value



Damage 4: Interior: Interior (Laderaum) - Holes - Loss in value



Damage 4: Interior: Interior (Laderaum) - Holes - Loss in value



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise