TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Besichtigungsort
TÜV SÜD Auto Partner: MVI Oberschleißheim
Mittenheimer Str. 64
85764 Oberschleißheim

Besichtigungsdatum: 23.10.2026
Protokollnummer: 48437115
Erstellt durch: Paula Busch
Besichtigt durch: Furkan Kara

VSSZZZKL1RR090646

Angaben zum Fahrzeug

Halter		**Besichtigungszustand**	ausreichend
Kennzeichen		**Laufleistung (abgelesen)**	21.219 km
Hersteller	CUPRA	**Restlauf bis Service**	5 Tag(e)
Typ/Modell	LEON SP	**HU (abgelesen aus ZBI)**	10/2027
Fahrgestellnummer	VSSZZZKL1RR090646	**Leistung**	180 kW
Hubraum	1.984 ccm	**Zylinder**	4
Erstzulassung	18.10.2024	**Polster/Farbe**	Stoff/Leder Kombination / Schwarz
Letzte Wartung		**Lackierung**	Grau
Kraftstoffart	Benzin	**Getriebe**	Automatik

Zustandsbericht

Wertmindernde Faktoren

Nr.	Bauteilgruppe	Beschreibung
1	Lenkanlage	Lenkrad - verkratzt / verschürft - Smart Repair

Gebrauchsspuren

Nr.	Bauteilgruppe	Beschreibung
Das Fahrzeug weist dem Alter und Einsatzzweck entsprechende Gebrauchsspuren auf.		

Fehlteile

Fehlteil

Festgestellte Nachlackierungen

Nr.	Ort
Keine feststellbar	

Hauptbereifung

Achse	Reifengröße	Hersteller	Reifentyp	Profiltiefe	Verktgl.	Zul.
1	235/35 R19 91Y	Hankook	Sommerreifen	6mm - 6mm	i.O.	i.O.
2	235/35 R19 91Y	Hankook	Sommerreifen	6mm - 6mm	i.O.	i.O.

Ersatz

Typ	Reifengröße	Hersteller	Reifentyp	Profiltiefe	Ablaufdatum
Notrad	125/70 R18 99M		Sommerreifen	5	

Der Verschleißzustand sowie evtl. Schäden an der Bereifung sind wertmäßig berücksichtigt.

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Besichtigungsort
TÜV SÜD Auto Partner: MVI Oberschleißheim
Mittenheimer Str. 64
85764 Oberschleißheim

Besichtigungsdatum:	23.10.2026
Protokollnummer:	**48437115**
Erstellt durch:	Paula Busch
Besichtigt durch:	Furkan Kara

Angaben zum Fahrzeug

Hersteller	CUPRA	**Besichtigungszustand**	ausreichend
Typ/Modell	LEON SP	**Laufleistung (abgelesen)**	21.219 km
Fahrgestellnummer	VSSZZZKL1RR090646	**Erstzulassung**	18.10.2024

Angaben zum Auftrag:
Auftragsgemäß erfolgte die Fahrzeugzustandsbewertung in demontagefreien Zustand.

Grundlage dieses Produktes stellt der Leitfaden für Fahrzeugrücknahmen und Bewertungen gemäß des Schadengrenzmusterkatalog des Auftraggebers dar. Die expliziten Feststellungen im Einzelfall trifft der Sachverständige objektiv im Rahmen der vorgegebenen Standards aufgrund eigener Sachkunde.

Fahrzeug-Identifizierung:
Die Fahrzeug-Identifizierungsnummer (FIN) wurde am Fahrzeug abgelesen und die Übereinstimmung im Verlauf der Besichtigung durch den Unterzeichner mit den vorgelegten Unterlagen festgestellt.

Besichtigungsbedingungen:
Die Besichtigungsbedingungen waren zur Beurteilung des Fahrzeuges ausreichend.

Allgemeinzustand:
Das Fahrzeug weist dem Alter und Einsatzzweck entsprechende Gebrauchsspuren auf.

Unterschrift Sachverständiger (Paula Busch)

Vorliegendes Druckexemplar wurde auf elektronischem Wege erzeugt. Der benannte Sachverständige versichert, dass der Inhalt die von ihm getroffenen Feststellungen korrekt wiedergibt. Es ist ohne Originalunterschrift gültig.

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Besichtigungsort
TÜV SÜD Auto Partner: MVI Oberschleißheim
Mittenheimer Str. 64
85764 Oberschleißheim

Besichtigungsdatum:	23.10.2026
Protokollnummer:	**48437115**
Erstellt durch:	Paula Busch
Besichtigt durch:	Furkan Kara

Übersichtsfotos



Abbildung 1: FIN



Abbildung 2: Schräg vorne



Abbildung 3: Schräg vorne



Abbildung 4: Schräg hinten



Abbildung 5: Schräg hinten



Abbildung 6: Montierte Bereifung



Abbildung 7: Montierte Bereifung



Abbildung 8: Montierte Bereifung



Abbildung 9: Montierte Bereifung



Abbildung 10: Innenraum vorne



Abbildung 11: Laderaum



Abbildung 12: Laderaum

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Besichtigungsort
TÜV SÜD Auto Partner: MVI Oberschleißheim
Mittenheimer Str. 64
85764 Oberschleißheim

Besichtigungsdatum:	23.10.2026
Protokollnummer:	**48437115**
Erstellt durch:	Paula Busch
Besichtigt durch:	Furkan Kara



Abbildung 13: Kombiinstrument



Abbildung 14: Kombiinstrument



Abbildung 15: Instrumententafel



Abbildung 16: Dokumente




Abbildung 17: Dokumente



Abbildung 18: Sonstiges

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Besichtigungsort
TÜV SÜD Auto Partner: MVI Oberschleißheim
Mittenheimer Str. 64
85764 Oberschleißheim

Besichtigungsdatum:	23.10.2026
Protokollnummer:	**48437115**
Erstellt durch:	Paula Busch
Besichtigt durch:	Furkan Kara


Beschädigungsfotos




Beschädigung #1: Lenkanlage: Lenkrad - verkratzt / verschürft - Smart Repair



Beschädigung #1: Lenkanlage: Lenkrad - verkratzt / verschü… - Smart Repair



Beschädigung #1: Lenkanlage: Lenkrad - verkratzt / verschürft - Smart Repair



Beschädigung #1: Lenkanlage: Lenkrad - verkratzt / verschü… - Smart Repair

Certificate of Conformity

046CC0176519

www.PS-Team.de

Complete vehicles

The undersigned hereby certify that the vehicle:

0.1.	Make (Trade name of manufacturer):		CUPRA
0.2.	Type:	Variant:	Version:
	KL	CFDNPAX0	FD7CFD7GC0034BIML1CBD17
0.2.1.	Commercial name:		CUPRA LEON SP
0.2.2.1.	Allowed Parameter Values for multistage type approval to use the base vehicle emission values		
	Final Vehicle actual mass [kg]:		----- - -----
	Final Vehicle technically permissible maximum laden mass[kg]:		----- - -----
	Frontal area for final vehicle [cm2]:		----- - -----
	Rolling resistance [kg/t]:		----- - -----
	Cross-sectional area of air entrance of the front grille [cm2]:		----- - -----
0.2.3.1.	Interpolation family's identifier:		IP-MQB37WZ_B1_0390-VSS-1
0.2.3.2.	ATCT family's identifier:		AT-5Q0_0V_0413_000-VSS-1
0.2.3.3.	PEMS family's identifier:		09-VSS-715W_KL_DNPA_FD7_B-000
0.2.3.4.	Roadload family's identifier:		RL-DQ381_7F_19_001-WWW-1
0.2.3.5.	Roadload matrix family's identifier (if applicable):		-----
0.2.3.6.	Periodic regeneration family's identifier:		PR-AU_00108_00_000-WWW-1
0.2.3.7.	Evaporative test family's identifier:		EV-CD_APW_D_AVAAXX-WWW-1
0.4.	Vehicle category:		M1
0.5.	Company name and address of manufacturer:		SEAT, S.A., Autovia A-2, Km. 585, ES-08760 Martorell
0.6.	Location and method of attachment of the statutory plates: On the right A-pillar,glued or bonded		
	Location of the vehicle identification number: In the engine compartment,right		
0.9.	Name and address of the manufacturer's representative:		-----
0.10.	Vehicle identification number:		VSSZZZKL1RR090646
0.11.	Date of manufacture of the vehicle:		2024-03-23

conforms in all respects to the type described in approval e9*2007/46*3167*27 granted on 2023-10-17 and can be permanently registered in Member States having right hand traffic and using metric units for the speedometer and metric units for the odometer.

Martorell, 2024-03-23

Daniel Cortina Munuera
Director Quality Assurance

Martorell, 2024-03-23

Robin Christoph Bräutigam
Head of Technical Conformity

Internal Manufacturer's data VSSZZZKL1RR090646

CoC Version: 1

49. CO_2 emissions/fuel consumption/electric energy consumption:

1. All powertrains, except OVC hybrid electric vehicles (if applicable):

WLTP values	CO_2 emissions			Fuel consumption (/100 km)			Electric Consumption
	Petrol/ Diesel: (g/km)	Gas: CNG/LPG (g/km)	Other: (g/km)	Petrol/ Diesel: (L)	Gas: CNG/LPG (L)/(m^3)	Others: (L)	(Wh/km)
Low:	252	---	---	11.1	---	---	-------
Medium:	167	---	---	7.4	---	---	-------
High:	138	---	---	6.1	---	---	-------
Extra High:	155	---	---	6.8	---	---	-------
Combined:	165	---	---	7.3	---	---	-------

2. Electric range of pure electric vehicles (if applicable):

Electric range [km]: ----- Electric range city [km]: -----

3. Vehicle fitted with eco-innovation(s): yes

3.1. General code of the eco-innovation(s): e9 29 37

3.2. Total CO_2 emissions savings due to the eco-innovation(s):

3.2.2. WLTP savings (if applicable) [g/km]: Petrol/Diesel: 1.91 Gas (CNG/LPG): ---- Others: ----

4. OVC hybrid electric vehicles (if applicable):

WLTP values (CO2 and fuel consumption sustaining, if not otherwise mentioned)	CO_2 emissions			Fuel consumption: (/100 km)			Electric Consumption (Wh/km)
	Petrol/ Diesel: (g/km)	Gas: CNG/LPG (g/km)	Others: (g/km)	Petrol/ Diesel: (L)	Gas: CNG / LPG (m^3)/(L)	Other: (L)	
Low	---	---	---	---	---	---	-------
Medium	---	---	---	---	---	---	-------
High	---	---	---	---	---	---	-------
Extra High	---	---	---	---	---	---	-------
City	---	---	---	---	---	---	-------
Combined (sustaining)	---	---	---	---	---	---	-------
Combined (depleting)	---	---	---	---	---	---	-------
Weighted, combined	---	---	---	---	---	---	-------

5. Electric range of OVC hybrid electric vehicles (if applicable):

Equivalent All Electric Range [km]: (EAER): ----- (EAER city): -----

All Electric Range [km]: (AER): ----- (AER city): -----

51. For special purpose vehicles: Designation in accordance with CR (CE) 2018/858 annex I part A point 5: ---------

52. Remarks:

NO 16.2.: with trailer axle 2:+10 kg##NO 35.: alt. to pos 35 with deviating val.
in pos 49: 225/40 R18 92Y XL#7,5JX18 ET46;##235/35 R19 91Y XL#8,0JX19 ET49;##22
5/35 R19 88H XL M+S#8,0JX19 ET49;##

54. Vehicle fitted with advanced vehicle systems: eCall, ESS, TPMS

55. Vehicle certified in accordance with UN-R No 155: no

56. Vehicle certified in accordance with UN-R No 156: no

Für dieses Dokument wurde eine Zulassungsbescheinigung Teil II (HB653810) ausgegeben. Landratsamt München

1.	Number of axles / wheels:	2 / 4
3.	Powered axles (number, position):	1, Axle 1
	Interconnection of powered axles:	----------
3.1.	Specify if the vehicle is non-automated/automated/fully automated:	non-automated
4.	Wheelbase[mm]:	2679
4.1.	Axle spacing [mm]:	2679
5.	Length [mm]:	4657
6.	Width [mm]:	1799
7.	Height [mm]:	1437
13.	Mass in running order [kg]:	1540
13.2.	Actual mass of the vehicle [kg]:	1601
16.	Technically permissible maximum masses:	
16.1.	Technically permissible maximum laden mass [kg]:	2080
16.2.	Technically permissible mass on each axle (1./2.) [kg]:	1080 / 1050
16.4.	Technically permissible maximum mass of the combination [kg]:	3680
18.	Technically permissible maximum towable mass in case of:	
18.1.	Drawbar trailer [kg]:	----
18.3.	Centre-axle trailer [kg]:	1600
18.4.	Unbraked trailer [kg]:	750
19.	Technically permissible maximum static vertical mass at the coupling point [kg]:	80
20.	Manufacturer of the engine:	Audi AG
21.	Engine code as marked on the engine:	DNP
22.	Working principle:	Positive ignition / 4 stroke
23.	Pure electric:	no
23.1.	Class of Hybrid (electric) vehicle:	----------
24.	Number and arrangement of cylinders:	4; in Line
25.	Engine capacity [cm³]:	1984
26.	Fuel:	petrol
26.1.	Mono fuel/Bi fuel/Flex fuel/Dual fuel:	mono fuel vehicle
26.2.	Type of dual fuel engine:	--------
27.	Maximum power	
27.1.	Maximum net power [kW at min^{-1}] (internal combustion engine):	180.00 / 5000
27.3.	Maximum net power [kW] (electric motor):	------
27.4.	Maximum 30 minutes power [kW] (electric motor):	------

28.	Gearbox (type):	automatic
	Gear	---- ---- ---- ---- ---- ---- ---- ---- ----
28.1.	Gearbox ratios:	------- ------- ------- ------- ------- ------- ------- ------- -------
28.1.2.	Final drive ratio:	------- ------- ------- ------- ------- ------- ------- ------- -------
29.	Maximum speed [km/h]:	250
30.	Axle(s) track (1./2.) [mm]:	1554 / 1520
35.	Fitted tyre/wheel combination/energyefficiency class of RRC/type category used for CO_2 determination:	
	Axle 1:	235/35 R19 91Y XL / 8,0JX19 ET49 / C / C1
	Axle 2:	235/35 R19 91Y XL / 8,0JX19 ET49 / C / C1
36.	Trailer brake connections:	----------
38.	Code for bodywork:	AC
40.	Colour of vehicle:	GREY
41.	Number and configuration of doors:	5 / le. 2, ri. 2, ba. 1
42.	Number of seating positions (including the driver):	5
42.1.	Seat(s) designated for use only when the vehicle is stationary:	---
42.3.	Number of wheelchair user accessible position:	---
46.	Sound level	
	Stationary [dB(A) at min^{-1}]:	78.00 / 3750
	Drive-by [dB(A)]:	68.00
47.	Exhaust emission level:	EURO 6 AP
47.1	Parameters for emission testing of V_{ind}:	
47.1.1.	Test mass [kg]:	1682
47.1.2.	Frontal area [m^2]:	----------

47.1.3. Road load coefficients	47.1.3.0. f0 [N]	47.1.3.1. f1 [N/(km/h)]	47.1.3.2. f2: [N/(km/h)²]
	144.1	0.252	0.03326

47.2.	Driving cycle:	
47.2.1.	Driving cycle class:	3b
47.2.2.	Downscaling factor (f_{dsc}):	-----
47.2.3.	Capped speed:	no
48.	Exhaust emissions:	715/2007*2018/1832AP

1.2. Test procedure: Type 1 (WLTP highest values) [mg/km] or WHSC (EURO VI) [mg/kWh]

Petrol / Diesel	CO	THC	NMHC	NO_x	THC + NO_x	NH_3 [ppm]	Particulates	Particles #
	211.8	23.4	20.9	19.8	--------	--------	0.1200	0.05E11
LPG/CNG	--------	--------	--------	--------	--------	--------	--------	--
Other	--------	--------	--------	--------	--------	--------	--------	--

2.2. Test procedure: WHTC (EURO VI) [mg/kWh]

Petrol / Diesel	CO	THC	NMHC	CH_4	NO_x	NH_3	Particulates	Particles #
	--------	--------	--------	--------	--------	--------	--------	--
LPG/CNG	--------	--------	--------	--------	--------	--------	--------	--
Other	--------	--------	--------	--------	--------	--------	--------	--

48.1.	Smoke corrected absorption coefficient [m^{-1}]:	--------
48.2.	Declared maximum RDE values (if applicable):	NO_x [mg/km] / Particles (number) with exponent (#/km)
	Complete RDE trip:	60.0 / 6.00 E11
	Urban RDE trip:	60.0 / 6.00 E11

MOBILITY CONCEPT

LVV Nr	6159396
Hersteller	Cupra
Model	León
Variante	DE - Kb5 2.0 TSI EU6d, VZ OPF, 2023 - 2024 2.0 TSI
Listenpreis	38.487,39
VIN	VSSZZZKL1RR090646
Erstzulassungsdatum	18.10.2024
Kennzeichen	M-Q 3512

Schadensfälle der int. Belegnummer: 6159396 11.11.2026

Schadennummer	Unfalldatum	Beschädigung	Schadenhöhe in EUR
2026107959	01.04.2026	| Stoßfänger vorne	3.367,07

Mobility Concept GmbH
Grünwalder Weg 34
D-82041 Oberhaching
Telefon +49 89 63266-0
Telefax +49 89 63266-266

E-Mail:leasing@mobility-concept.de
Internet: www.mobility-concept.de
Geschäftsführer:
Rudolf Rizzolli, CEO (Vorsitzender)
Marc-Oliver Bucksch, CFO

Sitz der Gesellschaft: Oberhaching
Amtsgericht München HR B 130788
Bankverbindung: UniCredit Bank AG
IBAN: DE29 7002 0270 0002 4960 11
Swift (BIC): HYVEDEMMXXX

Steuer-Nr.: 143/163/41358
USt-IdNr.: DE 813336066
Aufsichtsbehörde: Bundesanstalt für
Finanzdienstleistungsaufsicht
Graurheindorfer Str. 108, 53117 Bonn