TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number:	46196171
Order No. / Reference:	26511425
Inspection date:	29 Jun 2026

Manufacturer: Ford	Model: S-Max 2.5 Duratec FHEV TITANIUM
VIN: WF0JXXWPCHPC17714	

Vehicle details

Manufacturer / Type / Model / Equipment	
Ford S-Max 2.5 Duratec FHEV TITANIUM	
Vehicle Identification number	WF0JXXWPCHPC17714
Mileage (Read)	46,602 km
First registration	2 May 2023
Number of holders	1
Next periodical technical inspection	05/2028
(Report on hand)	
Power / Engine displacement	110 kw / 2,488 ccm
Fuel type / Cylinder	Hybrid Petrol / E / 4
Gearbox / Number of gears	Automatic / 1
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	28 %
Last service on / at	11/2025 at 37,133 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP510926
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BVI 00082		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	**fine dust sticker**	
Permitted total weight	2,350 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103V	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	235/55 R17 103V	Summer tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103V	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	235/55 R17 103V	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Ambient lighting in the front (including door storage, front door handle and footwell lighting)
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated (with integrated turn signals and ambient lighting and electrically foldable)
- Attachment points for safety partition grilles (attachment points 2nd row of seats)
- Hill start assist
- Overhead console with glasses storage compartment and child observation mirror
- Lane Assist including Lane Keeping Assist and Driver Alert (warns the driver of an unintentional lane change via short steering wheel vibrations (without activation of the turn signal) - additionally, active steering support assists in returning to the lane)
- Ford EasyFold: 2nd row seat backrests fold down electrically at the touch of a button.
- Ford Power Start function with Ford Key Free system (keyless starting and locking/unlocking)
- FordPass Connect including eCall and Wi-Fi hotspot (information about the current status or location of the vehicle as well as control of selected vehicle functions via smartphone with the FordPass app - eCall emergency call system to send an emergency call in the event of an accident or when manually activated - Wi-Fi hotspot (up to 4G/LTE7, for up to 10 mobile devices))
- Interior mirror, automatically dimming
- Isofix mounting (on all seats in the 2nd row)
- Electric child safety lock
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Rear headrests (3)
- Front headrests, 4-way height and tilt adjustable
- Steering wheel: Steering column, adjustable in height and reach
- Front center console with padded armrest (storage compartment and 2 cup holders)
- Ford navigation system including Ford SYNC 3 (AppLink (Android Auto and Apple CarPlay) - Touchscreen - Digital radio reception DAB/DAB+ (Digital Audio Broadcasting) - Acoustic and visual route guidance, dynamic navigation, lane guidance, road map for Europe - FordPass Connect additionally with live traffic information - Enhanced voice control - Enhanced voice output - Michelin travel guide for Europe - Quick destination search of addresses and points of interest in one input field (One Box Search))
- Front and rear parking pilot system
- Upholstery: Cloth
- Tire repair kit (for use at a maximum speed of 80 km/h)
- Tire Pressure Monitoring System (TMPS)
- LED taillights
- Windscreen wipers with rain sensor
- Anti-lock braking system (ABS) (with Electronic Stability Program (ESP), Roll Stability Control (RSC) and Traction Control System (TCS))
- Attachment points for safety partition grilles (attachment points 1st row of seats)
- Tires: 7.5 J x 17 alloy wheels (4) with 235/55 R 17 tires (in 5x2-spoke design)
- third brake light
- Roof rails "aluminum look"
- Tachometer
- Electric front and rear windows (with anti-pinch protection and automatic opening and closing function)
- High Beam Assist
- Electronic parking brake
- Ford Easy Fuel (The Ford Easy Fuel convenience refueling system eliminates the need for a separate internal fuel filler cap and prevents misfueling by detecting the size difference between petrol and diesel nozzles. The filler neck only opens when the correct fuel is used.)
- Luggage compartment cover (removable)
- Luggage compartment lighting
- Cruise control system with intelligent speed limiter
- Transmission: CVT automatic
- Back window, heater
- rear window wiper
- Interior lighting with delay circuit
- Intelligent Protection System (IPS) (front airbag for driver and front passenger - knee airbag for driver - head and shoulder airbags in the front and for the 2nd row of seats - side airbags for driver and front passenger - side airbags on the outer seats of the 2nd row of seats - seat belt tensioners and belt force limiters in the front - 3-point seat belts in all seats, height-adjustable in the front)
- Paint finish: Solid
- Steering wheel: Multifunction leather steering wheel
- Front and rear reading lights (with LED technology)
- MyKey key system (individually programmable second key) (setting options include: - Limiting the maximum speed and radio volume (to max. volume 15 out of 32) - Speed warning (when the set speed limit is exceeded) - Safety assistance systems cannot be deactivated - Extended warning system for unfastened seat belts)
- Fog lights with LED technology
- Emergency brake light (pulsating illumination of the brake lights during hard braking)
- Package: Winter (Heated windscreen - Heated leather steering wheel - Individually and variably heated front seats)
- Radio: Ford SYNC 3 (AppLink (Android Auto and Apple CarPlay) - 8" touchscreen (20.3 cm screen diagonal) - Digital radio reception DAB/DAB+ (Digital Audio Broadcasting) - 8 speakers - Steering wheel controls - Bluetooth hands-free system and audio streaming - 2 USB ports - Voice control for audio and phone - SMS text-to-speech function)

- Headlight dipped beam with switch-off delay including "greeting function"
- Headlight assistant with day/night sensor
- Electro-mechanical power steering (EPAS - Electric Power Assisted Steering)
- Seats: Driver and front passenger seats, 4-way manually adjustable (with manually adjustable lumbar support)
- 230 volt socket
- Trays on the front seatbacks
- LED daytime running lights
- Traffic sign recognition system
- Lashing eyes in the luggage compartment
- Immobiliser
- Central locking with remote control (remote luggage compartment release - second folding vehicle key)
- Side skirts and bumpers painted in body color
- Seats: 2nd row of seats with 3 individual seats (FoldFlat System)
- Seats: Front sports seats (with enhanced lateral support)
- Seats: Front seats can be heated individually and variably.
- Power outlet: 12-volt connection in the luggage compartment and in the center console
- Premium carpet floor mats front and rear (as well as in the 3rd row of seats if ordered as an optional extra)
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats (as well as the 3rd row of seats if ordered as an optional extra)
- Cigarette lighter (and ashtray in the center console)

Extra equipment

- Package: Business Package III (Sony navigation system incl. Ford SYNC 3 - Adaptive LED headlights with glare-free high beam - Adaptive cruise control with traffic jam assist and stop & go function - Pre-Collision Assist (distance display and distance warning, collision warning system and active emergency braking assist) - Front camera with "Split View" technology incl. reversing camera - Blind Spot Assist incl. Cross Traffic Alert - Electric, sensor-controlled tailgate and Ford Key Free System - Park Assist with automatic parking function)
- Detachable towbar (including ESP trailer stabilization)
- Paint finish: Frozen White
- Safety partition net behind the 2nd row of seats
- Side windows from the 2nd row of seats and rear window, dark tinted.

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - Smart repair

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.

Figure 1: Diagonal front (left)

Figure 2: Diagonal front (right)

Figure 3: Diagonal rear (left)

Figure 4: Diagonal rear (right)

Figure 5: Interior - front



Figure 6: Interior - rear

Figure 7: Instrument cluster

Figure 8: Instrument panel

Figure 9: Interior 360° view

Figure 10: Cargo area

Figure 11: VIN

Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents

Figure 15: Documents

Figure 16: Documents

Figure 17: Additional tyres

Figure 18: Navigation

Figure 19: Misc.

Figure 20: Misc.

Figure 21: Misc.

Figure 22: Misc.

Figure 23: Misc.

Figure 24: Misc.



Figure 25: Misc.

Figure 26: Misc.



Figure 27: Misc.

Figure 28: Misc.

Figure 29: Misc.

Figure 30: Misc.

Figure 31: Misc.

Figure 32: Misc.

Figure 33: Misc.

Figure 34: Misc.

Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair

Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair

Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair

Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair

Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer:	WF0JXXWPCHPC17714
Hersteller / Modell:	FORD FORD S-Max 2.5 Duratec FHEV TITANIUM

Datum	KM-Stand	Beschreibung
04.11.2025	37.133	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst
11.04.2024	18.196	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges