
APPRAISAL REPORT



VEHICLE IDENTIFICATION

Driver name:	HM Tongeren
Make:	VOLKSWAGEN
Model / version:	GOLF VIII
Wine:	WVWZZZCDXRW305161
Plate:	2FHS258
Mileage:	50476
SOH:	
First registration:	15/05/2024
Color:	DEEP BLACK P




ADDITIONAL INFORMATION



Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book	
Number of keys:	2
Original key:	✓


PICTURES
















































WINE INFORMATION

Radio	Radio with navigation system	7 speakers
Bluetooth	Sequential transmission	6 reports
Differential lock	Automatic headlights	LED spotlights
Style Equipment	Chrome window surround	Material: alloy
Reference letter (J)	Front diameter 16	Rear diameter 16
Front width 7.0	Rear width 7.0	Front diameter 16
Rear diameter 16	Front height 55	Rear height 55
Forward speed index V	Rear speed index V	Front width 205
Rear width 205	Rear air conditioning	3-zone automatic climate control
Front center armrest	Rear center armrest	Chrome interior finish
Petrol hybrid	1395 cm3	1.40 liters
150 kW	204 hp	Euro 6

Pearlescent varnished effect	Standard maintenance	Front disc brakes
Rear disc brakes	Electrically adjustable left-side mirror	Electrically adjustable right-side mirror
Heated left-side mirror	Heated right-side mirror	Rétroviseur intérieur jour/nuit automatique
Siège avant gauche à réglage électrique	Siège avant gauche à réglage mémorisé	Siège avant gauche à réglage lombaire
Sièges avant massants	Fixations Isofix siège passager avant	Garnitures tissu et Alcantara
Volant cuir	Volant multifonction	Aide au stationnement avant
Aide au stationnement arrière	Caméra avant	Caméra arrière de recul
Régulateur automatique de la distance	Affichage lecture des panneaux de signalisation	Verrouillage centralisé à commande à distance
Carte mains libres	Appel de secours	détecteur de pluie essuie-vitre
Ceintures de sécurité arrière à enrouleur	Témoin d'oubli de ceinture avant	Témoin d'oubli de ceinture arrière
Assistant maintien de la voie	Freinage d'urgence assistée autonome (urbain)	depuis 11.23
Digital Cockpit Pro	grille de calandre et poignées de portes éclairées	antenne AM/FM
Car2X communication	radio digitale (DAB)	services Online
connexion USB av/ar	boulons de roue avec antivol	garnitures de portes en simili-cuir noir/gris silex
ceintures de sécurité avant avec prétensionneurs et tensionneur final	éclairage d'ambiance	suspension ar à 4 bras
câble de charge pour prise domestique Mode 2 Type 2 E+F (10A) EV3	câble de charge pour station de recharge publique Mode 3 Type 2 3P (16A) 76C	e-Sound avec haut-parleurs av
transmission hybride PHEV	airbag central entre les sièges av	activated carbon (EVAP) tank

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
GPS:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Heated front seats:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlight type:		**Tow bar type:**	
Charging cables:	1	**Fast charging cables:**	1

TIRES

Position	Depth	Brand	Dimensions	Kind	Rims	Runflat
Front left	6 mm		205/55R16 94V	All seasons		?
Front right	6 mm		205/55R16 94V	All seasons		?
Rear left	6 mm		205/55R16 94V	All seasons		?
Rear right	6 mm		205/55R16 94V	All seasons		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Rental	Damage type
1	Interior - Ozonreiniging wegens geurhinder	Dirty
2	Bumper F	Grooved
3	Roof - +-96 deuken	Hail damage
4	Bonnet - +- 10 deuken	Hail damage
6	Alloy rim RL polished	Grooved
7	Bumper R	Grooved
8	Tailgate / Boot	Grooved
9	Alloy rim RR polished	Grooved
10	Alloy rim FR polished	Grooved

Total: 9

ACCEPTABLE / NOT TO BE INVOICED

#	Rental	Damage type	Renta®	Repaired	Already invoiced
5	Bodywork	Teeth and scratches	✓	✗	✗

Total: 1

DAMAGE DETAILS

1 - Interior - Ozonreiniging wegens geurhinder - Dirty






2 - Bumper F - Grooved





3 - Roof - +-96 deuken - Hail damage








4 - Hat - +- 10 deuken - Hail damage






6 - Alloy rim RL polished - Grooved





7 - Bumper R - Grooved








8 - Tailgate / Boot - Grooved







9 - Alloy rim RR polished - Grooved







10 - Alloy rim FR polished - Grooved






5 - Bodywork - Dent(s) and scratch(es) - Renta®












SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

16/10/2026 11:35