TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

# Expertise

Protocol number: 48451909
Order No. / Reference: 27210216
Inspection date: 2 Nov 2026

| Manufacturer: Opel | Model: Astra Sports Tourer 1.5 D Automatik Ultimate |
|---|---|
| VIN: VXKFCYHZTP1084638 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Opel Astra Sports Tourer 1.5 D Automatik Ultimate | |
| **Vehicle Identification number** | VXKFCYHZTP1084638 |
| **Mileage** (Read) | 109,297 km |
| **First registration** | 27 Mar 2024 |
| **Number of holders** | 1 |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,499 ccm / 3 |
| **Power** | 96 kW |
| **Gearbox / Number of gears** | Automatic / 8 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Station wagon |
| **Colour / colour code** | Vulkan Grau Metallic |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Alcantara / Leather |
| **Colour of upholstery** | Black-Anthracite |

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | Available / complete | **Next maintenance in** | |
| **Last service on / at** | 08/2026 at 104,364 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GY762353 |
| **Previous damage / Accident** | None detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | No |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 1889 / AEY 00088 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 1,980 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 225/40 R18 92V | All-season tyres on Light alloy | Kleber | 5mm / 5mm |
| 2) | 225/40 R18 92V | All-season tyres on Light alloy | Kleber | 5mm / 5mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| N | 125/85 R16 99M | Summer tyres on Steel | Uniroyal | 4 mm |
| | Tirefit | Expiration date 07/2028 | | |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- Storage compartments (storage compartment in the center console, in the front doors suitable for 1.5-liter beverage bottles, in the rear doors suitable for 0.5-liter beverage bottles, glove compartment with LED lighting)
- Airbag: Front and rear outer head airbags
- Aluminum pedals
- Automatic activation of the hazard warning lights (and unlocking of the doors after deployment of the airbag or seatbelt pretensioner)
- On-board computer
- Roof design line, in black
- Diesel particulate filter (DPF) maintenance-free (exhaust aftertreatment via SCR (Selective Catalytic Reduction) catalyst with AdBlue (urea injection). Vehicles with BlueInjection technology require refilling of the AdBlue fluid between regular service intervals. A display in the vehicle informs the driver in good time when refilling is necessary.)
- Transmission: 8-speed automatic transmission
- Electric tailgate, sensor-controlled (self-opening and self-closing via foot gesture)
- Back window, heater
- rear window wiper
- Intelli-Drive 1.0 (Forward Collision Warning with Automatic Emergency Braking, Pedestrian Detection, Active Lane Keeping Assist, Traffic Sign Recognition and Driver Alert System, Cross Traffic Alert and Automatic Speed Assist with Stop Function, Blind Spot Warning)
- Cable set for trailer hitch
- Dual-zone automatic climate control (dual-zone automatic climate control with separate temperature control for driver and front passenger - recirculation mode, manual - particle/activated carbon filter - automatic air distribution - sun position sensor - humidity sensor)
- Steering wheel: Leather steering wheel, flat-bottomed, perforated, with steering wheel remote control and paddle shifters
- Illuminated makeup mirrors in both sun visors
- Navigation system, Hi-Fi sound system and head-up display (multimedia infotainment system with 10" color touchscreen display and 10" driver information display; navigation system with integrated memory; 3D map display for Europe and Russia; dynamic route guidance; TomTom Online Traffic; online POI search and route guidance; parking information; fuel price information; live weather; over-the-air map updates; intelligent voice control; "Hey Opel" quick button with 6 functions; active route suggestions; Hi-Fi sound system with 8 speakers)
- Tire pressure monitoring system
- Reversing camera: 360-degree reversing camera
- Keyless locking and starting system Keyless Open & Start
- safety net
- Airbag: Chest-pelvis side airbags, driver and front passenger (side airbag, front passenger can be manually deactivated)
- Airbag: Front airbags, driver and front passenger (front passenger airbag can be manually deactivated)
- Anti-lock braking system (ABS) (including brake assist)
- Exterior mirrors, electrically adjustable, heated and folding
- Exterior mirror housings in black
- Hill Start Assist
- third brake light
- Headliner, Black
- Tachometer
- Electronic brake force distribution (EBD)
- Electronic Stability Program (ESP) and Traction Control with engine and brake intervention (TCPlus)
- Electric windows front and rear (with one-touch function and anti-pinch protection)
- Glass sliding/sunroof, electric with spoiler position (pinch protection - comfort closing function via radio remote control of the central locking system - sunshade roller blind)
- Interior rearview mirror, automatically dimming
- IntelliLux LED Pixel Light (Adaptive LED matrix headlights with individual light distribution and the following functions: - City light - Highway light - Country road light - Static cornering light - Turning light - Parking function light - High beam: traffic-dependent dimming taking into account preceding and oncoming traffic - Automatic headlight range control, LED taillights, LED daytime running lights, LED turn signals, automatic low beam, rain sensor)
- Front headrests and 3 rear headrests, height adjustable
- LED ambient lighting (front doors, adjustable in 8 colors)
- LED interior lighting (including reading lights, front and rear, as well as trunk lighting and lighting in the front footwell)
- Steering wheel heating
- Center armrest, front and rear (front center armrest with USB port and 2 USB chargers - front and rear cup holders - storage compartments - rear center armrest with pass-through)
- Fog light
- Opel Blitz logo, Astra lettering on the rear (high-gloss black surround for air intakes)
- Opel Vizor with frame in high-gloss black
- Electric parking brake
- Parkpilot, front and rear parking aid
- Tire repair kit (including tire sealant and 12-volt compressor (without jack))
- Rear seat backrest folds forward in a 40:20:40 split
- Seat belts: Three-point seat belts in all seats (belt force limiter and belt tensioner in the front and on the outer rear seats - warning tone and light for unfastened seat belts in all seats)
- Heated seats for driver and front passenger (multi-stage adjustable)
- Solar Protect heat-insulating glazing (in the rear, heavily tinted)

- Seats: Ergonomic sport active seat driver Greta fabric/premium leather look (Ergonomic sport active seat (AGR), driver - Greta fabric/premium leather look, black, - driver's seat 10-way adjustable (length, height, tilt, backrest tilt, seat cushion tilt) - front passenger seat 6-way adjustable (length, height, tilt) - 4-way front headrests - pockets on the back of the front seats)
- 12V power outlet in the center console
- Door sill trims with Ultimate lettering, front
- Pre-installation for ISOFIX child seat mounting system (incl. top tether attachment points, rear outer)
- Wireless Charging
- Start/Stop system (Driving assistant - Reinforced starter - AGM high-performance battery - eco switch to deactivate the start/stop function - Brake energy recuperation)
- Electronic immobilizer
- Heated windscreen, ThermaTec
- Central locking with remote control (and interior switch)

### Extra equipment

- Paint finish: Metallic
- Wheels: Pre-installation for emergency wheels
- 18" 5-spoke alloy wheels in bicolor/black

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Door - rear right side | Door edge - Scratch(es) - Smart repair |
| 2 | Wing mirror - right side | Cap - Scratch(es) - Smart repair |
| 3 | Door - front right side | Door - dent(s) - Smooth repair work |
| 4 | Door - front left side | Door - dent(s) - Smart repair |
| 5 | Wheel / tyres | Alloy rim - rear left side - Scratched - Replace |
| 6 | Wheel / tyres | Alloy rim - rear right side - Scratched - Replace |
| 7 | Wheel / tyres | Alloy rim - front left side - Scratched - Replace |
| 8 | Wheel / tyres | Alloy rim - front right side - Scratched - Replace |
| 9 | Front bumper | Front bumper - Scratched - Paint |
| 10 | Bonnet | Bonnet - Scratch(es) - Paint |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Side panel - rear right side | Side panel - Scratch(es) - No deduction |
| 2 | Door - front left side | Door edge - Scratch(es) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Missing parts

**Description**

Interior - Luggage net

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Restlauf Service nicht Abrufbar




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area





**Figure 11:** VIN




**Figure 12:** Mounted tyres





**Figure 13:** Documents




**Figure 14:** Documents





**Figure 15:** Documents





**Figure 16:** Documents





**Figure 17:** Navigation



**Figure 18:** Misc.



**Figure 19:** Misc.



**Figure 20:** Misc.



**Figure 21:** Misc.




**Figure 22:** Misc.




**Figure 23:** Misc.





**Figure 24:** Misc.




**Damage 1:** Door - rear right side: Door edge - Scratch(es) - Smart repair



**Damage 1:** Door - rear right side: Door edge - Scratch(es) - Smart repair




**Damage 2:** Wing mirror - right side: Cap - Scratch(es) - Smart repair



**Damage 2:** Wing mirror - right side: Cap - Scratch(es) - Smart repair



**Damage 3:** Door - front right side: Door - dent(s) - Smooth repair work



**Damage 3:** Door - front right side: Door - dent(s) - Smooth repair work



**Damage 4:** Door - front left side: Door - dent(s) - Smart repair



**Damage 4:** Door - front left side: Door - dent(s) - Smart repair



**Damage 5:** Wheel / tyres: Alloy rim - rear left side - Scratched - Replace




**Damage 5:** Wheel / tyres: Alloy rim - rear left side - Scratched - Replace



**Damage 5:** Wheel / tyres: Alloy rim - rear left side - Scratched - Replace



**Damage 5:** Wheel / tyres: Alloy rim - rear left side - Scratched - Replace




**Damage 6:** Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



**Damage 6:** Wheel / tyres: Alloy rim - rear right side - Scratched - Replace




**Damage 6:** Wheel / tyres: Alloy rim - rear right side - Scratched - Replace




**Damage 6:** Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



**Damage 7:** Wheel / tyres: Alloy rim - front left side - Scratched - Replace



**Damage 7:** Wheel / tyres: Alloy rim - front left side - Scratched - Replace




**Damage 7:** Wheel / tyres: Alloy rim - front left side - Scratched - Replace



**Damage 7:** Wheel / tyres: Alloy rim - front left side - Scratched - Replace



**Damage 8:** Wheel / tyres: Alloy rim - front right side - Scratched - Replace



**Damage 8:** Wheel / tyres: Alloy rim - front right side - Scratched - Replace




**Damage 8:** Wheel / tyres: Alloy rim - front right side - Scratched - Replace



**Damage 9:** Front bumper: Front bumper - Scratched - Paint




**Damage 9:** Front bumper: Front bumper - Scratched - Paint



**Damage 9:** Front bumper: Front bumper - Scratched - Paint



**Damage 10:** Bonnet: Bonnet - Scratch(es) - Paint



**Damage 10:** Bonnet: Bonnet - Scratch(es) - Paint