TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48510933
Order No. / Reference: 27157702-2
Inspection date: 20 Oct 2026

Manufacturer: Opel	Model: Astra Sports Tourer 1.5 D Business Edition
VIN: VXKFCYHZLP1042297	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Astra Sports Tourer 1.5 D Business Edition	
Vehicle Identification number	VXKFCYHZLP1042297
Mileage (Read)	106,819 km
First registration	1 Aug 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	96 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Arktis Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Grey

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	11,000 km
Last service on / at	07/2026 at 98,677 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS851844
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / AEY 00071		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,980 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 94V	All-season tyres on Light alloy	Continental	5mm / 5mm
2)	205/55 R16 94V	All-season tyres on Light alloy	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/85 R16 99M	Summer tyres on Steel	Uniroyal	3 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments: Storage compartment in the center console, in the front doors suitable for 1.5-liter beverage bottles, in the rear doors suitable for 0.5-liter beverage bottles, glove compartment with LED lighting
- Airbag: Front and rear outer head airbags
- Anti-lock braking system (ABS) including brake assist
- Exterior mirrors, electrically adjustable, heated and manually foldable
- Exterior mirror housings in black
- On-board computer
- Diesel particulate filter (DPF) maintenance-free exhaust aftertreatment via SCR (Selective Catalytic Reduction) catalyst with AdBlue (urea injection). Vehicles with BlueInjection technology require refilling of the AdBlue fluid between regular service intervals. A warning light in the vehicle will inform the driver when refilling is necessary.
- Electric windows front and rear - with one-touch function and anti-pinch protection
- rear window wiper
- Automatic climate control Single-zone automatic climate control with particle and activated carbon filter
- LED interior lighting including reading lights, front and rear, and trunk lighting
- Steering wheel: Leather steering wheel, flat-bottomed, with steering wheel remote control
- Steering wheel heating
- Center armrest, front and rear - Front center armrest with USB port and 2 USB chargers - Front and rear cup holders - Storage compartments - Rear center armrest with pass-through
- Tire pressure monitoring system
- 180-degree reversing camera - Park Pilot, front and rear parking aid
- Keyless Start system
- Seats: Ergonomic active driver's seat in Modene fabric - certified by the German Campaign for Healthy Backs (AGR) - adjustable length, height, tilt, backrest angle, and seat cushion angle - electro-pneumatically adjustable lumbar support (height and length) - extendable thigh support - Modene fabric, black - heated front seats and steering wheel
- Start/Stop system - Driving assistant - Reinforced starter motor - High-performance AGM battery - Eco switch to deactivate the start/stop function - Brake energy recuperation
- Wireless Charging
- Airbag: Chest-pelvis side airbags, driver and front passenger side airbag, front passenger airbag can be manually deactivated
- Airbag: Front airbags, driver and front passenger - front passenger airbag can be manually deactivated
- Automatic activation of the hazard warning lights and unlocking of the doors after deployment of the airbag or seatbelt tensioner.
- Hill Start Assist
- third brake light
- Tachometer
- Eco Coaching: Upshift recommendation via display in the driver information display
- Electronic brake force distribution (EBD)
- Electronic Stability Program (ESP) and Traction Control with engine and brake intervention (TCPlus)
- Transmission: 6-speed manual transmission
- Back window, heater
- Cable set for trailer hitch
- Front headrests and 3 rear headrests, height adjustable
- Paintwork: Roof in car color
- LED headlights - LED daytime running lights - LED taillights - LED turn signals - Manual headlight range adjustment - High beam assist - Automatic low beam - Rain sensor
- Illuminated makeup mirrors in both sun visors
- Fog light
- Electric parking brake
- Tire repair kit including tire sealant and 12-volt compressor (without jack)
- Wheels: 7 J x 16 alloy wheels (5 double spokes) in silver with low rolling resistance tires 205/55 R 16
- Rear seat backrest folds forward in a 40:20:40 split
- Seat belts: Three-point seat belts in all seats - belt force limiters and belt tensioners in the front and on the outer rear seats - warning tone and light for unfastened seat belts in all seats
- Heated seats, driver and front passenger - multi-stage switchable
- Solar Protect heat-insulating glazing in the rear, heavily tinted.
- 12V power outlet in the center console
- Pre-wiring for ISOFIX child seat mounting system including top tether attachment points, rear outer
- Electronic immobilizer
- Central locking with remote control and interior switch

Extra equipment

- Navigation system Multimedia Infotainment system with 10" touchscreen color display and 10" driver information display Navigation system with integrated memory 3D map display for Europe and Russia Dynamic route guidance via map and/or arrow display and voice prompts TomTom Online Traffic Online POI search and route guidance Parking information Fuel price information Live weather Over-the-air map updates Intelligent voice control Hey Opel Shortcut key 6 functions Active route suggestions
- 16" alloy wheels 5 DS All-weather
- cargo area liner
- Detachable trailer hitch including trailer stability program TSP
- Paint finish: Solid
- Rubber mats
- safety net
- Wheels: Retrofitting a spare wheel

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 31 Jul 2024	2.382,93 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Navigation




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction