TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48290343
Order No. / Reference: 27198997
Inspection date: 23 Oct 2026

Manufacturer: Opel	Model: Crossland 1.5 Diesel Automatik Elegance
VIN: W0V7H9EJ0N4337223	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Crossland 1.5 Diesel Automatik Elegance	
Vehicle Identification number	W0V7H9EJ0N4337223
Mileage (Read)	45,300 km
First registration	16 Sept 2022
Number of holders	2
Next periodical technical inspection	09/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	88 kW
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Jade Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	-180 km
Last service on / at	09/2025 at 36,702 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GN181416
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1844 / AKJ 00320		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,860 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/60 R16 89H	Summer tyres on Light alloy	Bridgestone	4mm / 4mm
2)	195/60 R16 89H	Summer tyres on Light alloy	Bridgestone	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92H	Winter tyres on Steel	Semperit	4mm / 4mm
2)	205/60 R16 92H	Winter tyres on Steel	Semperit	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag: Front and rear outer head airbags
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- third brake light
- Roof spoiler
- Tachometer
- Electronic Stability Program (ESP Plus)
- Electric rear windows
- Speed controller with limiter
- Back window, heater
- Interior lighting
- Rear headrests (3)
- Paint finish: Metallic special color Nautic Blue
- LED headlights
- Steering wheel: Leather steering wheel with chrome elements and steering wheel remote control
- Upholstery: Fabric/Premium leather look
- Radio: Digital radio reception DAB/DAB+/DMB-R
- Tire repair kit
- Tire pressure warning
- Power steering
- Seat belts: Three-point seat belts in all seats
- Seats: Ergonomic active seat (AGR) driver
- Lane Assist
- 12V power outlet in the center console
- Underride protection look, front and rear, in silver
- Pre-installation for child seat mounting system "ISOFIX"
- Heat-insulating glazing, tinted
- Airbag for driver and passenger side
- Airbag: Side airbag for driver and front passenger side
- Armrest, driver
- Hill Start Assist
- On-board computer
- Roof design line, above, in chrome
- Diesel particulate filter (DPF) maintenance-free
- Electronic brake force distribution (EBD)
- Driver information display, 3.5"
- Electric front windows
- Transmission: 6-speed automatic transmission
- rear window wiper
- Automatic climate control, two zones
- Front headrests
- LED ambient lighting
- LED daytime running lights
- Headlight range adjustment, manual
- Center armrest, front
- Quickheat rapid heating system
- Radio: Multimedia radio with 7" color touchscreen display, 6 speakers
- Wheels: Alloy wheels 6.5 J x 16 with tires 195/60 R16 (10 spokes)
- Visibility equipment
- Seats: Seat backrest split 60:40, foldable
- Start/Stop System
- Traction control (TC Plus)
- Traffic sign assistant
- Immobiliser
- Central locking with remote control

Extra equipment

- Navigation system: Multimedia Navi Pro with 8" color touchscreen display, voice control for audio, telephone, and navigation (Bluetooth audio streaming, hands-free calling via Bluetooth interface, phonebook and call list display, FM/AM radio, Autostore, RDS-EON, automatic music recognition, image display via USB port, Apple CarPlay, Android Auto, text message reading and dictation, up to 10 mobile phones can be paired, navigation with integrated memory, European road map (including Russia and Turkey), 3D map display, dynamic route guidance, 2 USB ports, 3.5" color driver information display).
- Cargo area partition
- Parkpilot, front and rear parking aid (with acoustic warning signal when parking forwards and backwards)
- Solar Protect heat-insulating glazing (in the rear, heavily tinted)
- Steering wheel: Heated leather steering wheel and seat heating, multi-stage, driver and passenger

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - Due - Replace

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper (unpainted) - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Interior - Rear shelf

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Damage 1: Misc.: Inspection / maintenance - Due - Replace



Missing part 1: Interior: Rear shelf - Missing - Replace