TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48059122
Order No. / Reference: 27152885
Inspection date: 12 Oct 2026

Manufacturer: Ford	Model: Kuga 2.5 Duratec PHEV TITANIUM
VIN: WF0FXXWPMHPE87952	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Kuga 2.5 Duratec PHEV TITANIUM	
Vehicle Identification number	WF0FXXWPMHPE87952
Mileage (Read)	42,616 km
First registration	11 Sept 2023
Number of holders	1
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	2,488 ccm / 4
Power	112 kW
Gearbox / Number of gears	Automatic / 1
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Agate Black Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Anthracite-Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	11 %
Last service on / at	01/2025 at 21,320 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT903202
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BTM 00020		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,320 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R17 102V	Summer tyres on Light alloy	Bridgestone	4mm / 4mm
2)	225/65 R17 102V	Summer tyres on Light alloy	Bridgestone	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R17 102H	Winter tyres on Light alloy	Dunlop	6mm / 6mm
2)	225/65 R17 102H	Winter tyres on Light alloy	Dunlop	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Acoustic Vehicle Alerting System (AVAS)
- Anti-lock braking system
- Electrically adjustable, heated and folding exterior mirrors (painted in body color - with integrated turn signals and ambient lighting)
- Tires: Tire repair kit (maximum speed 80 km/h when used)
- Fabric headliner
- Roof spoiler (painted in car color)
- Dual exhaust system
- Electronic Stability Program (ESP) (with hill start assist, traction control and emergency brake assist)
- Lane keeping assist including lane keeping assist
- Electric parking brake with auto hold function
- Ford Easy Fuel (Ford Easy Fuel comfort refueling system (Eliminates the need for a separate internal fuel cap and prevents misfueling by detecting the size difference between petrol and diesel nozzles. The filler neck only opens when the correct fuel is used.)
- Luggage compartment cover, roller blind, removable
- Luggage compartment lighting
- Transmission: continuously variable automatic transmission (CVT)
- rear window wiper
- Intelligent Protection System (IPS) (front airbag for driver and front passenger - front and rear head and shoulder airbags - side airbag for driver and front passenger - seat belt tensioners and force limiters in the front and on the outer seats of the 2nd row - 3-point seat belts in all seats, height-adjustable in the front - warning system for unfastened driver and front passenger seat belts)
- LED taillights
- Steering wheel: Steering wheel, 3-spoke design, in Sensico synthetic leather
- MyKey key system (individually programmable second key)
- Navigation system: Ford navigation system incl. Ford SYNC 3 (AppLink, Android Auto, Apple CarPlay - 8" touchscreen (20.3cm screen diagonal) - DAB/DAB+ radio reception (Digital Audio Broadcasting) - 6 speakers - Steering wheel controls - Bluetooth® hands-free system and audio streaming - 2 USB ports - Voice control for audio and telephone - SMS text-to-speech function - Road map for Europe)
- Tire Pressure Monitoring System (TPMS)
- Rear view camera
- Windscreen wipers with rain sensor
- Headlights with delayed shut-off
- Power steering (electro-mechanical, speed-dependent (EPAS - Electric Power Assisted Steering))
- Seats: Map pockets on the driver's and front passenger's seat backrests
- Seats: Front seats, individually and variably heated
- Power outlet: 12-volt connection in the luggage compartment
- Central locking with remote control and remote luggage compartment release
- Ambient lighting (front including front door storage, footwell and cup holder lighting with LED technology)
- Passenger airbag deactivation
- Tires: 7 J x 17 alloy wheels (4) in 5x2-spoke design (with 225/65 R 17 tires)
- third brake light
- Roof rails, silver-colored
- 12.3-inch digital instrument panel
- Tachometer
- Selective driving mode switch (5 driving modes to choose from: Normal, Sport, Eco, Slippery and Unpaved Roads)
- Electric front and rear windows (with quick-down function including all-around closing function)
- Ford EcoCoach (shows the efficiency of current driving behavior)
- Ford Power Start function & Ford Key Free system (keyless locking/unlocking)
- FordPass Connect (including eCall, live traffic information and Wi-Fi hotspot)
- Cruise control
- Illuminated glove compartment
- Heated rear window
- Interior mirror, automatically dimming
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Front and rear headrests (5) height adjustable
- Charging cable (for household sockets and public charging stations)
- Steering column, adjustable in height and reach
- Front center console with integrated armrest (2 front cup holders)
- Fog light
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Front and rear parking pilot system
- Upholstery: Cloth
- Post-Collision Assist
- Pre-Collision Assist (including forward alert system (FA) with pedestrian and bicycle detection - active from approx. 5 km/h to 130 km/h, pedestrian and bicycle detection up to approx. 80 km/h.)
- Projection lens headlights with LED daytime running lights
- Headlight assistant with day/night sensor
- Seats: Driver and front passenger seats, 8-way manually adjustable (including adjustable lumbar support)
- Seats: Rear bench seat, sliding, with split-folding backrest
- Seats: Front sports seats with integrated headrests
- Sun visor on driver and passenger side
- Carpet floor mats front and rear, velour
- Immobiliser

Extra equipment

- Paint finish: Agate Black Metallic
- Safety partition net (including attachment points behind the first and second rows of seats)
- Charging cable for public charging station HTSAJ

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Wing mirror - left side	Cap - Scratch(es) - Smart repair
3	Door - rear right side	Door edge - Scratch(es) - Smart repair
4	Door - rear right side	Door handle - outside - Scratch(es) - Smart repair
5	Roof	Roof - dent(s) - Smooth repair work
6	Rear bumper	Rear bumper - Scratch(es) - Smart repair
7	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
8	Door - rear left side	Door - Scratch(es) - Smart repair
9	Roof	Roof rail - right side - Scratch(es) - Paint
10	Rear bumper	Rear bumper (unpainted) - Scratch(es) - Loss in value
11	Rear bumper	Spoiler - Scratch(es) - Replace
12	Interior	Rear shelf - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Side panel - rear left side	Side panel - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.




Figure 37: Misc.



Figure 38: Misc.




Damage 2: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 2: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 3: Door - rear right side: Door edge - Scratch(es) - Smart repair




Damage 3: Door - rear right side: Door edge - Scratch(es) - Smart repair



Damage 4: Door - rear right side: Door handle - outside - Scratch(es) - Smart repair



Damage 4: Door - rear right side: Door handle - outside - Scratch(es) - Smart repair



Damage 5: Roof: Roof - dent(s) - Smooth repair work




Damage 5: Roof: Roof - dent(s) - Smooth repair work




Damage 5: Roof: Roof - dent(s) - Smooth repair work



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 6: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 8: Door - rear left side: Door - Scratch(es) - Smart repair



Damage 8: Door - rear left side: Door - Scratch(es) - Smart repair



Damage 9: Roof: Roof rail - right side - Scratch(es) - Paint



Damage 9: Roof: Roof rail - right side - Scratch(es) - Paint



Damage 9: Roof: Roof rail - right side - Scratch(es) - Paint




Damage 10: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 10: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 10: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 10: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 11: Rear bumper: Spoiler - Scratch(es) - Replace




Damage 11: Rear bumper: Spoiler - Scratch(es) - Replace



Damage 12: Interior: Rear shelf - Broken / torn - Replace



Damage 12: Interior: Rear shelf - Broken / torn - Replace



Wear and tear 1: Side panel - rear left side: Side panel - Scratch(es) - No deduction