TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

Expertise

Protocol number: 48297500
Order No. / Reference: 27191442
Inspection date: 22 Oct 2026

Manufacturer: Skoda	Model: Kodiaq 1.5 TSI iV DSG Selection
VIN: TMBJW7PS2ST083175	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Kodiaq 1.5 TSI iV DSG Selection	
Vehicle Identification number	TMBJW7PS2ST083175
Mileage (Read)	19,202 km
First registration	15 May 2025
Number of holders	1
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,498 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	moonweiss-metallic (S9R)
Doors / Seats	5 / 5
Upholstery type	Part leather
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	10,900 km
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HM630724
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AYE 00020		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,432 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R18 100V	Summer tyres on Light alloy	Hankook	6mm / 6mm
2)	235/55 R18 100V	Summer tyres on Light alloy	Hankook	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Turning assistant including evasive steering support
- Airbag, center airbag front
- Airbag, driver and passenger
- Airbag, front and rear head airbags
- Ambient lighting inside and logo projector outside
- Anti-lock braking system (ABS)
- Attention and fatigue detection
- Exterior mirrors and door handles painted in body color
- Hydraulic brake assist
- Roof rails, black
- Digital rotary controls (Smart Dials)
- E-Sound
- Electronic transverse differential lock (XDS+)
- Driving profile selection
- Front radar assistant including city emergency braking function with pedestrian and cyclist detection
- Illuminated glove compartment
- rear window wiper
- Intelligent Speed Assist (ISA)
- Interior Design Selection Loft
- Isofix anchorage on the outer rear seats including top tether
- Front and rear headrests are height-adjustable.
- Paint finish: Uni Energy Blue
- Mode 3 charging cable, Type 2/3, 16A
- LED headlights with driving light assistant
- Rear center armrest with cup holders
- Front center armrest including cup holder
- Multi-collision brake
- Front and rear parking sensors with maneuvering brake function
- Radio: Basic infotainment system
- Radio accessories: Wireless SmartLink
- Umbrella compartment in the driver's door
- Tire Mobility Kit
- Wheels: 18" Mazeno Aero alloy wheels, silver polished
- Electromechanical power steering
- Seats: Heated front seats
- Seats: Rear seat backrest split 40:20:40, foldable
- Seats: Front seats height-adjustable including manually adjustable lumbar support
- Lane keeping assistant (Lane Assist)
- Lane change assist (Side Assist) and parking assist, as well as exit warning.
- Pockets on the back of the front seats including smartphone pockets
- Lashing eyes in the luggage compartment
- Immobiliser
- Electric auxiliary heater
- Storage compartments in the door panels with bottle holders (1.5 l) and compartments for high-visibility vests, front and back.
- Airbag, front side airbags
- Trailer hitch preparation
- Traction control (ASR)
- Electrically adjustable, heated and folding exterior mirrors
- Hill start assist
- Glasses compartment in the headliner
- Digital Cockpit Plus (10")
- Third brake light
- Electronic parking brake including auto-hold function
- ESC Electronic Stability Control
- Electric windows front and rear
- Cruise control
- Transmission: 6-speed dual-clutch transmission (DSG)
- Heated rear window
- Automatically dimming interior mirror with sensors, frameless
- Isofix anchorage on the front passenger seat
- Electric child safety lock for the rear doors and windows
- Climatronic air conditioning (3-zone)
- Crossroad Assist
- Mode 2 Type 2 / E+F charging cable (10A)
- LED taillights with black strip between the lights
- Steering wheel: Leather steering wheel with multifunction buttons including paddle shifters.
- Engine drag torque control (MSR)
- Otto particulate filter
- Phonebox with inductive fast charging function for 2 smartphones including cooling
- Radio accessories: 2 x USB-C ports in the front and 2 x USB-C charging ports in the rear.
- Rain sensor and driving light assistant (Easy Light Assist)
- Tire pressure monitoring
- Rear view camera
- Seat belts
- Seats: Remote release of the rear seat backrests (2nd row) in the boot
- Skoda Care Connect
- Sun visors with illuminated make-up mirror on driver and passenger side
- 12V power outlet in the luggage compartment and on the back of the center console
- Textile floor mats
- Traffic sign recognition
- Preparation for an alcohol test
- Central locking including remote control integrated into the key

Extra equipment

- Acoustic glazing in the front side windows and Sunset ((rear window and rear side windows dark tinted))
- Luggage net partition
- Paint finish: Pearl effect
- Package: Driver assistance
- Package: Infotainment Plus (Navigation system - 13" infotainment display - Display cleaner - Head-up display - Infotainment Online (3-year subscription) - ChatGPT integration)
- Package: Light & Sight (Matrix LED headlights - Dynamic Light Assist - LED taillights with animated turn signals and red crystal structure strip between the lights)
- Wheels: 18" alloy wheels Soira Aero, anthracite polished (7.5Jx18, ET40, with tires 235/55 R18 100V)
- Swiveling trailer hitch (with electric release, including trailer stabilization)
- Interior Design Selection Suite Black (Leather/imitation leather seat covers in black, perforated with black stitching - Black imitation leather pad - Grey trim and black door panels - Grey headliner)
- Package: Comfort Plus (iV) (KESSY, keyless entry and start-stop system - anti-theft alarm system - electric tailgate operation with comfort opening - electrically adjustable front seats with memory function and electrically adjustable lumbar support - Canton sound system)
- Package: Winter (Heated front and outer rear seats - Heated leather steering wheel with multifunction buttons and paddle shifters)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - Smart repair

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair