APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	BMW
Model / version:	1 SERIES HATCH
Vin:	WBA7M710607L59027
Plate:	2CQN446
Mileage:	70278
First registration:	19/10/2022
Color:	SAPHIRSCHWAR

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES






















































VIN INFORMATION

Boîte manuelle	6 rapports	Projecteurs à LED
Matière : alliage	Lettre repère (J)	Diamètre avant 16
Diamètre arrière 16	Largeur avant 7,0	Largeur arrière 7,0
Diamètre avant 16	Diamètre arrière 16	Hauteur avant 55
Hauteur arrière 55	Indice de vitesse avant W	Indice de vitesse arrière W
Largeur avant 205	Largeur arrière 205	Climatisation réfrigérant 1234YF
Diesel	1496 cm3	1.50 litre
85 kw	116 ch	Métallisée vernissée
Rétroviseur intérieur jour/nuit automatique	Siège avant gauche réglable en hauteur	Sièges avant réglable en hauteur
Garnitures tissu	Aide au stationnement avant	Aide au stationnement arrière
Caméra avant	Régulateur automatique de la distance	Appel de secours

Airbag passager désactivable
Freinage d'urgence assistée autonome (urbain)
Contrôle pression des pneus
mesures CO2 étendues
BMW Live Cockpit Plus

Protection piéton
Avertisseur d'angle mort

depuis 07.22
tuner DAB
encarts intérieurs argent Quartz mat nervuré

Assistant maintien de la voie
Avertisseur de collision avant

Advantage
pack de rangement
spécifique Europe

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	6 mm		205/55R16 91H	All-seasons	?	
Front right	6 mm		205/55R16 91H	All-seasons	?	
Rear left	6 mm		205/55R16 91H	All-seasons	?	
Rear right	6 mm		205/55R16 91H	All-seasons	?	

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Rear window - Ontstickeren	Not original part
2	Cover insulation - Marterschade	Damaged
3	Bumper F	Grooved
5	Door FL	Dent(s)
6	Bumper R	Scratch(es)
7	Wing RR	Dent(s) and scratch(es)

Total: 6

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
4	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Rear window - Ontstickeren - Not original part





2 - Cover insulation - Marterschade - Damaged




3 - Bumper F - Grooved






5 - Door FL - Dent(s)





6 - Bumper R - Scratch(es)








7 - Wing RR - Dent(s) and scratch(es)





4 - Bodywork - Dent(s) and scratch(es) - Renta®












SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

27/10/2026 13:46