AUDI A3 BERLINE

Vehicle information

Make:	**AUDI**	License:	**2CMY075**
Gearbox:		Body color:	
Model:	**A3 BERLINE**	VIN:	**WAUZZZGY1PA023429**
Fuel type:		Power:	**110 kW**
Version:	**1.5 TFSI 35 110KW S LINE**	First registration	**21/09/2022**
Mileage:	**25543 km**	N° of doors:	

Damage summary

Front	1
Interior	1
Left	2
Right	5
Roof & others	2

Commercial pictures






























Options according to the inspector

GPS	**Yes**

Damages

Alloy rim FR

Scratch(es)

Repair and paint (complete)


Right






Bodywork
Damaged
Acceptable
Roof & others














Bonnet
Dent(s) and scratch(es)
Repair and paint (complete)
Front








Door FL
Scratch(es)
Paint
Left





Door RL
Scratch(es)
Paint
Left





Interior
Damaged
Acceptable
Interior





Mirror side repeater R
Scratch(es)
Replace
Right





Outer door handle FR
Scratch(es)
Repair and paint (complete)
Right





Outside rear-view mirror base R
Scratch(es)
Smart repair
Right





Outside rear-view mirror housing R
Scratch(es)
Repair and paint (complete)
Right





Roof

Dent(s) and scratch(es)

Repair and paint (complete)

Roof & others










Tyres

Front Left
Summer
Aluminium
225/45/17/91/Y
Bridgestone
6.0 mm
Front Right
Summer
Aluminium
225/45/17/91/Y
Bridgestone
6.0 mm
Rear Left
Summer
Aluminium
225/45/17/91/Y
Bridgestone
7.0 mm
Rear Right
Summer
Aluminium
225/45/17/91/Y
Bridgestone
7.0 mm

Checks

Battery level	**40**	Category	**Passenger Car**
Certificate of Conformity	**Yes**	Compressor	**Yes**
Maintenance	**OK**	Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**0**	Number of keys total	**2**
Registration Certificate Car (BE)	**Yes**	Registration Certificate Home (BE)	**No**
Repair kit	**Yes**	Reset to factory settings	**No, not possible**
Statutory inspection	**OK**	Type of Maintenance book	**Digital maintenance**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.