TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48511704
Order No. / Reference: 27199472
Inspection date: 26 Oct 2026

Manufacturer: Skoda	Model: Octavia Combi 2.0 TDI DSG 4x4 Scout
VIN: TMBLK8NX8PY162983	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI DSG 4x4 Scout	
Vehicle Identification number	TMBLK8NX8PY162983
Mileage (Read)	94,519 km
First registration	26 Jun 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	147 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	Car station wagon
Colour / colour code	Black Magic Pearlescent (F9R)
Doors / Seats	5 / 5
Upholstery type	Alcantara / cloth
Colour of upholstery	Grey-Brown

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	7,800 km
Last service on / at	12/2025 at 72,225 km		
Key is / should be	3 / 3	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GZ001490
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AWM 00063		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,114 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 95V	Winter tyres on Light alloy	Bridgestone	4mm / 4mm
2)	205/55 R17 95V	Winter tyres on Light alloy	unterschiedliche Hersteller	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 91V	Summer tyres on Light alloy	Goodyear	2mm / 2mm
2)	225/45 R18 95Y	Summer tyres on Light alloy	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the luggage compartment with cargo element
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, driver's knee airbag
- Airbag, head airbags
- Airbag, front side airbags
- Airbag: Center airbag front
- Ambient lighting (dashboard, front trim strips and footwell with selectable color climate) in the interior as well as logo projector on the outside)
- Automatically dimming exterior mirror (driver's side)
- Electrically folding exterior mirrors
- Hill start assist including auto-hold function
- Hydraulic brake assist (HBA)
- Grey headliner
- Decorative strip in ash brown
- Digital instrument cluster (Virtual Cockpit) 10.2"
- Third brake light
- Electronic transverse differential lock (XDS+)
- Driving light assistant (Coming Home / Leaving Home function)
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Cruise control system
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec: Start/stop system including brake energy recuperation
- Interior mirror automatically dimming
- Kessy, keyless entry and start-stop system
- Child safety lock for the rear doors and windows
- Removable boot cover
- Headrests (5) front and rear height adjustable
- LED fog lights
- LED license plate lights
- LED matrix headlights and dynamic high beam assist (AFS) (Dynamic and automatic headlight range control - headlight cleaning system including washer fluid level control)
- Steering wheel: height and reach adjustable
- Rear center armrest with pass-through option
- Front center armrest, including storage compartment
- Engine drag torque control (MSR)
- Front and rear parking sensors
- Upholstery: Cloth
- Radio accessories: 2 USB-C ports on the front
- Radio accessories: 8 speakers
- Radio accessories: Digital radio reception DAB+
- Radio accessories: Voice control
- Rain sensor
- Tire mobility kit (tire repair spray incl. compressor)
- Seat belts (Three three-point seat belts in the rear)
- Storage compartments (Four roof grab handles, rear with coat hooks; holder for the warning vest under the driver's seat; storage compartments in the front door panels with 1.5l bottle holders; storage compartments in the rear door panels with 0.5l bottle holders; ticket holder on the windshield; coat hooks on the B-pillars; storage compartments in the doors with felt lining)
- All-wheel drive 4x4
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Center section of the dashboard with fabric covering
- Electrically adjustable and heated exterior mirrors
- Heated windshield washer nozzles including 5l washer fluid reservoir
- Glasses compartment in the headliner
- Roof rails, anodized
- Diesel particulate filter
- Tachometer
- Electronic parking brake
- Electronic Stability Control (ESC)
- Driving profile selection
- Chassis: Chassis lift (15 mm increased ground clearance - modified damper settings - engine underbody protection)
- Front radar assistant including city emergency braking function and pedestrian and cyclist detection
- Tinted windows
- Heated rear window
- Rear window wiper including windshield washer system
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Climatronic air conditioning (2-zone) (fully automatic, separately adjustable for driver and front passenger, and with anti-allergen filter & activated carbon filter)
- LED taillights in crystal glass look and animated turn signals
- LED headlights with LED daytime running lights
- Remote release of the rear seat backrests in the trunk
- Steering wheel: Heated steering wheel including heated front seats
- Steering wheel: Leather steering wheel with multifunction buttons and paddle shifters (leather steering wheel and gearshift lever with leather elements - infotainment and driver assistance system operation)
- Pedals in stainless steel look
- Radio: Bolero music system with capacitive 10" color display
- Radio accessories: Bluetooth hands-free system
- Radio accessories: SmartLink (Apple CarPlay - Android Auto)
- Tire pressure monitoring
- Electromechanical power steering
- Safety lights in the front side doors
- Seats: Rear seat backrest split 60:40, foldable

- Seats: Height-adjustable driver and passenger seats (including lumbar support)
- Speed limiter
- Lane keeping assistant (Lane Assist)
- 12V socket in the trunk
- Telephone: Phonebox with inductive charging function (connection via external antenna)
- Phone: Wireless SmartLink for Apple CarPlay
- Textile floor mats
- Front door sill trims
- Lashing eyes in the trunk
- Immobiliser
- SKODA Care Connect (SOS emergency call function (eCall+ including automatic activation in the event of an accident with airbag deployment) - Mobility service (connection option for rapid assistance in case of breakdown) - Information service (connection option to the hotline for all questions relating to vehicle functions) - Free remote vehicle access for 1 year (Remote Access) with access to vehicle data and functions via smartphone, e.g. parking position, activating hazard warning lights, current fuel level)
- Central locking including remote control integrated into the key and EASY Start

Extra equipment

- Swiveling trailer hitch including trailer stabilization and adapter
- P.: Info. Bus.Columbus (Style,RS,Scout)
- Wheels: 18" Braga alloy wheels, anthracite polished (7.5J x 18, ET 48 with 225/45 R18 tires)
- Heated windscreen
- Comfort opening with electric tailgate operation (Combi)
- Paint finish: Pearl effect
- Package: Comfort (Scout) (3-zone Climatronic - Sunset (dark tinted rear window and rear side windows) - Acoustic glazing in the front side windows - Heated front and outer rear seats)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	C-pillar - trim - interior, left sde - Scratched - Loss in value
2	Mudguard - right side	Mudguard - right side - Scratch(es) - Smart repair
3	Door - front left side	Door - Scratch(es) - Smart repair
4	Rear bumper	Spoiler - Scratch(es) - Replace
5	Front bumper	Front bumper - Dent / paintcoat damage - Smart repair
6	2nd wheel set	2 tyres - Worn - Replace
7	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
8	Rear bumper	Rear bumper - Dent / paintcoat damage - Repair and paint
9	Side panel - rear right side	Side panel - Scratch(es) - Paint
10	Front bumper	Spoiler - Scratched - Replace
11	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
12	Door - rear right side	Door - Dent / paintcoat damage - Paint
13	Door - rear left side	Door - Dent / paintcoat damage - Repair and paint
14	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
15	Roof	Roof - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen with lane departure assistant - Stone chips - No deduction
2	Trim / covers	Door trim - front right side - Scratch(es) - No deduction
3	Trim / covers	C-pillar - trim - interior, right side - Scratch(es) - No deduction
4	Side panel - rear right side	Sill - Scratch(es) - No deduction
5	Boot lid / rear door	Boot lid (polierbar) - Scratch(es) - No deduction
6	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
7	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Umbrella

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: Cargo area



Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.





Figure 31: Misc.



Figure 32: Misc.



Damage 1: Trim / covers: C-pillar - trim - interior, left sde - Scratched - Loss in value




Damage 1: Trim / covers: C-pillar - trim - interior, left sde - Scratched - Loss in value



Damage 2: Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair




Damage 2: Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door - Scratch(es) - Smart repair



Damage 4: Rear bumper: Spoiler - Scratch(es) - Replace



Damage 4: Rear bumper: Spoiler - Scratch(es) - Replace



Damage 4: Rear bumper: Spoiler - Scratch(es) - Replace



Damage 5: Front bumper: Front bumper - Dent / paintcoat damage - Smart repair



Damage 5: Front bumper: Front bumper - Dent / paintcoat damage - Smart repair




Damage 5: Front bumper: Front bumper - Dent / paintcoat damage - Smart repair




Damage 6: 2nd wheel set: 2 tyres - Worn - Replace



Damage 7: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 7: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 8: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 8: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 8: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint




Damage 8: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 9: Side panel - rear right side: Side panel - Scratch(es) - Paint




Damage 9: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 9: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 9: Side panel - rear right side: Side panel - Scratch(es) - Paint




Damage 10: Front bumper: Spoiler - Scratched - Replace




Damage 10: Front bumper: Spoiler - Scratched - Replace




Damage 10: Front bumper: Spoiler - Scratched - Replace




Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Paint




Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Paint




Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Paint




Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Paint




Damage 13: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 15: Roof: Roof - Scratch(es) - Paint



Damage 15: Roof: Roof - Scratch(es) - Paint




Damage 15: Roof: Roof - Scratch(es) - Paint




Damage 15: Roof: Roof - Scratch(es) - Paint



Wear and tear 2: Trim / covers: Door trim - front right side - Scratch(es) - No deduction



Wear and tear 2: Trim / covers: Door trim - front right side - Scratch(es) - No deduction



Wear and tear 4: Side panel - rear right side: Sill - Scratch(es) - No deduction



Wear and tear 4: Side panel - rear right side: Sill - Scratch(es) - No deduction



Wear and tear 5: Boot lid / rear door: Boot lid (polierbar) - Scratch(es) - No deduction



Wear and tear 5: Boot lid / rear door: Boot lid (polierbar) - Scratch(es) - No deduction



Wear and tear 6: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Wear and tear 6: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Wear and tear 7: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wear and tear 7: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Missing part 1: Equipment: Umbrella - Missing - Replace