



Volkswagen Golf (UKL): 2FST631

Vinnnumber:	WVWZZZCD0RW853637	Versionname:	Golf VIII Variant Life Business 1.0TSi 110pk/cv 5p
First Registrationdate:	8/08/2024	Fiscalpower:	
Expertise Mileage:	77417	Power Kw:	81
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	plus 6400 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/55/16/91 V				
Summer tyres:	Fr.L.	Vredestein: 2 mm	Fr.R.	Vredestein: 2 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL	2.0			
Tyre profile depth FR	2.0			
Tyre profile depth RL	4.0			
Tyre profile depth RR	5.0			
Tyre size FL	205/55 R 16 91 V			
Tyre size FR	205/55 R 16 91 V			
Tyre size RL	205/55 R 16 91 V			
Tyre size RR	205/55 R 16 91 V			
Tyre type FL	All seasons			
Tyre type FR	All Seasons			
Tyre type RL	All seasons			
Tyre type RR	All Seasons			
Tyre make FL	2480			
Tyre make FR	2480			
Tyre make RL	2480			
Tyre make RR	2480			

Assistance equipment

Repair kit	No	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bumper F, Scratch(es), Spot repair





Tyre FL, Worn, Check



Tyre repair kit, Missing, Replace



Bumper R, Scratch(es), Acceptable



Parking sensor R, Not functioning (well), Replace



Tyre FR, Worn, Check



Kenteken	2FST631
Merk Model	Volkswagen Golf VIII Variant Life Business 1.0TSi 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	8/8/24

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/4/25	55,204	batterij	Vervangen
12/4/25	55,204	bougie	Vervangen
12/4/25	55,204	klein materiaal	
12/4/25	55,204	koelwatervloeistof	Bijvullen/-laden
12/4/25	55,204	luchtfiler interieur	Vervangen
12/4/25	55,204	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
12/4/25	55,204	remschijven en blokken achter	Vervangen
12/4/25	55,204	remschijven en blokken vooraan	Vervangen
12/4/25	55,204	ruitenswisserrubber achter	Vervangen
12/4/25	55,204	ruitenswisserrubber vooraan	Vervangen
12/4/25	55,204	ruitenswisservloeistof	Bijvullen/-laden
3/7/25	25,874	klein materiaal	
3/7/25	25,874	koelwatervloeistof	Bijvullen/-laden
3/7/25	25,874	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
3/7/25	25,874	ruitenswisservloeistof	Bijvullen/-laden