



TOYOTA Corolla Touring Sports: FV-026-AM

Vinnumber:	SB1Z93BE00E148325	Versionname:	COROLLA TOURING SPORTS Hybride 122h Dynamic Business Supp Lomb VP [5P] bva 0-122CH-5cv (break)
First Registrationdate:	9/11/2020	Fiscalpower:	
Expertise Mileage:	85002	Power Kw:	
Bodytype:	Break	Body colour:	Light Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Seats electric F L	
GPS big screen color		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Seats F heated			
Type of climate control	Autom climate control		

Tyres

	205/55/16/91 V			
Summer tyres:	Fr.L.	Continental: 45%	Fr.R.	Continental: 60%
	Re.L.	Bridgestone: 50%	Re.R.	Bridgestone: 60%
Tyre profile depth FL				5.2
Tyre profile depth FR				4.4
Tyre profile depth RL				4.9
Tyre profile depth RR				4.3
Tyre size FL				205/55 R 16 91 V
Tyre size FR				205/55 R 16 91 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Interior, Stain, Cleaning			



Inner door sill FL, Dent(s), Repair and paint (complete)



Roof liner, Unclamped, Dismount/Mount



Alloy rim FL, Scratch(es), Replace




Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Bumper FR, Scratch(es), Paint



Wing RR, Scratch(es), Paint



Door FR, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Tailgate / Boot, Scratch(es), Paint



Rubber seal for boot lid, Tear, Replace



Historique Maintenance

Immatriculation: **FV-026-AM**

Date de 1ère immatriculation: **09/11/2020**

Modèle: **Toyota COROLLA TOURING SPORTS Hybride 122h Dynamic Business Supp Lomb VP [5P] bva 0-122CH-5cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
30/03/2026	82.566	TOYS MOTORS TOURS	BATTERIE RPLT
03/06/2025	67.732	TOYS MOTORS TOURS	REVISION ET CLIM
	0		FILTRE A AIR RPLT
	0		LIQUIDE DE FREIN
	0		BALAIS ESSUIE GLACE AV AR
22/10/2024	57.280	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
05/04/2024	48.509	TOYS MOTORS TOURS	REVISION
26/09/2023	36.426	TOYS MOTORS TOURS	LIQUIDE DE FREIN
	0		REVISION ET CLIM