



**Toyota Corolla:**

Vinnumber:	<b>SB1Z93BE20E368307</b>	Versionname:	
First Registrationdate:	<b>2/03/2023</b>	Fiscalpower:	
Expertise Mileage:	<b>90599</b>	Power Kw:	
Bodytype:		Body colour:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>3231</b>
Fueltype:	<b>Hybrid Petrol</b>		
Maintenance:	<b>OK</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	<b>No Tow bar</b>
Radio multimedia:			
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		
Adaptive cruise control:			
Type of GPS storage:	<b>HD</b>		

**Limited Technical Inspection**

**Tyres**

<b>205/55/16/91 V</b>				
Summer tyres:	Fr.L.	<b>Pirelli: 6 mm</b>	Fr.R.	<b>Pirelli: 6 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>
Tyre profile depth FL				<b>6.0</b>
Tyre profile depth FR				<b>6.0</b>
Tyre profile depth RL				<b>4.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>205/55 R 16 91 V</b>
Tyre size FR				<b>205/55 R 16 91 V</b>
Tyre size RL				<b>205/55 R 16 91 V</b>
Tyre size RR				<b>205/55 R 16 91 V</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>264</b>
Tyre make FR				<b>264</b>
Tyre make RL				<b>255</b>
Tyre make RR				<b>255</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT	<b>564,61</b>
Bumper F, Scratch(es), Acceptable	<b>0,00</b>



Alloy rim FL, Scratch(es), Repair and paint (complete)

133,03



Alloy rim RL, Scratch(es), Acceptable

0,00



Boot lid covering R, Scratch(es), Acceptable

0,00



Wing RR, Scratch(es), Repair and paint (complete)

431,58

