



Peugeot 2008 (UKL): 2CER861

Vinnumber:	VR3UDYHSKNJ659433	Versionname:	2008 Roadtrip 1.5 BlueHDi S&S 110pk/cv 5p
First Registrationdate:	27/06/2022	Fiscalpower:	
Expertise Mileage:	101805	Power Kw:	81
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Diesel		
Maintenance	OK		
Maintenance	+ 29500 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Maintenance book present		
Type of GPS storage	HD		

Tyres

215/60/17/100 V				
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Cooper: 7 mm	Re.R.	Cooper: 7 mm
Tyre profile depth FL	6.0			
Tyre profile depth FR	6.0			
Tyre profile depth RL	7.0			
Tyre profile depth RR	7.0			
Tyre size FL	215/60 R 17 100 V			
Tyre size FR	215/60 R 17 100 V			
Tyre size RL	215/60 R 17 100 V			
Tyre size RR	215/60 R 17 100 V			
Tyre type FL	All seasons			
Tyre type FR	All Seasons			
Tyre type RL	Summer			
Tyre type RR	All Seasons			
Tyre make FL	264			
Tyre make FR	264			
Tyre make RL	1957075			
Tyre make RR	1957075			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Floor covering FL, Tear, Acceptable			



Door FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Kenteken	2CER861
Merk Model	Peugeot 2008 Roadtrip 1.5 BlueHDi S&S 110pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	6/27/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
1/15/26	88,117	controle niveaus	Uitvoeren
7/25/25	77,118	80000 km	Uitvoeren
7/25/25	77,118	oliezeef	Vervangen
7/25/25	77,118	remblokken vooraan	Vervangen
7/25/25	77,118	ruitenswisserrubber vooraan	Vervangen
7/12/24	54,803	60000 km	Uitvoeren
7/12/24	54,803	brandstof hoofdfilter	Vervangen
7/12/24	54,803	luchtfilter	Vervangen
7/12/24	54,803	luchtfilter interieur	Vervangen
7/12/24	54,803	oliezeef	Vervangen
7/12/24	54,803	remvloeistof	Vervangen
7/12/24	54,803	ruitenswisserrubber achter	Vervangen
7/12/24	54,803	ruitenswisserrubber vooraan	Vervangen
6/30/23	30,735	30000 km	Uitvoeren
6/30/23	30,735	luchtfilter interieur	Vervangen
6/30/23	30,735	oliezeef	Vervangen
6/30/23	30,735	ruitenswisserrubber vooraan	Vervangen