



## HYUNDAI TUCSON: GR-305-HH

Vinnnumber:	<b>TMAJC81AGPJ378374</b>	Versionname:	<b>HYUNDAI TUCSON 1.6 CRDI 136 DCT-7 HYBRID 48V BUSINESS VP [5P] bva 7-136CH-7cv (SUV)</b>
First Registrationdate:	<b>20/09/2023</b>	Fiscalpower:	
Expertise Mileage:	<b>130853</b>	Power Kw:	<b>100</b>
Bodytype:	<b>SUV</b>	Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Interior colour:	<b>Black</b>
Fueltype:	<b>Hybrid</b>	Type of rims (mounted):	<b>Aluminium</b>
Engine functioning:	<b>Yes</b>	Dashboard color:	<b>Black</b>
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		

## Options

Number of keys total	<b>1</b>	Radio	
Number keys remote	<b>1</b>	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Rear view camera	
Windows electric R		Seat cover lining	<b>Lining Other</b>
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	<b>Autom climate control</b>		

## Tyres

<b>215/65/17/103 V</b>				
Summer tyres:	Fr.L.	<b>Continental: 45%</b>	Fr.R.	<b>Continental: 50%</b>
	Re.L.	<b>Michelin: 80%</b>	Re.R.	<b>Michelin: 80%</b>
Tyre profile depth FL				<b>5.1</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>2.9</b>
Tyre profile depth RR				<b>2.8</b>
Tyre size FL				<b>215/65 R 17 103 V</b>
Tyre size FR				<b>215/65 R 17 103 V</b>
Tyre size RL				<b>215/65 R 17 103 V</b>
Tyre size RR				<b>215/65 R 17 103 V</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>256</b>
Tyre make FR				<b>256</b>
Tyre make RL				<b>261</b>
Tyre make RR				<b>261</b>

## Assistance equipment

Interior, Dirty, Cleaning



Glove compartment lid, Scratch(es), Replace



Dashboard, Scratch(es), Repair/replace (lump sum)



Interior trim, Damaged, Replace



Interior trim, Damaged, Replace



Steering wheel, Scratch(es), Repair/replace (lump sum)



Remote ignition key, Missing, Repair/replace (lump sum)



Door panel FR, Scratch(es), Replace



Tyre RR, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Wing FL, Scratch(es), Acceptable



Bumper F, Scratch(es), Paint



Rear bulkhead lining, Scratch(es), Replace



Internal boot lining R, Scratch(es), Acceptable



Rubber seal for boot lid, Tear, Replace



# Historique Maintenance

Immatriculation: **GR-305-HH**

Date de 1ère immatriculation: **20/09/2023**

Modèle: **Hyundai TUCSON 1.6 CRDI 136 DCT-7 HYBRID 48V BUSINESS VP [5P] bva 7-136CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
16/04/2026	127.419	CARROSSERIE CARROT	DIVERS CARROSSERIE
12/02/2026	120.798	ENJIN AUTOMOBILE	REVISION ET CLIM ET AIR ET CARBURANT
	0		DISQUES PLAQUETTES AV RPLT
	0		BALAI ESSUIE GLACE AR
	0		REFUS
07/10/2025	100.815	ENJIN AUTOMOBILE	REVISION ET CLIM
	0		BALAI ESSUIE GLACE AV
	0		LIQUIDE DE FREIN
26/08/2025	94.049	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS ETE
03/06/2025	82.195	EUROFLEET TYRES AND SERVICES	REPARATION DE ROUE
13/05/2025	79.526	ENJIN AUTOMOBILE	REVISION
	0		LAMPE CODE AVD RPLT
16/04/2025	76.723	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
	0		GARDIENNAGE
19/12/2024	61.462	ENJIN AUTOMOBILE	REVISION ET CLIM
	0		LIQUIDE DE FREIN
	0		PLAQUETTES AR RPLT
	0		BALAI ESSUIE GLACE AR
16/10/2024	51.997	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
	0		GARDIENNAGE
04/07/2024	38.910	ENJIN AUTOMOBILE	BALAI ESSUIE GLACE AV
	0		REVISION ET CLIM
	0		LIQUIDE DE FREIN
	0		PLAQUETTES AV RPLT
24/04/2024	30.025	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
	0		PERMUTATIONS PNEUS
29/02/2024	22.141	ENJIN AUTOMOBILE	REVISION
06/11/2023	2.370	GOODYEAR FRANCE	REPLACEMENT PNEUS HIVER