

# MAKES

## Tesla Model 3 '18 BEV

### Vehicle information

Make:	<b>Tesla</b>	License:	
Gearbox:	<b>Automatic</b>	Body color:	
Model:	<b>Model 3 '18 BEV</b>	VIN:	<b>LRW3E7FA6LC103687</b>
Fuel type:	<b>Electric</b>	Power:	<b>225 kW</b>
Version:	<b>Model 3 50KWh RWD Stand.Range+</b>	First registration	<b>04/12/2020</b>
Mileage:	<b>149718 km</b>	N° of doors:	

### Damage summary


Interior




1

Rear

3

### Commercial pictures





## Options according to the inspector

Central consol F	<b>Yes</b> GPS	<b>Yes</b> Headlights Xenon/LED/Laser	<b>Yes</b>
Panoramic roof	<b>Yes</b> Radio multimedia	<b>Yes</b> Telephone equipment	<b>Yes</b>

## Damages

### Boot lid covering R

Scratch(es)  
Smart repair  
Rear



### Bumper R

Scratch(es)  
Repair and paint (partial)  
Rear



### Rear window

Scratch(es)  
Replace  
Rear



### Shutter / cover

Broken  
Smart repair  
Interior



## Tyres

### Front Left

Summer

235/45/18/98/V

BF Goodrich

5.5 mm

### Front Right

Summer

235/45/18/98/V

BF Goodrich

5.8 mm

### Rear Left

Summer

235/45/18/98/V

BF Goodrich

5.8 mm

### Rear Right

Summer

235/45/18/98/V

BF Goodrich

4.8 mm

## Checks

Certificate of Conformity	<b>No</b> CO2 Emission	<b>0</b>
Digital maintenance	<b>Yes</b> GPS storage	<b>Yes</b>
GPS storage	<b>HD</b> Luggage cover	<b>N/A</b>
Number head rests	<b>1</b> Number of charging cables (rapid charge)	<b>1</b>
Number of keys total	<b>2</b> Service book	<b>N/A</b>
User's manual	<b>Yes</b>	

### Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.