



TOYOTA COROLLA TOURING SPORTS: GL-918-RQ

Vinnnumber:	SB1Z93BE30E352049	Versionname:	TOYOTA COROLLA TOURING SPORTS Hybride 122h
First Registrationdate:	17/01/2023		Dynamic Business Beyond Zer VP [5P] bva 0-
Expertise Mileage:	101944		122CH-5cv (break)
Bodytype:	Break	Fiscalpower:	90
Gearbox:	Automatic	Power Kw:	Blue
Transmission:	Front	Body colour:	Metallic
Fueltype:	Hybrid	Paint type:	Black
Engine functioning:	Yes	Interior colour:	Aluminium
Battery functioning:	Yes	Type of rims (mounted):	Black
Vehicle running:	Yes	Dashboard color:	
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Rear view camera	
Type of climate control	Autom climate control	Seat cover lining	Lining Other

Tyres

	205/55/16/94 V			
Summer tyres:	Fr.L.	Goodyear: 45%	Fr.R.	Goodyear: 15%
	Re.L.	Bridgestone: 40%	Re.R.	Bridgestone: 45%
Tyre profile depth FL				5.4
Tyre profile depth FR				7.2
Tyre profile depth RL				5.6
Tyre profile depth RR				5.2
Tyre size FL				205/55 R 16 94 V
Tyre size FR				205/55 R 16 94 V
Tyre size RL				205/55 R 16 94 V
Tyre size RR				205/55 R 16 94 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Jack	No
Runflat	Yes

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Interior, Stain, Cleaning



Dashboard, Scratch(es), Replace



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Outside rear-view mirror housing L, Scratch(es), Acceptable



Door FL, Scratch(es), Paint



Door RL, Scratch(es), Paint



Outer sill L, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Wing RR, Dent(s), Repair and paint (complete)



Door RR, Scratch(es), Paint



Outer sill R, Scratch(es), Paint



Jack, Missing, Repair/replace (lump sum)



Bumper R, Scratch(es), Paint



Historique Maintenance

Immatriculation: **GL-918-RQ**

Date de 1ère immatriculation: **17/01/2023**

Modèle: **Toyota COROLLA TOURING SPORTS Hybride 122h Dynamic Business Beyond Zer VP [5P] bva 0-122CH-5cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
18/12/2025	87.215	GCA BORDEAUX	LIQUIDE DE FREIN
	0		REVISION ET CLIM
	0		FILTRE A AIR RPLT
29/10/2024	52.200	GCA BORDEAUX	DIVERS ECHAPPEMENT
	0		REVISION ET CLIM
	0		LIQUIDE DE FREIN
15/01/2024	30.018	GCA BORDEAUX	REVISION ET CLIM