



Skoda Octavia: 2ARB213

Vinnumber:	TMBJW7NX2MY167419	Versionname:	
First Registrationdate:	17/06/2021	Fiscalpower:	
Expertise Mileage:	85322	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2228
Fueltype:	Hybrid Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/45/18/95 V				
Winter tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/45 R 18 95 V
Tyre size FR				225/45 R 18 95 V
Tyre size RL				225/45 R 18 95 V
Tyre size RR				225/45 R 18 95 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2289,83
Bonnet, Hail damage, Repair and paint (complete)	465,70



Bumper R, Scratch(es), Repair and paint (complete)	296,58
--	--------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Outer sill R, Dent(s) and scratch(es), Spot repair	148,33
--	--------



Roof pillar R, Dent(s), Paintless dent repair	95,47
---	-------



Wing RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim RR polished, Scratch(es), Acceptable	0,00
--	------



Roof, Hail damage, Repair and paint (complete)	823,04
--	--------



Charging cable (normal), Missing, Check	0,00
---	------



Charging cable (fast), Missing, Replace	256,50
---	--------

