

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number			Code / Agency				Date accident 23/06/2026								
				Expert code			Adjuster code			Policy number			Injured person can recover the VAT								
Date assignment 23/06/2026		Date first survey 01/07/2026		Place ROMA		C/O VAR		Repairs TO START		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)												Formerly plate									
Lessee / Co-owner												Date of overhaul									
Vehicle (Brand - Model - Version) MAZDA CX-60 2.5L e-SKYACTIV PHEV Excl. Line AWD Auto								Plate GM790PS		Vin Chassis JMZKH0HBX01121438				First Registration 30/01/2023							
Usage status NON CONOSCIUTO		Km 42787		Tyres % 50		Color NERO		Type of enamel METALLIZED/DOUBLE				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts			
								Dif Time		Dif Time		Dif Time		Time		+		(VAT excluded)			
1	KAAA50241	Rear bumper side trim					L	S		S		S									
1	KAAA50231	Rear bumper side trim					R	S		S		S									
1	KR9P50031ABB	Front bumper						S		S		S									
1	KAAA51W30B	Front wheel arch trim					L	S		S		S									
1	KAAC68550H02	Internal panel of rear door					L	S		S		S									
1	KAAC68520H02	Internal panel of rear door					R	S		S		S									
1	Codice Ricambio	Pneumatico post.					R	S		S		S									
1	KAAA502218P	Rear bumper						M		M		M									
1	KBY76202XA	Rear hatch						M				M									
1	KBY17302XE	Rear door					L	M				M									
1	KBY370410	rear mudguard					R	L				L									
1	KBY17202XE	Rear door					R	L		L		M									
1	KBY15802XG	Front door					R	L		L		L									
1	KBY15231X	Front bonnet						L				L									
1	KBY15902XG	Front door					L	L				L									
1	KBY371410	rear mudguard					L	L				L									
1	Codice Ricambio	Proiettore - Luc.					L														
1	Codice Ricambio	n. 4 cerchi in lega rettifica																			

New for old value (N)	Remarks
	Pneum. Bridgestone 235/50 R20. Vhl sporco. Presenti due cavi di ricarica (mod2-3); verificare dot. di serie.

ALPHABET

Telaio JMZKH0HBX01121438

GM790PS

MAZDA CX-60 2.5L e-SKYACTIV PHEV Excl. Line AWD Auto sports utility vehicle 327CV 5P automatico

Current Odo (Time of Ma	Maintenance Request	Service Type Descriptio	Maintenance Job Description
78	17/04/23	Maintenance	Gestione Garanzia
24.300	17/02/25	Tagliando a 20 000 km	Tagliando a 20 000 km
38.259	28/04/26	Tagliando a 40 000 km	Tagliando a 40 000 km