



Volkswagen Golf (UKL): 2DVX609

Vinnumber:	WVWZZZCD0PW535742	Versionname:	Golf VIII Variant Life Business 1.0TSi 110pk/cv 5p
First Registrationdate:	10/07/2023	Fiscalpower:	
Expertise Mileage:	47712	Power Kw:	81
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/55/16/91 V			
Summer tyres:	Fr.L.	Vredestein: 2 mm	Fr.R.	Vredestein: 2 mm
	Re.L.	Vredestein: 3 mm	Re.R.	Vredestein: 3 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				2.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				205/55 R 16 91 V
Tyre size FR				205/55 R 16 91 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Interior, Dirty, Cleaning			



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Bumper R, Dent(s) and scratch(es), Replace and paint



Boot lid covering R, Scratch(es), Acceptable



Bodywork, Not original part, Check



Bodywork, Dirty, Check



Kenteken	2DVX609
Merk Model	Volkswagen Golf VIII Variant Life Business 1.0TSi 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	7/10/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/13/25	25,477	batterij	Vervangen
5/13/25	25,477	klein materiaal	
5/13/25	25,477	koelwatervloeistof	Bijvullen/-laden
5/13/25	25,477	luchtfilter interieur	Vervangen
5/13/25	25,477	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
5/13/25	25,477	remvloeistof	Vervangen
5/13/25	25,477	ruitenswisserrubber achter	Vervangen
5/13/25	25,477	ruitenswisserrubber vooraan	Vervangen
5/13/25	25,477	ruitenswisservloeistof	Bijvullen/-laden