BMW

1.5 216DA GRAN COUPE

VIN: WBA11AM0107J93913



Description

Registration number 2BCP994	**First registration date** 01/10/2021	**Odometer** 129579 km
Color MINERALWEISS METALLIC	**Model year** 2020	**Upholstery** -
Number of doors 4	**Number of seats** 5	**Generation** -
CO2 138	**Engine displacement** 1496	**Gearbox type** Automatic
Engine type Combustion	**Number of gears** 7	**Drivetrain** Front Wheel Drive (FWD)
Max power 85 KW		

Vehicle Equipments

Alloy wheel rims	Climate control	Rear sensors
Front sensors	SATNAV	Cruise control
Sliding roof	Heated seats	Automatic headlights
Rain-sensitive wipers		

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 27/10/2026	**Inspection approval date** 28/10/2026


Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Defects & corrections

#	Element	Defect	Correction
001	Personal Data / -	Non Compliant	Carry out
	 		
002	Bonnet soundproofing / -	Tear	Acceptable
			
003	Rim / Front Left Rim/Tyre diameter : 17 "	Scratched	Repair
	 		
004	Rim / Front Right Rim/Tyre diameter : 17 "	Scratched	Acceptable
	 		

Loose Items

- [x] Conformity certificate
- [x] Registration certificate
- [x] Registration certificate owner
- [x] Card key
- [x] Spare Key
- [x] User manual
- [x] Document holder

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	GOODYEAR	225/45/17 Summer	6 mm
Front Right	GOODYEAR	225/45/17 Summer	6 mm
Back Left	GOODYEAR	225/45/17 Summer	7 mm
Back Right	GOODYEAR	225/45/17 Summer	7 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment



Front right



Odometer



Navigation




Vin




Other


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other




Other



Personal Data / - / Non Compliant



Personal Data / - / Non Compliant



Bonnet soundproofing / - / Tear



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.