



CITROËN BERLINGO: FS-070-PQ

Vinnumber:	VR7EFYHYCLJ680396	Versionname:	CITROËN BERLINGO M 650kg BlueHDi 100 S&S BVM Driver VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)
First Registrationdate:	10/09/2020	Fiscalpower:	
Expertise Mileage:	114135	Power Kw:	75
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	4	Radio	
Number keys remote	1	Front parking sensors	
GPS big screen color		Rear parking sensors	
Windows electric F		Roof rack	
Cruise Control		Sliding door right-side	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Type of climate control	Manual climate control		

Tyres

	195/65/15/95 V			
Summer tyres:	Fr.L.	Michelin: 50%	Fr.R.	Michelin: 50%
	Re.L.	Michelin: 45%	Re.R.	Michelin: 45%
Tyre profile depth FL				5.0
Tyre profile depth FR				4.9
Tyre profile depth RL				5.1
Tyre profile depth RR				5.1
Tyre size FL				195/65 R 15 95 V
Tyre size FR				195/65 R 15 95 V
Tyre size RL				195/65 R 15 95 V
Tyre size RR				195/65 R 15 95 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Runflat	No
Gear shift lever cover, Tear, Replace			



Door panel FL, Unclapsed, Dismount/Mount



Seat cover FL, Tear, Repair/replace (lump sum)



Interior, Stain, Cleaning



Steel rim RL, Deformed / Strained, Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace



Bumper F, Scratch(es), Repair and paint (complete)



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Scratch(es), Acceptable



Door trim RR, Scratch(es), Replace



Outside rear-view mirror housing R, Scratch(es), Replace



Door FR, Scratch(es), Paint



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RL, Scratch(es), Acceptable



Bodywork, Glue residues, Remove lettering



Historique Maintenance

Immatriculation: **FS-070-PQ** Date de 1ère immatriculation: **10/09/2020**

Modèle: **Citroen BERLINGO M 650kg BlueHDi 100 S&S BVM Driver VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
25/11/2025	106.667	MIDI AUTO 84	VANNE EGR RPLT
	0		DIAG
22/01/2025	97.665	TREBON AUTO SA	REVISION
	0		ADBLUE
	0		BALAIS ESSUIE GLACE AV
	0		DIVERS CLIM
07/01/2025	96.248	EUROMASTER FRANCE	REPARATION DE ROUE
06/11/2024	92.063	EUROMASTER FRANCE	REPARATION DE ROUE
11/09/2024	88.916	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
05/09/2024	88.512	TREBON AUTO SA	DISQUES PLAQUETTES AR RPLT
	0		DISQUES PLAQUETTES AV RPLT
17/05/2024	82.600	EUROMASTER FRANCE	REMPLACEMENT PNEUS ETE
19/07/2023	62.973	TREBON AUTO SA	FILTRE A AIR RPLT
	0		REVISION
	0		ADBLUE
	0		RECYCLAGE
	0		LIQUIDE DE FREIN
	0		REVISION
	0		BALAIS ESSUIE GLACE AV
	0		FILTRE CLIM RPLT
27/06/2023	61.897	EUROMASTER FRANCE	REMPLACEMENT PNEUS ETE
12/04/2023	54.679	EUROMASTER FRANCE	CHAINES NEIGE RPLT
09/03/2023	54.679	TREBON AUTO SA	REMPLACEMENT PNEUS ETE
17/01/2023	51.551	TREBON AUTO SA	RECYCLAGE
	0		DISQUES PLAQUETTES AV RPLT
	0		FEU ARG RPLT
	0		PILE DE CLE RPLT
28/07/2022	42.584	EUROMASTER FRANCE	REMPLACEMENT PNEUS ETE
25/02/2022	32.215	TREBON AUTO SA	BALAIS ESSUIE GLACE AV
	0		RECYCLAGE
	0		REVISION
	0		ADBLUE

Historique Maintenance

Immatriculation: **FS-070-PQ**

Date de 1ère immatriculation: **10/09/2020**

Modèle: **Citroen BERLINGO M 650kg BlueHDi 100 S&S BVM Driver VU [4P] bvm 5-100CH-5cv
(fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
02/02/2022	29.984	EUROMASTER FRANCE	REPARATION DE ROUE
	0		REMPLACEMENT PNEUS ETE
22/09/2021	20.384	EUROMASTER FRANCE	REMPLACEMENT PNEUS ETE