



PEUGEOT 3008: FW-777-YP

Vinnumber:	VF3M4DGZUMS027389	Versionname:	PEUGEOT 3008 1.6 HYBRID 225 E-EAT8 Allure Pack VP [5P] bva 8-225CH-10cv (SUV)
First Registrationdate:	3/02/2021	Fiscalpower:	
Expertise Mileage:	112544	Power Kw:	165
Bodytype:	SUV	Body colour:	Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	
Type of climate control	Autom climate control	Lining Other	
		Lining Semi-leather	

Tyres

225/55/18/98 V			
Summer tyres:	Fr.L.	Other: 0%	Fr.R.
	Re.L.	Continental: 45%	Re.R.
		Continental: 45%	
Tyre profile depth FL			8.0
Tyre profile depth FR			8.0
Tyre profile depth RL			5.3
Tyre profile depth RR			5.4
Tyre size FL			225/55 R 18 98 V
Tyre size FR			225/55 R 18 98 V
Tyre size RL			225/55 R 18 102 V
Tyre size RR			225/55 R 18 102 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			All seasons
Tyre type RR			All Seasons
Tyre make FL			263
Tyre make FR			263
Tyre make RL			256
Tyre make RR			256

Assistance equipment

Interior, Dirty, Cleaning





Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FL, Scratch(es), Paint



Bumper moulding F, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Door FR, Dent(s), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Paint



Wing trim RR, Scratch(es), Replace



Boot moulding, Scratch(es), Paint



Historique Maintenance

Immatriculation: FW-777-YP Date de 1ère immatriculation: 03/02/2021

Modèle: Peugeot 3008 1.6 HYBRID 225 E-EAT8 Allure Pack VP [5P] bva 8-225CH-10cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
07/01/2026	110.397	AXIOME ORGEVAL	COURROIE ACCESSOIRES RPLT
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		LIQUIDE DE FREIN
	0		REVISION ET CLIM ET AIR ET BOUGIES
10/07/2025	99.212	AXIOME ORGEVAL	BATTERIE RPLT
	0		DIAG
03/12/2024	85.027	BOUAFLE MOTORS	COURROIE ACCESSOIRES RPLT
	0		RECYCLAGE
	0		REVISION
20/01/2024	62.008	CONTITRADE FRANCE	REPLACEMENT PNEUS 4 SAISONS
14/01/2024	61.258	CONTITRADE FRANCE	REPLACEMENT PNEUS 4 SAISONS
12/12/2023	58.713	VAUBAN AUTOMOBILE - HERBLAY	RECYCLAGE
	0		CULASSE RPLT
08/06/2023	47.692	VAUBAN AUTOMOBILE - HERBLAY	LIQUIDE DE FREIN
	0		REVISION
	0		FILTRE CLIM RPLT
	0		RECYCLAGE
	0		BALAIS ESSUIE GLACE AV
27/09/2022	31.626	EUROFLEET TYRES AND SERVICES	REPARATION DE ROUE
22/04/2022	24.753	VAUBAN AUTOMOBILE - HERBLAY	BALAIS ESSUIE GLACE AV
	0		REVISION