



Volkswagen ID.4: L319LJ

Vinnnumber:	WVGZZZE2ZMP044671	Versionname:	ID 4 150kW / 77kWh Life Aut.
First Registrationdate:	15/06/2021	Fiscalpower:	
Expertise Mileage:	143725	Power Kw:	150
Bodytype:		Body colour	Mangan Grey metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	1055
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Rear parking sensors
GPS		Hook
Autom climate control		
Radio multimedia		


Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 50 / 19 / 103 / T / Aluminium	3,8 mm	Hankook	Summer
	Right	235 / 50 / 19 / 103 / T / Aluminium	3,7 mm	Hankook	Summer
Rear	Left	255 / 50 / 19 / 103 / T / Aluminium	3,8 mm	Hankook	Summer
	Right	255 / 50 / 19 / 103 / T / Aluminium	4,2 mm	Hankook	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bumper corner RR, Stone chip(s), Repair and paint (complete)



Bumper corner RL, Scratch(es), Repair and paint (complete)



Kenteken	L319LJ
Merk Model	Volkswagen ID 4 150kW / 77kWh Life Aut.
Brandstofsoort	Elektrisch
Datum deel1	15-06-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
26-08-25	122.434	Onderhoudsbeurt
26-08-25	122.434	Remvloeistof
26-08-25	122.434	Tankklepmotor
25-03-25	111.489	APK
11-07-23	62.998	Onderhoudsbeurt
11-07-23	62.998	Remvloeistof
11-07-23	62.998	Ruitenwischerblad(en) achterzijde
11-07-23	62.998	Ruitenwischerblad(en) voorzijde