MACADAM









DS 7 CROSSBACK: FV-187-BC

Vinnumber:	**VR1JCYHZRLY042837**	Versionname:	**DS DS 7 CROSSBACK BlueHDi 130 Automatique Business VP [5P] bva 8-130CH-7cv (SUV)**
First Registrationdate:	**10/11/2020**	Fiscalpower:	
Expertise Mileage:	**118632**	Power Kw:	**96**
Bodytype:	**SUV**	Body colour	**Black**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Gold**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Seats electric F L	
GPS big screen color		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	**Lining Other**
Steering wheel leather			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**215/65/17/103 V**			
	Fr.L.	**Michelin: 55%**	Fr.R.	**Michelin: 60%**
	Re.L.	**Michelin: 45%**	Re.R.	**Michelin: 50%**

Tyre profile depth FL	**4.6**
Tyre profile depth FR	**4.3**
Tyre profile depth RL	**5.1**
Tyre profile depth RR	**5.0**
Tyre size FL	**215/65 R 17 103 V**
Tyre size FR	**215/65 R 17 103 V**
Tyre size RL	**215/65 R 17 103 V**
Tyre size RR	**215/65 R 17 103 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Interior, Dirty, Chemical cleaning




Alloy rim RL, Scratch(es), Repair/replace (lump sum)





Alloy rim FR, Scratch(es), Repair/replace (lump sum)





Door FL, Scratch(es), Paint




Bumper F, Scratch(es), Paint





Wing RR, Scratch(es), Paint




Door RR, Scratch(es), Paint




Bumper R, Scratch(es), Acceptable




Other exterior parts, Missing, Replace




ALPHABET

Historique Maintenance

Immatriculation: **FV-187-BC** Date de 1ère immatriculation: **10/11/2020**

Modèle: **DS 7 CROSSBACK BlueHDi 130 Automatique Business VP [5P] bva 8-130CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
30/04/2026	107.148	STELLANTIS & YOU LOMME	REVISION
	0		DIVERS
	0		AVOIR
	0		COURROIE ACCESSOIRES RPLT
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		LIQUIDE DE FREIN
	0		FILTRE CLIM RPLT
23/06/2025	84.291	STELLANTIS &YOU FRANCE SAS	DIVERS CLIM
	0		RECYCLAGE
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		REVISION
21/02/2025	77.766	DEKRA AUTOMOTIVE S.A	CONTRE VISITE CT
12/02/2025	77.553	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
07/06/2024	62.688	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
05/06/2024	62.683	STELLANTIS &YOU FRANCE SAS	BALAI ESSUIE GLACE AR
	0		RECYCLAGE
	0		PLAQUETTES AV RPLT
	0		DIVERS CLIM
	0		REVISION
	0		FILTRE A AIR RPLT
	0		FILTRE CLIM RPLT
	0		REVISION
	0		BALAIS ESSUIE GLACE AV
10/05/2023	44.050	AUTOPLAN SERVICES	PERMUTATIONS PNEUS
06/07/2022	36.859	AUTOPLAN SERVICES	ADBLUE
	0		REVISION
19/07/2021	13.461	AUTOPLAN SERVICES	ADBLUE
	0		REVISION ET CLIM