



SEAT ALHAMBRA:

Vinnumber:	VSSZZZ7N2LV511585	Versionname:	2.0 TDI 110kW Move Style
First Registrationdate:	20/05/2020	Fiscalpower:	
Expertise Mileage:	107875	Power Kw:	110
Bodytype:		Body colour:	Brown
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1209
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/50/17/92 H				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/50 R 17 92 H
Tyre size FR				225/50 R 17 92 H
Tyre size RL				225/50 R 17 92 H
Tyre size RR				225/50 R 17 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2072,77
-------------------	---------

Seat cover FL, Stain, Cleaning	29,16
--------------------------------	-------



Seat cover FL, Damaged, Acceptable 0,00



Bonnet, Dent(s), Acceptable 0,00



Bumper F, Dent(s), Repair and paint (complete) 355,89



Alloy rim RL polished, Rust, Acceptable 0,00



Door FL, Dent(s), Acceptable 0,00




Bumper R, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), Replace 941,55



Tailgate / Boot, Dent(s), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Acceptable 0,00



Tyre FR, Tear, Replace	211,22
------------------------	--------



Door FR, Scratch(es), Repair and paint (complete)	534,95
---	--------



Wing RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Roof, Scratch(es), Touch up	0,00
-----------------------------	------

