TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48399458
Order No. / Reference: 27171481
Inspection date: 27 Oct 2026

Manufacturer: Volkswagen	Model: ID.5 Pro Performance
VIN: WVGZZZE29PP532503	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen ID.5 Pro Performance	
Vehicle Identification number	WVGZZZE29PP532503
Mileage (Read)	54,045 km
First registration	22 Aug 2023
Number of holders	1
Next periodical technical inspection	08/2028
(Report on hand)	
Fuel type	Electric
Power	70 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Car station wagon
Colour / colour code	Gletscherweiß Metallic / Dach Schwarz
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	279 Tag(e)
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV319865
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0603 / CQL 00005		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,640 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101T	Summer tyres on Light alloy	Hankook	4mm / 4mm
2)	255/50 R19 103T	Summer tyres on Light alloy	Hankook	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 USB-C ports on the front
- Airbag for driver and front passenger, with front passenger airbag deactivation
- Ambient lighting, 10 colors
- Adaptive Cruise Control (ACC) "stop & go" including speed limiter
- On-board tools and tire mobility set
- Car2X
- Black surround for the infotainment display and central controls
- Driving profile selection
- Back window, heater
- Interior mirror automatically dimming
- ISOFIX mounting points for child car seats
- Rear headrests (3)
- Front headrests
- LED taillights
- Steering wheel: Multifunction steering wheel
- Centre console
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Upholstery: Seat center panels of the front seats and the outer rear seats in "Matrix" fabric
- Tire pressure monitoring system
- Wheel accessories: Covers for alloy wheels
- Wheel accessories: Wheel locks with enhanced theft protection
- Keyless Start system
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Armrest for front seats
- Seats: Rear bench seat undivided, backrest asymmetrically split and foldable
- Bumpers in body color
- Ambient lighting with logo projection
- Traffic sign recognition
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear
- Turning brake function and evasive steering support
- Airbags: Front and rear head airbags, front side airbags, center airbag
- App-Connect including App-Connect Wireless for Apple CarPlay and Android Auto
- Electrically adjustable, folding and heated exterior mirrors
- third brake light
- e-Sound
- Parking assistance
- ESP Electronic Stability Program
- Transmission: 1-speed automatic
- Infotainment accessories: Online update capability from ID.Software 2.1
- "Climatronic" air conditioning system (active combination filter - stationary air conditioning)
- Mode 3 Type 2 charging cable, 16 A
- LED headlights with automatic headlight control
- Illuminated makeup mirrors in the sun visors
- Fatigue detection
- Emergency call service
- Stainless steel pedals in a "Play/Pause" design
- Radio accessories: 6 + 1 speakers
- Radio accessories: Digital radio reception DAB+
- Wheels: Alloy wheels (4) "Hamar" 8 J x 19 in black gloss-turned finish (wheels in black, surface gloss-turned - tires 235/55 R 19 front, tires 255/50 R 19 rear)
- Windscreen wiper intermittent control
- electromechanical power steering
- Seat belts: Warning tone and light for unfastened seat belts in the front and rear.
- Seats: Driver's seat height adjustable
- Voice control
- Lane keeping assistant “Lane Assist”
- Telephone interface
- First aid kit, warning triangle and high-visibility vest
- Prepared for later activation: "Discover Pro" navigation function
- Central locking including remote control

Extra equipment

- Foldable towbar (electric release)
- Package: Infotainment package (Navigation system "Discover Pro" - Telephone interface "Comfort" with inductive charging function)
- Paint finish: Metallic, different roof color
- Textile floor mats front and rear
- Heat pump for range optimization

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Instrument panel

Figure 10: Interior 360° view (Online Link)



Figure 11: Cargo area




Figure 12: VIN



Figure 13: Mounted tyres



Figure 14: Documents



Figure 15: Documents




Figure 16: Documents



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.