MACADAM









PEUGEOT PARTNER: FS-192-DL

Vinnumber:	**VR3EFYHYCLJ650097**	Versionname:	**PEUGEOT PARTNER BLUEHDI 100 S&S 950KG LONG ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**
First Registrationdate:	**20/08/2020**	Fiscalpower:	
Expertise Mileage:	**196079**	Power Kw:	**75**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Front parking sensors	
GPS big screen color		Rear parking sensors	
Windows electric F		Sliding door right-side	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	**Lining Other**
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**205/60/16/96 V**			
	Fr.L.	**Other: 35%**	Fr.R.	**Other: 50%**
	Re.L.	**Other: 35%**	Re.R.	**Other: 40%**

Tyre profile depth FL	**5.8**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**5.6**
Tyre size FL	**205/60 R 16 96 V**
Tyre size FR	**205/60 R 16 96 V**
Tyre size RL	**205/60 R 16 96 V**
Tyre size RR	**205/60 R 16 96 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**263**
Tyre make FR	**263**
Tyre make RL	**263**
Tyre make RR	**263**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Remote ignition key, Missing, Repair/replace (lump sum)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Acceptable




Outer sill R, Dent(s) and scratch(es), Replace and paint




Sliding door R, Scratch(es), Polish




Door FR, Scratch(es), Polish




Bumper R, Scratch(es), Acceptable





Boot door panel RL, Rust, Paint





Supplementary brake light, Scratch(es), Replace




Rear light R, Scratch(es), Replace




Bodywork, Not original part, Sticker removal small



ALPHABET

Historique Maintenance

Immatriculation: **FS-192-DL** Date de 1ère immatriculation: **20/08/2020**

Modèle: **Peugeot PARTNER BLUEHDI 100 S&S 950KG LONG ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
31/08/2026	194.871	BAILLY PONT MOUSSON	DIVERS MOTEUR
			BIELLETTE DE DIRECTION AVG RPLT
07/07/2026	192.869	BAILLY PONT MOUSSON	DIVERS SUSPENSION
			PLAQUETTES AV RPLT
			DISQUES PLAQUETTES AR RPLT
			ADDITIF FAP CTRL
			LIQUIDE DE REFROIDISSEMENT RPLT
			FILTRE A CARBURANT RPLT
			FILTRE A AIR RPLT
			LIQUIDE DE FREIN
			FILTRE CLIM RPLT
			VOLANT MOTEUR RPLT
			EMBRAYAGE RPLT
			REVISION
			TRIANGLE INFERIEUR AVG RPLT
24/12/2025	172.517	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS 4 SAISONS
23/12/2025	172.360	CAR AVENUE BAILLY	INJECTEUR ADBLUE RPLT
			ECLAIRAGE DE PLAQUE RPLT
			POT CATALYTIQUE FAP RPLT
			DISQUES PLAQUETTES AV RPLT
25/08/2025	160.243	CAR AVENUE BAILLY	REVISION
			FILTRE A AIR RPLT
			REVISION
			ADBLUE
			BALAIS ESSUIE GLACE AV
			DIVERS ECHAPPEMENT
			DIVERS CLIM
			FILTRE CLIM RPLT
02/12/2024	140.297	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS 4 SAISONS
29/08/2024	129.655	CAR AVENUE BAILLY	PLAQUETTES AV RPLT
			ECLAIRAGE DE PLAQUE RPLT
			LIQUIDE DE REFROIDISSEMENT RPLT

Historique Maintenance

Immatriculation: **FS-192-DL** Date de 1ère immatriculation: **20/08/2020**

Modèle: **Peugeot PARTNER BLUEHDI 100 S&S 950KG LONG ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
			DIVERS MOTEUR
			ANTIBROUILLARD RPLT
17/06/2024	124.705	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
27/03/2024	119.124	CAR AVENUE BAILLY	ADBLUE
			COURROIE ACCESSOIRES RPLT
			BALAIS ESSUIE GLACE AV
			DIVERS CLIM
			REVISION
			REVISION
			FILTRE A AIR RPLT
			LIQUIDE DE FREIN
			FILTRE CLIM RPLT
15/02/2024	115.767	CAR AVENUE BAILLY	POT CATALYTIQUE FAP RPLT
09/02/2024	115.360	EUROFLEET TYRES AND SERVICES	REPARATION DE ROUE
30/11/2023	106.754	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS HIVER
15/05/2023	88.012	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
12/05/2023	87.500	CAR AVENUE BAILLY	DISQUES PLAQUETTES AV RPLT
			DISQUES PLAQUETTES AR RPLT
03/02/2023	81.089	CAR AVENUE BAILLY	REVISION ET CLIM ET AIR ET CARBURANT
			REVISION ET CLIM ET AIR ET CARBURANT
			REVISION ET CLIM ET AIR ET CARBURANT
			REVISION ET CLIM ET AIR ET CARBURANT
			BALAIS ESSUIE GLACE AV
			ADBLUE
01/06/2023	76.773	BAILLY NANCY	DIVERS FREIN
24/10/2022	69.943	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS HIVER
05/08/2022	61.927	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS ETE
24/11/2021	40.735	CAR AVENUE BAILLY	FILTRE CLIM RPLT
			BALAIS ESSUIE GLACE AV
			REVISION
			FILTRE A AIR RPLT

Historique Maintenance

Immatriculation: **FS-192-DL** Date de 1ère immatriculation: **20/08/2020**

Modèle: **Peugeot PARTNER BLUEHDI 100 S&S 950KG LONG ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
			REVISION
			RECYCLAGE
			ADBLUE
23/11/2021	38.820	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
30/04/2021	19.073	EUROFLEET TYRES AND SERVICES	REPARATION DE ROUE
			PERMUTATIONS PNEUS
11/02/2021	11.521	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS HIVER